

Appendix IS-15

Asbestos and Lead-Based Paint Survey Report

June 3, 2019

Ms. Paige Dow
Skid Row Housing Trust
1317 E. 7th Street
Los Angeles, California 90021

Subject: Asbestos & Lead-Based Paint Re-Inspection
508 4th Street
Los Angeles, California 90021
Partner Project No. 19-247394.2

Dear Ms. Dow:

Partner Engineering and Science, Inc. (Partner) was engaged by Skid Row Housing Trust to prepare an asbestos & lead-based paint re-inspection report. Partner conducted a site inspection to confirm asbestos-containing materials (ACM) and lead-based paints (LBP) previously identified in the Partner report dated May 17, 2018 attached below.

On May 24, 2019, Freddy Torres, of Partner, inspected the site to confirm the condition and inventory of materials from the previous report. Partner confirmed no additional suspect ACM and LBP. All observed materials appeared to be in good condition. Partner accessed four units, common area hallways, recreation rooms, and the roof.

We appreciate the opportunity to provide environmental services to The Skid Row Housing Trust. If you have any questions concerning this report, or if we can assist you in any other matter, please contact me at 310.615.4500.

Sincerely,

Partner Engineering and Science, Inc.



Jenny Redlin, REPA
Relationship Manager

Attachments:

Photograph Log

May 2018 Report

Certification

SUPPORTING DOCUMENTS



1. View of the exterior facade.



2. View of the blue and green vinyl flooring.



3. View of the unit interiors.



4. View of the interior hallways.



5. View of the kitchen interior.



6. View of the hallway flooring.



ASBESTOS & LEAD-BASED PAINT SURVEY REPORT

508 4TH STREET
LOS ANGELES, CALIFORNIA 90013

May 24, 2018
Partner Project No. 18-215754.1



Prepared for

SKID ROW HOUSING TRUST
1317 E. 7TH STREET
LOS ANGELES, CALIFORNIA 90021

May 24, 2018

Peter Enzminger
Skid Row Housing Trust
1317 E. 7th Street
Los Angeles, California 90021

Subject: Asbestos and Lead-Based Paint Survey Report
508 4th Street
Los Angeles, California 90013
Partner Project No. 18-215754.1

Dear Mr. Peter Enzminger:

Partner Engineering and Science, Inc. (Partner) is pleased to provide the results of the *Asbestos & Lead-based Paint Survey* of the abovementioned address (the "subject property"). This survey was performed in general conformance with the scope and limitations as detailed in our proposal.

This survey included a site reconnaissance as well as sampling and analysis. An assessment was conducted, conclusions stated, and recommendations outlined, as necessary.

We appreciate the opportunity to provide environmental services to Skid Row Housing Trust. If you have any questions concerning this report, or if we can assist you in any other matter, please contact me at (310) 765-7243.

Sincerely,

Partner Engineering and Science, Inc.



Jenny Redlin
Relationship Manager

EXECUTIVE SUMMARY

Partner Engineering and Science, Inc. (Partner) was contracted by Skid Row Housing Trust to conduct a lead-based paint (LBP) inspection and asbestos survey at the property located at 508 4th Street Los Angeles, California 90013.

LEAD-BASED PAINT

All painted and/or finished components were evaluated in 30 of the 39 units and all common areas according to the specifications described in the protocols for LBP inspection in the Housing and Urban Development (HUD) Guidelines Chapter 7 (revised 2012) and all applicable Federal, State, and local regulations. The lead evaluation at this property was performed on May 17th, 2018.

According to the HUD guidelines, a lead reading by XRF of 1.0 mg/cm² or above is considered positive for the presence of LBP. The County of Los Angeles uses an action level of 0.7 mg/cm². This action level will be referenced throughout the report.

Components having lead levels at or above the action level are visually assessed for condition and approximate surface area. LBP surfaces were found to be in intact condition at the time of inspection and do not require paint stabilization, but should be monitored on an ongoing basis. No lead paint hazards were identified within the areas accessed during this assessment. If lead paint hazards are identified in areas not previously accessed, they should be properly remediated in accordance with all applicable local, state and federal regulations.

During the evaluation, XRF testing was performed on at least one location per testing combination, except for interior walls, where four readings were taken (or one on each wall). The XRF testing was conducted using a Heuresis lead paint analyzer. A surface-by-surface visual assessment of the painted and/or finished surfaces was conducted to determine which lead-coated surfaces/components are deteriorated at or above action levels.

Partner has determined that there is no LBP at the property at or above 0.7 mg/cm².

Partner collected 62 samples of suspect lead-contaminated dust in the residential units accessed for XRF testing. A dust-lead hazard is defined as surface dust in a residential dwelling or child-occupied facility that contains a mass-per-area concentration of lead equal to or exceeding 40 µg/ft² on floors or 250 µg/ft² on interior window sills based on wipe samples (40 CFR 745.65). The analytical results indicate that no dust wipe samples exceeded the dust-lead hazard threshold.

ASBESTOS

The roof appeared to be in good overall condition and was not sampled as a part of the survey. None of the materials sampled were found to contain asbestos:

Friable Regulated Asbestos-Containing Materials (RACM)

- None

Non-Friable Category I and II ACM

- None

Asbestos-Containing Construction Material (ACCM) – Cal/OSHA (<1% Asbestos)

- None

The EPA recommends that all ACM be removed by a certified asbestos contractor prior to any renovation or demolition activities that may impact the material. In the absence of planned renovation/demolition activities, the EPA recommends that ACMs be managed in-place whenever asbestos is identified in a building. Any damaged asbestos materials should be removed, repaired, encapsulated, or enclosed. Asbestos materials that are not damaged may be managed in place in accordance with a written Operations and Maintenance Program.

TABLE OF CONTENTS

1.0	INTRODUCTION	1
1.1	Property Description	1
1.2	Purpose And Scope.....	1
1.3	Methodology	1
2.0	ASBESTOS/LEAD SURVEY.....	4
2.1	Visual Inspection	4
2.2	Analytical Results.....	5
3.0	CONCLUSION	11
4.0	LIMITATIONS.....	14
5.0	SIGNATURES OF PROFESSIONALS.....	15

APPENDICES

- Appendix A** Analytical Results, Chain-of-Custody Forms, XRF Data Sheets
- Appendix B** Site Plan
- Appendix C** Certifications
- Appendix D** Photographic Documentation
- Appendix E** California DPH Form 8552

1.0 INTRODUCTION

1.1 Property Description

Address:	508 4th Street Los Angeles, California
Nature of Use:	Multi-Family
Number of Buildings:	One
Number of Floors:	Three
Surveyed By:	Freddy Torres, Inspector
Assessment Date/Time:	May 17, 2018 10:00 am

1.2 Purpose And Scope

The purpose of this asbestos and lead-based paint survey (survey) was to sample and analyze suspect asbestos-containing materials (ACM) and suspect lead-based paint (LBP) which could present an exposure risk during potential renovation activities. The suspect asbestos containing materials sampled during the survey were limited to major components within accessible areas of the interior and exterior of the building. The roof was not sampled as a part of this survey.

Multi-family housing is defined as any group of units of similar construction with 21 or more units built before 1960 or are of unknown age, or 10 or more units built from 1960 through 1977. The number of units to be tested is based upon the U.S. Department of Housing and Urban Development, Chapter 7: Lead-Based Paint Inspection, as specified in Table 7.3. Thirty-one units were accessed at the site to evaluate the presence of presumed ACM and LBP. Thirty-one units are the prescribed number of units according to the U.S. Department of Housing and Urban Development, Chapter 7: Lead-Based Paint Inspection, for a multi-family residential complex constructed prior to 1960 with 39 units.

1.3 Methodology

ASBESTOS

Suspect ACM were sampled according to the guidelines set forth in 40 CFR Part 763, and later analyzed using the Polarized Light Microscopy (PLM) method in accordance with the EPA reference method 600/R-93/116 for Determination of Asbestos in Bulk Building Materials.

The United States Environmental Protection Agency (USEPA) as set forth in 40 CFR 763, defines a homogeneous area as "an area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in color and texture." The regulation requires that a minimum number of representative samples be collected from each homogeneous area. If asbestos is identified in any samples from a homogeneous area, the entire homogeneous area is considered to contain asbestos.

The aforementioned testing and analytical constraints can affect the findings and recommendations of this survey. Specifically, no assurance is given regarding the asbestos content of the samples beyond these parameters. Further investigation is not recommended unless the client can determine it is cost-effective to do so.

The ACM most likely to release asbestos fibers are those which are in a friable state. Friability describes the condition of asbestos. The definition of friable is any material, when dry, that is capable of being crumbled, pulverized or reduced to powder by hand pressure (40 CFR 763).

Non-friable sources of asbestos are materials containing cement or asphalt binder which may become friable and release fibers if the sources are exposed to actions such as abrasion, drilling, cutting, fracturing or hammering. Non-friable sources of asbestos do not typically pose a significant exposure risk if they remain in good condition and are not disturbed. During renovation or demolition activities, non-friable sources may become friable and thus may pose an exposure risk.

The PLM method is the most commonly used method to analyze building materials for the presence of asbestos. This method utilizes the optical properties of minerals to identify the selected constituent. The use of this method enables identification of the type and the percentage of asbestos in a given sample. The detection limit of the PLM method for asbestos identification is typically one percent (1%) asbestos.

The California Occupational Safety and Health regulations define asbestos-containing construction material (ACCM) as any material which contains greater than one-tenth of one percent (0.1%) asbestos. Materials containing "trace" amounts of asbestos are reported by the laboratory as <1% which could qualify as ACCM in the State of California. Further quantification is possible utilizing either Transmission Electron Microscopy (TEM) analysis or point counting via PLM.

LEAD-BASED PAINT

The subject property was visually inspected and potential LBP were identified. The painted/finished surfaces containing suspect LBP were analyzed and the data was recorded using a XRF.

Painted or varnished surfaces were analyzed for LBP using a hand-held XRF device. The XRF uses a Cobalt 57 (Co-57) isotope radioactive source to 'excite' the atomic structure of painted surfaces. Once 'excited', lead (Pb) atoms emit unique x-ray fluorescence radiation energy. The radiation detector within the XRF then translates these x-rays into a quantitative measure of lead concentration. If present, the XRF will determine the amount of lead in paint with a 95% confidence level. The lead concentrations are reported in milligrams per square centimeter (mg/cm²).

Measurements were taken at locations representative of all painted or varnished surfaces for each different testing combination in the areas inspected. In order to obtain a reading, the XRF analyzer is placed with the face of the instrument flush against the surface to be tested. It is then held in place for the duration of the sample, approximately 4 to 16 source seconds, or until the measurement has reached the acceptable range of accuracy. The sampling time is dependent on the age of the radioactive source inside the XRF.

XRF analysis yields the total lead content of a painted surface, hereby not distinguishing between individual concentrations of painted layers. The XRF was calibrated with a National Institute of Standards and Testing (NIST) calibration surface prior to and post analysis of painted surfaces.

The subject property's orientation is described using HUD's recommended guidelines, assigning the letters A, B, C and D to each side. Side A corresponds to the main entrance of each building. The remaining side identifications are assigned in a clock-wise manner. Each tested component location is identified using the building's assigned letter as a reference point.

The HUD Guidelines for lead-containing paint require a lead hazard abatement activity in cases where lead content is above one half of one percent (0.5%) by weight or equal to or in excess of one milligram per square centimeter (1.0 mg/cm²). This requirement for lead hazard abatement only applies to housing that is administrated or funded by HUD. *Section 1017 of the HUD Guidelines, Residential LBP Reduction Act of 1992*, otherwise known as "Title X", defines a lead-based paint hazard as "any condition that causes exposure to lead that would result in adverse human health effects" resulting from lead-contaminated dust, bare, lead-contaminated soil, and/or lead-contaminated paint that is deteriorated or present on accessible, friction, or impact surfaces. Therefore, under Title X, intact LBP on most walls and ceilings would not be considered a "hazard", although the paint should be maintained and its condition monitored to ensure that it does not deteriorate and become a hazard.

The California Department of Public Health (CDPH) *Title 17 CCR Division 1, Chapter 8, Section 35033* defines LBP as paint or other surface coating that contains any amount of lead equal to or in excess of 1.0 mg/cm² or more than 0.5% by weight. This requirement for lead hazard abatement only applies to public and residential buildings.

Cal/OSHA and Federal OSHA Lead in Construction Standards consider any amount of lead in paint to be a concern (including levels below regulated thresholds) during renovation and demolition activities.

Los Angeles County defines "dangerous levels of lead-bearing substances" as any paint, varnish, lacquer, putty, plaster, or similar coating which contains lead or its compounds in excess of 0.7 mg/cm² by XRF (Los Angeles County Code, Title 11, Health and Safety Chapter 11.28).

In general, there are many other building materials which can contain lead in the average building. When conducting construction or demolition activities which disturb lead in any amount or create an exposure to workers, the employer is required to provide worker protection and conduct exposure assessments. Employers should consult Federal OSHA Regulations at 29 CFR 1926.62, "Lead in Construction" standards for complete requirements prior to construction or demolition activities.

Notification must be given to all contractors at the work site prior to the start of activities that may create a lead hazard. Characterization and disposal of lead-containing waste materials (LCWMs) must comply with federal, state and local authorities.

Contractors must maintain current licenses as required by applicable state or local jurisdictions for the removal, transport, disposal of LCWMs, or other regulated lead-based paint activities.

2.0 ASBESTOS/LEAD SURVEY

2.1 Visual Inspection

During the course of the property visit, Mr. Freddy Torres, performed a review of accessible areas of the subject building for the presence of suspect ACM and LBP. The purpose of this assessment is for renovation purposes only; therefore, additional suspect ACM and/or LBP could be present.

Partner did not attempt to disassemble mechanical equipment, open pipe chases, or assess materials within wall voids. Regardless of the thoroughness of a survey, the possibility exists that some areas containing ACM and/or LBP were not identified, inaccessible, or different from those materials at specific locations.

The subject property consists of one building constructed with exterior brick finishes with interior drywall finishes, and multiple vinyl floorings. The subject property was occupied at the time of the survey.

ASBESTOS

Suspect asbestos-containing materials observed at the time of the inspection were sampled and analyzed for asbestos content. The survey also established whether any of the substrates sampled could be considered friable and/or significantly damaged or capable of immediate worker exposure.

LEAD-BASED PAINT

Suspect painted surfaces observed at the time of the inspection were tested for lead content. The inspection also evaluated the condition of the painted surfaces sampled and whether they constituted a high risk of worker exposure. Painted or varnished surfaces were analyzed for LBP using a hand-held XRF device. The lead concentrations are reported in milligrams per square centimeter (mg/cm²).

2.2 Analytical Results

ASBESTOS

Thirty units were accessed at the site to evaluate the presence of presumed ACM. A total of 25 bulk samples of presumed ACM were collected for analysis. The samples were grouped into homogeneous categories, assigned individual sample numbers, sealed in plastic bags, and transported under proper chain-of-custody documentation to LA Testing. LA Testing is accredited by the American Industrial Hygiene Association (AIHA) and the National Voluntary Laboratory Accreditation Program (NVLAP No. 200232-0) for the analysis of asbestos bulk samples. Refer to Appendix A for analytical data.

Analytical Results (ACM)

Sample No.	Location	Description	Asbestos Content
1-01	1 st Floor Entry	Drywall & Associated Joint Compound	<i>None Detected</i>
1-02	Community Room	Drywall & Associated Joint Compound	<i>None Detected</i>
1-03	Laundry Room	Drywall & Associated Joint Compound	<i>None Detected</i>
1-04	Unit 212	Drywall & Associated Joint Compound	<i>None Detected</i>
1-05	Unit 209	Drywall & Associated Joint Compound	<i>None Detected</i>
1-06	Unit 310	Drywall & Associated Joint Compound	<i>None Detected</i>
1-07	Unit 315	Drywall & Associated Joint Compound	<i>None Detected</i>
2-01	1 st Floor Storage	Fiberglass Pipe Insulation	<i>None Detected</i>
2-02	1 st Floor Storage	Fiberglass Pipe Insulation	<i>None Detected</i>
2-03	1 st Floor Storage	Fiberglass Pipe Insulation	<i>None Detected</i>
3-01	Unit 211	White 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
3-02	Unit 212	White 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
3-03	Unit 208	White 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
4-01	2 nd Floor Hallway	Grey 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
4-02	3 rd Floor Hallway	Grey 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
4-03	3 rd Floor Hallway	Grey 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>

Sample No.	Location	Description	Asbestos Content
5-01	Community Room	Green 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
5-02	Community Room	Green 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
5-03	Unit 305	Green 12x12 Vinyl Floor Tile plus Mastic	<i>None Detected</i>
6-01	Unit 213	Beige Sheet Vinyl Flooring	<i>None Detected</i>
6-02	Unit 212	Beige Sheet Vinyl Flooring	<i>None Detected</i>
6-03	Unit 302	Beige Sheet Vinyl Flooring	<i>None Detected</i>
7-01	Stairwell	Grey Vinyl Stair Tread	<i>None Detected</i>
7-02	Stairwell	Grey Vinyl Stair Tread	<i>None Detected</i>
7-03	Stairwell	Grey Vinyl Stair Tread	<i>None Detected</i>

Asbestos-containing material is defined as any material containing more than one percent (1%) asbestos as determined using PLM (40 CFR 61).

In California, asbestos-containing construction material (ACCM) is defined by Cal-OSHA as any material containing more than 0.1% (one-tenth of one percent) of asbestos by weight (CCR Title 8, Section 1529).

Documentation of the laboratory results should be retained as a reference for future renovation/demolition activities.

LEAD-BASED PAINT

Thirty units were accessed at the site to evaluate the presence of presumed LBP. A representative number of interior/exterior painted surfaces/components were tested for LBP at the subject property.

A total of 258 XRF readings (including 6 calibration readings) were collected throughout the subject property. Of the 252 actual XRF readings taken, none contained a lead content greater than 0.7 mg/cm^2 , which is the current regulatory threshold for the requirement of lead-safe work practices in the County of Los Angeles, as assessed using an XRF instrument. Additional readings confirmed detectable levels of lead in paint (less than 0.7 mg/cm^2). Please see Appendix A for Suspect Lead-Based Paint Inspection Results.

LBP is defined under the US Department of Housing and Urban Development (HUD) and the Environmental Protection Agency (EPA) as paint or other surface coating with lead content equal to or greater than 1.0 mg/cm^2 of surface area by XRF or 0.5% by weight (5,000 parts per million (ppm)) by paint chip analysis. :

Dust Testing

Partner collected 60 samples of suspect lead-contaminated dust in the residential units accessed for XRF testing. A dust-lead hazard is defined as surface dust in a residential dwelling or child-occupied facility that contains a mass-per-area concentration of lead equal to or exceeding 40 $\mu\text{g}/\text{ft}^2$ on floors or 250 $\mu\text{g}/\text{ft}^2$ on interior window sills based on wipe samples (40 CFR 745.65). The testing results are provided in the following table:

Dust Wipe Sample Results

Sample No.	Location	Description	Results (mg/cm²)
LW1	Unit 212 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW2	Unit 211 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW3	Unit 210 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW4	Unit 213 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW5	Unit 214 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW6	Unit 209 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW7	Unit 215 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW8	Unit 208 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW9	Unit 201 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW10	Unit 207 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW11	Unit 202 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW12	Unit 204 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW13	Unit 203 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW14	Unit 205 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW15	Unit 206 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW16	Unit 312 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW17	Unit 311 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW18	Unit 310 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$
LW19	Unit 313 Floor	Wipe	<10 $\mu\text{g}/\text{ft}^2$

Sample No.	Location	Description	Results (mg/cm ²)
LW20	Unit 315 Floor	Wipe	<10 µg/ft ²
LW21	Unit 314 Floor	Wipe	<10 µg/ft ²
LW22	Unit 309 Floor	Wipe	<10 µg/ft ²
LW23	Unit 308 Floor	Wipe	<10 µg/ft ²
LW24	Unit 301 Floor	Wipe	<10 µg/ft ²
LW25	Unit 302 Floor	Wipe	<10 µg/ft ²
LW26	Unit 305 Floor	Wipe	<10 µg/ft ²
LW27	Unit 307 Floor	Wipe	<10 µg/ft ²
LW28	Unit 306 Floor	Wipe	<10 µg/ft ²
LW29	Unit 304 Floor	Wipe	<10 µg/ft ²
LW30	Unit 303 Floor	Wipe	<10 µg/ft ²
LW31	Unit 212 Window Sill	Wipe	<13 µg/ft ²
LW32	Unit 211 Window Sill	Wipe	<13 µg/ft ²
LW33	Unit 210 Window Sill	Wipe	<13 µg/ft ²
LW34	Unit 213 Window Sill	Wipe	<13 µg/ft ²
LW35	Unit 214 Window Sill	Wipe	<13 µg/ft ²
LW36	Unit 209 Window Sill	Wipe	<13 µg/ft ²
LW37	Unit 215 Window Sill	Wipe	<13 µg/ft ²
LW38	Unit 208 Window Sill	Wipe	<13 µg/ft ²
LW39	Unit 201 Window Sill	Wipe	<13 µg/ft ²
LW40	Unit 207 Window Sill	Wipe	<13 µg/ft ²
LW41	Unit 202 Window Sill	Wipe	<13 µg/ft ²
LW42	Unit 204 Window Sill	Wipe	<13 µg/ft ²
LW43	Unit 203 Window Sill	Wipe	<13 µg/ft ²
LW44	Unit 205 Window Sill	Wipe	<13 µg/ft ²

Sample No.	Location	Description	Results (mg/cm ²)
LW45	Unit 206 Window Sill	Wipe	<13 µg/ft ²
LW46	Unit 312 Window Sill	Wipe	<13 µg/ft ²
LW47	Unit 311 Window Sill	Wipe	<13 µg/ft ²
LW48	Unit 310 Window Sill	Wipe	<13 µg/ft ²
LW49	Unit 313 Window Sill	Wipe	<13 µg/ft ²
LW50	Unit 315 Window Sill	Wipe	<13 µg/ft ²
LW51	Unit 314 Window Sill	Wipe	<13 µg/ft ²
LW52	Unit 309 Window Sill	Wipe	<13 µg/ft ²
LW53	Unit 308 Window Sill	Wipe	<13 µg/ft ²
LW54	Unit 301 Window Sill	Wipe	<13 µg/ft ²
LW55	Unit 302 Window Sill	Wipe	<13 µg/ft ²
LW56	Unit 305 Window Sill	Wipe	<13 µg/ft ²
LW57	Unit 307 Window Sill	Wipe	<13 µg/ft ²
LW58	Unit 306 Window Sill	Wipe	<13 µg/ft ²
LW59	Unit 304 Window Sill	Wipe	<13 µg/ft ²
LW60	Unit 303 Window Sill	Wipe	<13 µg/ft ²
BLK1	Blank	Wipe	<10 µg/ft ²
BLK2	Blank	Wipe	<10 µg/ft ²

The analytical results indicate that none of the dust wipe samples exceeded the dust-lead hazard thresholds.

3.0 CONCLUSION

ASBESTOS

The roof appeared to be in good overall condition and was not sampled as a part of the survey. None of the materials sampled were found to contain asbestos:

Friable Regulated Asbestos-Containing Materials (RACM)

- None

Non-Friable Category I and II ACM

- None

Asbestos-Containing Construction Material (ACCM) – Cal/OSHA (<1% Asbestos)

- None

The EPA recommends that all ACM be removed by a certified asbestos contractor prior to any renovation or demolition activities that may impact the material. In the absence of planned renovation/demolition activities, the EPA recommends that ACMs be managed in-place whenever asbestos is identified in a building. Any damaged asbestos materials should be removed, repaired, encapsulated, or enclosed. Asbestos materials that are not damaged may be managed in place in accordance with a written Operations and Maintenance Program.

Federal, state and local laws require building owners and/or their representatives, prior to any demolition and/or renovation operations which may disturb any asbestos-containing materials in their buildings, to meet the following requirements:

- Notifications,
- Removal techniques (such as wetting) for asbestos-containing materials,
- Clean-up procedures,
- Waste storage and disposal requirements.

The potential exists for additional suspect ACM to be exposed during demolition and/or renovation activities. Such materials should be sampled and analyzed for asbestos content prior to any renovation and/or demolition activities that could impact these materials.

LEAD-BASED PAINT

The results of this inspection indicate that no lead in amounts greater than or equal to 0.7 mg/cm² in paint was found in building components, using the inspection protocol in Chapter 7 of the *HUD Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (2012)*.

Some of the samples also contained detectable concentrations of lead. Due to the representative nature of the testing under HUD Chapter 7 Guidelines, those testing combinations that tested positive for LBP are indicative of all similar testing combinations also being positive for LBP. Likewise, the testing combinations that tested negative for LBP are indicative of all similar testing combinations also being negative for LBP. Any inaccessible areas should be presumed as LBP until they can be proven otherwise by testing.

No Lead paint hazards were identified within the areas accessed during this assessment. If lead paint hazards are identified in areas not previously accessed, they should be properly remediated in accordance with all applicable local, state and federal regulations.

Poor surfaces are considered to be a hazard and should be corrected. Fair surfaces should be repaired, but are not yet considered to be a hazard; if not repaired, they should be monitored frequently. Intact surfaces should be managed under an Operations and Maintenance Plan which includes periodic inspections for condition changes in the paint.

Damaged paint or deteriorated paint should undergo corrective action to stabilize the paint. This work should be conducted by trained workers utilizing lead-safe work practices. Paint stabilization usually involves removing loose and flaking paint, and repainting with a layer of protective non-LBP. If any construction or renovation work is conducted on the subject property, contractors and tenants should be notified about the presence, location, and type of LBP.

The analytical results indicate that none of the dust wipe samples exceeded the dust-lead hazard threshold

Work activities impacting LBP pose a potential exposure risk for workers and/or building occupants. Workers trained in proper safety and respiratory techniques should perform renovation activities that may impact the LBP described in this report. All construction work where an employee may be occupationally exposed to lead must comply with OSHA requirements set forth in 29 CFR 1926.62. This regulation requires initial employee exposure monitoring to evaluate worker exposure during work that disturbs lead-containing materials (lead present in detectable levels). Partner suggests that engineering controls, respiratory protection and personal protective equipment be employed at the start of a project that could disturb LBP.

Once renovation activities have been completed, a clearance examination by a Lead Inspector/Assessor is required by HUD to determine the effectiveness of the paint stabilization. Waste items generated during a renovation, abatement, or demolition project should be properly sampled and profiled to determine the final disposition of the waste.

The potential exists for additional suspect lead-containing materials to be exposed during demolition and/or renovation activities. Such materials should be sampled and analyzed for lead content prior to any renovation and/or demolition activities that could impact these materials.

A copy of this summary must be provided to new lessees (tenants) and purchasers of this property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to new tenants. Landlords (lessors) and sellers are also required to distribute an educational pamphlet and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

Section 1018 of Title X requires the following activities before a purchaser or lessee is obligated under a contract to purchase or lease target housing: (1) Sellers and lessors must provide purchasers and lessees with a lead hazard information pamphlet, as developed under section 406(a) of TSCA; (2) sellers and lessors must disclose the presence of known lead-based paint and/or lead-based paint hazards in such housing and provide purchasers and lessees with any lead hazard evaluation report available to the seller or lessor; (3) sellers must permit purchasers a 10-day opportunity to conduct a risk assessment or inspection for the presence of lead-based paint hazards; and (4) sales contracts must include an attached Lead Warning Statement and acknowledgment, signed by the purchaser.

4.0 LIMITATIONS

No warranties expressed or implied, are made by Partner or its subcontractor EMSL/LA Testing, or their employees as to the use of any information, apparatus, product or process disclosed in this report. Every reasonable effort has been made to assure correctness. If an Asbestos and/or Lead Abatement Contractor or other Demolition/Construction Contractor is employed, such contractor should bring any discrepancies found in this report as it relates to current site conditions or newly discovered site conditions to the immediate attention of Partner.

This report should not be used solely for abatement bidding purposes. Any quantities of ACM and/or lead hazards listed are estimates only and not meant to be used to solicit abatement quotations. These quantities should be confirmed by abatement contractors prior to submitting bids for abatement.

State-of-the-art practices have been employed to perform this asbestos and lead survey. The scope of this evaluation was severely limited to areas which were considered reasonably accessible (i.e., less than 15 feet from the floor), or within range of a visual inspection through reasonable means. No demolition or product research was performed in attempts to reveal material compositions. The services consist of professional opinions and recommendations made in accordance with generally accepted engineering principles/practices. These services are designed to provide an analytical tool to assist the client. Partner and its employees/representatives bear no responsibility for the actual condition of the structure or safety of this site pertaining to asbestos and/or lead contamination regardless of the actions taken by the survey team or the client.

The asbestos sampling was limited to major building components within accessible areas of the interior only.

5.0 SIGNATURES OF PROFESSIONALS

Partner has performed an asbestos and lead-based paint survey on the property located at 508 4th Street Los Angeles, California in general conformance with the scope and limitations of the protocol and the limitations stated earlier in this report. Exceptions to or deletions from this protocol are discussed earlier in this report.

Prepared By:

Partner Engineering and Science, Inc.



Freddy Torres, CAC, CLIA
Cal/DOSH #10-4593
Cal/DPH #17424



Karen Willing, CAC, CLIA
Senior Reviewer

APPENDIX A

- 1 ANALYTICAL RESULTS**
- 2 CHAIN OF CUSTODY**
- 3 XRF DATA SHEETS**



EMSL Analytical, Inc.

3356 West Catalina Drive Phoenix, AZ 85017

Tel/Fax: (602) 276-4344 / (602) 276-4053

<http://www.EMSL.com> / phoenixlab@emsl.com

EMSL Order: 121803198

Customer ID: 32PRTN78

Customer PO: 18-215754.1

Project ID:

Attention: Freddy Torres
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500

Fax:

Received Date: 05/21/2018 10:00 AM

Analysis Date: 05/21/2018 - 05/22/2018

Collected Date: 05/17/2018

Project: 18-215754.1 508 E.4th St. Los Angeles, CA

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1-01-Texture <small>121803198-0001 Paint excluded.</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-01-Tape <small>121803198-0001A</small>	DWJC	Beige Fibrous Homogeneous	99% Cellulose	1% Non-fibrous (Other)	None Detected
1-01-Joint Compound <small>121803198-0001B</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-01-Drywall <small>121803198-0001C</small>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-02-Joint Compound <small>121803198-0002 Paint excluded.</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-02-Drywall <small>121803198-0002A</small>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-03-Texture <small>121803198-0003 Paint excluded.</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-03-Tape <small>121803198-0003A</small>	DWJC	Beige Fibrous Homogeneous	99% Cellulose	1% Non-fibrous (Other)	None Detected
1-03-Joint Compound <small>121803198-0003B</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-03-Drywall <small>121803198-0003C</small>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-04-Joint Compound <small>121803198-0004 Paint excluded.</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-04-Drywall <small>121803198-0004A</small>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-05-Texture <small>121803198-0005 Paint excluded.</small>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-05-Tape <small>121803198-0005A</small>	DWJC	Beige Fibrous Homogeneous	99% Cellulose	1% Non-fibrous (Other)	None Detected

Initial report from: 05/23/2018 12:06:26



EMSL Analytical, Inc.

3356 West Catalina Drive Phoenix, AZ 85017

Tel/Fax: (602) 276-4344 / (602) 276-4053

<http://www.EMSL.com> / phoenixlab@emsl.com

EMSL Order: 121803198
Customer ID: 32PRTN78
Customer PO: 18-215754.1
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1-05-Joint Compound <i>121803198-0005B</i>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-05-Drywall <i>121803198-0005C</i>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-06-Joint Compound <i>121803198-0006</i> <i>Paint excluded.</i>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-06-Drywall <i>121803198-0006A</i>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
1-07-Joint Compound <i>121803198-0007</i> <i>Paint excluded.</i>	DWJC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
1-07-Drywall <i>121803198-0007A</i>	DWJC	Brown/White Fibrous Heterogeneous	10% Cellulose 2% Glass	85% Gypsum 3% Non-fibrous (Other)	None Detected
2-01-Wrap <i>121803198-0008</i>	Fiberglass P.I.	Various Fibrous Heterogeneous	40% Cellulose 5% Glass	55% Non-fibrous (Other)	None Detected
2-01-Insulation <i>121803198-0008A</i>	Fiberglass P.I.	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
2-02-Wrap <i>121803198-0009</i>	Fiberglass P.I.	Various Fibrous Heterogeneous	40% Cellulose 5% Glass	55% Non-fibrous (Other)	None Detected
2-02-Insulation <i>121803198-0009A</i>	Fiberglass P.I.	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
2-03-Wrap <i>121803198-0010</i>	Fiberglass P.I.	Various Fibrous Heterogeneous	40% Cellulose 5% Glass	55% Non-fibrous (Other)	None Detected
2-03-Insulation <i>121803198-0010A</i>	Fiberglass P.I.	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
3-01-VFT <i>121803198-0011</i>	White 12x12 VFT Plus Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
3-01-Mastic <i>121803198-0011A</i>	White 12x12 VFT Plus Mastic	Clear Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
3-02-VFT <i>121803198-0012</i> <i>No Mastic present.</i>	White 12x12 VFT Plus Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
3-03-VFT <i>121803198-0013</i> <i>No Mastic present.</i>	White 12x12 VFT Plus Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-01-VFT <i>121803198-0014</i>	Grey 12x12 VFT Plus Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-01-Mastic <i>121803198-0014A</i>	Grey 12x12 VFT Plus Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 05/23/2018 12:06:26



EMSL Analytical, Inc.

3356 West Catalina Drive Phoenix, AZ 85017

Tel/Fax: (602) 276-4344 / (602) 276-4053

<http://www.EMSL.com> / phoenixlab@emsl.com

EMSL Order: 121803198
Customer ID: 32PRTN78
Customer PO: 18-215754.1
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
4-02-VFT <i>121803198-0015</i>	Grey 12x12 VFT Plus Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-02-Mastic <i>121803198-0015A</i>	Grey 12x12 VFT Plus Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-03-VFT <i>121803198-0016</i>	Grey 12x12 VFT Plus Mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-03-Mastic <i>121803198-0016A</i>	Grey 12x12 VFT Plus Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
5-01-VFT <i>121803198-0017</i>	Green 12x12 VFT Plus Mastic	Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
5-01-Mastic <i>121803198-0017A</i>	Green 12x12 VFT Plus Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
5-02-VFT <i>121803198-0018</i> <i>No Mastic present.</i>	Green 12x12 VFT Plus Mastic	Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
5-03-VFT <i>121803198-0019</i> <i>No Mastic present.</i>	Green 12x12 VFT Plus Mastic	Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
6-01-SVF <i>121803198-0020</i>	Beige SVF	White/Beige Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
6-02-SVF <i>121803198-0021</i>	Beige SVF	White/Beige Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
6-03-SVF <i>121803198-0022</i>	Beige SVF	White/Beige Fibrous Heterogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
6-03-Mastic <i>121803198-0022A</i>	Beige SVF	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
6-03-Leveler <i>121803198-0022B</i>	Beige SVF	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
7-01 <i>121803198-0023</i>	Grey Vinyl Stair Tread	Gray Non-Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
7-02 <i>121803198-0024</i>	Grey Vinyl Stair Tread	Gray Non-Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
7-03 <i>121803198-0025</i>	Grey Vinyl Stair Tread	Gray Non-Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected

Initial report from: 05/23/2018 12:06:26



EMSL Analytical, Inc.

3356 West Catalina Drive Phoenix, AZ 85017

Tel/Fax: (602) 276-4344 / (602) 276-4053

<http://www.EMSL.com> / phoenixlab@emsl.com

EMSL Order: 121803198

Customer ID: 32PRTN78

Customer PO: 18-215754.1

Project ID:

Analyst(s) _____

Isai Portillo (16)

Jacob Markey (32)

Michelle Wilson, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Phoenix, AZ NVLAP Lab Code 200811-0, AZ0937

Initial report from: 05/23/2018 12:06:26

12/803198

Heart

CHAIN OF CUSTODY-BULK SUSPECT ACM ANALYSIS

Partner ESI

2154 Torrance Blvd, Suite 200

Torrance, California 90501

Phone (310)615-4500, Fax (310)866-928-7408

CLIENT: _____

PROJECT #: 18-215754.1

Lab: U.A. Testing

Technician: Freddy Torres

Sampling Date: 5/21/18

PROJECT LOCATION: SOBEA St.

Los Angeles, Ca

Page: 1 of 2

Sample #	Material Description	Sample Location	Material Location	Quantity (SF or LF)	Friable (Y or N)	Condition (G/D/SD)
1-01	DWJC	First Floor Entry	Walls & Ceilings		N	G
1-02	↓	Community Rm	↓		↓	↓
1-03		Laundry Rm				
1-04		Rm 212				
1-05		209				
1-06		310				
1-07		315				
2-01		Fiberglass P.I				
2-02	↓	↓	↓		↓	↓
2-03						

Please Email results to Krobets@partneresi.com

CONTACT: Freddy Torres 310-200-4006

TAT: _____ SD 24HR 48HR 72HR

ANALYSIS: PLM Bulk-EPA/600 1,000 Pt Count Other

Relinquished: [Signature]

Date/Time: 5-8-18

Relinquished: _____

Date/Time: *Per Freddy 48HR

Received: [Signature]

Date/Time: 5/21/18 10:00 am

Received: _____

Date/Time: TAT 5/21/18

Legend:	ACP - ACOUSTIC CEILING PANEL	N - North E - East
SAACM - SPRAY-APPLIED ACOUSTIC CEILING MATERIAL	ACT - ACOUSTIC CEILING TILE	S - South W - West
DWJC - DRY WALL JOINT COMPOUND	RPPM - ROOF PATCH & PENETRATION MASTIC	G - Good
VFT/M - VINYL FLOOR TILE & MASTIC	ARS - ASPHALT ROOF SHINGLES	D - Damaged
SVF - SHEET VINYL FLOORING	ROR - ROLLED-ON ROOFING	SD - Sig. Damaged
VCB/M - VINYL COVE BASE & MASTIC	Comments:	
HDI - HEATING DUCT INSULATION	Transite Pipe QTY _____ Size _____	
PI - PIPE INSULATION		
BAI - BLOWN-IN ATTIC INSULATION		

EMSL Fedex 7954 8780 6068

Order ID: 121803198

Page 1 of 2

CHAIN OF CUSTODY-BULK SUSPECT ACM ANALYSIS

Partner ESI

2154 Torrance Blvd, Suite 200
Torrance, California 90501

Phone (310)615-4500, Fax (310)866-928-7408

18-215754.1

Page of

Sample #	Material Description	Sample Location	Material Location	Quantity (SF or LF)	Friable (Y or N)	Condition (G/D/SD)
3-01	white 12x12 VFT plus Mastic	Unit 211	Various Floorings		N	G
3-02	↓	↓ 212	↓		↓	↓
3-03	↓	↓ 208	↓		↓	↓
4-01	Grey	2nd Floor Hallway				
4-02	↓	3rd ↓ ↓				
4-03	↓	↓ ↓ ↓				
5-01	Green	Community Room				
5-02	↓	↓				
5-03	↓	Unit 305				
6-01	Beige SVF	↓ 213				
6-02	↓	↓ 212				
6-03	↓	↓ 302	↓			
7-01	Grey Vinyl Stair Tread	Stairwell	Stairwell			
7-02	↓	↓	↓		↓	↓
7-03	↓	↓	↓		↓	↓



Chain of Custody

LATESTING Order Number (Lab Use Only):

#331810986

LATESTING
520 MISSION STREET
SOUTH PASADENA, CA 91030

PHONE: (800) 303-0047
FAX: (323) 254-9982

Company: <u>Partner Engineering</u>		LATESTING-Bill to: <input type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street:		Third Party Billing requires written authorization from third party	
City: <u>Torrance</u>	State/Province: <u>CA</u>	Zip/Postal Code:	Country:
Report To (Name): <u>Kevin Roberts</u>		Fax #:	
Telephone #: <u>310-200-4008</u>		Email Address:	
Project Name/Number: <u>508 4th St Los Angeles</u>			
Please Provide Results: <input type="checkbox"/> Fax <input type="checkbox"/> Email		Purchase Order:	U.S. State Samples Taken:

Turnaround Time (TAT) Options* - Please Check

3 Hours
 6 Hours
 24 Hours
 48 Hours
 3 Days
 4 Days
 5 Days
 2 Weeks

*For RUSH TAT's Please Call Ahead to Confirm Lab Hours and Availability

Asbestos

PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ 8hr. TWA TEM - Air <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Water Fibers $\geq 10\mu\text{m}$ <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	PLM - Bulk <input type="checkbox"/> PLM EPA 600/R-93/116 <input type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> NYS 198.1 (friable-NY) <input type="checkbox"/> NYS 198.6 (non-friable-NY) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/ Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)	TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> EPA Reg. 1 Screening Protocol (Qualitative)
TEM - Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe-ASTM D6480		Other:

Lead (Pb)

Flame Atomic Absorption <input type="checkbox"/> Chips SW846-7000B or AOAC 974.02 <input type="checkbox"/> Soil SW846-7000B/7420 <input type="checkbox"/> Air NIOSH 7082 <input type="checkbox"/> Wastewater SM3111B or SW846-7000B/7420 <input type="checkbox"/> ASTM Wipe SW846-7000B/7420 <input checked="" type="checkbox"/> non ASTM Wipe SW846-7000B/7420 <input type="checkbox"/> TCLP SW846-1311/7420/SM 3111B	ICP <input type="checkbox"/> Air NIOSH 7300 Modified <input type="checkbox"/> non ASTM Wipe SW846-6010B or C <input type="checkbox"/> ASTM Wipe SW846-6010B or C <input type="checkbox"/> Soil SW846-6010 B or C <input type="checkbox"/> Waste Water SW846-6010B or C <input type="checkbox"/> TCLP SW846-6010B or C
Graphite Furnace Atomic Absorption <input type="checkbox"/> Soil SW846-7421 <input type="checkbox"/> Wastewater EPA 200.9 <input type="checkbox"/> Air NIOSH 7105 <input type="checkbox"/> Drinking Water EPA 200.9	Other: <input type="checkbox"/>

Materials Science

Common Particle ID (large particles)
 Full Particle ID (environmental dust)
 Basic Material ID (solids)
 Advanced Material ID
 Physical Testing (Tensile, Compression)
 Combustion-by-products (soot, char, etc.)
 X-Ray Fluorescence (elem. analysis)
 X-Ray Diffraction (Crystalline Part.)
 MMVF's (Fibrous glass, RCF's)
 Particle Size (sieve/microscopy/laser)
 Combustible Dust
 Petrographic Examination
Other:

Microbiology

Wipe and Bulk Samples <input type="checkbox"/> Mold & Fungi - Direct Examination <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi Culture (Genus & Species) <input type="checkbox"/> Bacterial Count & ID (Up to Three Types) <input type="checkbox"/> Bacterial Count & ID (Up to Five Types) <input type="checkbox"/> MRSA <input type="checkbox"/> <i>Pseudomonas aeruginosa</i>	Air Samples <input type="checkbox"/> Mold & Fungi (Spore Trap) <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi (Genus & Species) <input type="checkbox"/> Bacterial Culture & ID (Up to Three Types) <input type="checkbox"/> Bacterial Culture & ID (Up to Five Types) <input type="checkbox"/> Endotoxin Testing
Water Samples <input type="checkbox"/> Total Coliform & E.coli (P/A) <input type="checkbox"/> Fecal Coliform (SM 9222D) <input type="checkbox"/> Sewage Screen <input type="checkbox"/> Heterotrophic Plate Count (SM 9215)	Real Time Q-PCR (See Analytical Guide for Code) Code: Legionella <input type="checkbox"/> Level 1 <input type="checkbox"/> Level 2 <input type="checkbox"/> Level 3 <input type="checkbox"/> Level 4 Other: <input type="checkbox"/>

IAQ

Nuisance Dust NIOSH 0500 0600
 Airborne Dust PM10 TSP
 Silica Analysis: All Species
 Silica Analysis - Single Species
 Alpha Quartz Cristobalite Tridymite
 HVAC Efficiency
 Carbon Black
 Airborne Oil Mist
Other:

**Comments/Special Instructions:

Client Sample #'s	<u>LOW - BLK 2</u>	Total # of Samples:	<u>62</u>
Relinquished (Client):		Date:	<u>5-21-18</u>
Received (Lab):		Date:	<u>5/21/18</u>
		Time:	<u>8:00</u>
		Time:	<u>2:40P</u>



Chain of Custody
LA Testing Order Number (Lab Use Only):

#331810986

LA TESTING
 520 MISSION STREET
 S. PASADENA, CA 91030
 PHONE: (323) 254-9960
 FAX: (323) 254-9982

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
LW 1	Unit 212 Floor	144 in. ²	5/17/18
2	211		
3	210		
4	213		
5	214		
6	209		
7	215		
8	208		
9	201		
10	207		
11	202		
12	204		
13	203		
14	205		
15	206		
16	312		

*Comments/Special Instructions:



Chain of Custody
LATESTING Order Number (Lab Use Only):

#331810986

LATESTING
 520 MISSION STREET
 SOUTH PASADENA, CA 91030
 PHONE: (800) 303-0047
 FAX: (323) 254-9982

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
LW 17	Unit 311 Floor	144 in. ²	5/17/18
18	310		
19	313		
20	315		
21	314		
22	309		
23	308		
24	301		
25	302		
26	305		
27	307		
28	306		
29	304		
30	303		
31	212 window sill	108 in. ²	
32	211		

*Comments/Special Instructions:



Chain of Custody
LATESTING Order Number (Lab Use Only):

#331810986

LATESTING
 520 MISSION STREET
 SOUTH PASADENA, CA 91030
 PHONE: (800) 303-0047
 FAX: (323) 254-9982

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
LW 33	Unit 210 Window sill	108 in. 2	5/17/18
34	213		
35	214		
36	209		
37	215		
38	208		
39	201		
40	207		
41	202		
42	204		
43	203		
44	205		
45	206		
46	312		
47	311		
48	310		

*Comments/Special Instructions:



508 4th St.

Chain of Custody
LATESTING Order Number (Lab Use Only):

#331810986

LATESTING
 520 MISSION STREET
 SOUTH PASADENA, CA 91030
 PHONE: (800) 303-0047
 FAX: (323) 254-9982

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
LW 49	Unit 313 window sill	108in.2	5/17/18
50	315		
51	314		
52	309		
53	308		
54	301		
55	302		
56	305		
57	307		
58	306		
59	304		
60	303		
BLK 1	BLANK		
BLK 2	↓		

*Comments/Special Instructions:

#331810986

Tom,Carolynn

From: Tom,Carolynn on behalf of LA Testing Lab - Huntington Beach
Sent: Monday, May 21, 2018 6:01 PM
To: Roberts, Kevin; kwilling@partneresi.com
Cc: LA Testing Lab - Huntington Beach
Subject: RE: 713 5th St. Los Angeles & 508 4th St. Los Angeles

Good Evening,

Per our conversation Karen. I'll change the TAT to 4days for Friday results. I'll also inform the analyst to release results as she completes each project.

Sorry for the inconvenience this may have caused,



Carolynn Tom | *Laboratory Analyst*

LA Testing | 5431 Industrial Drive | Huntington Beach, CA 92649
Phone: 714-828-4999 | Fax: 714-828-4944 | Toll Free: 800-755-1794
Lab Hours: Monday - Friday 8AM - 6PM, Saturday 9AM - 5PM, Sunday On-Call

Some of the resources LATesting, Inc. offers to our clients:

[LABConnect](#) | [Order Products](#) | [Client Corner](#) | [Training](#) | [Additional Resources](#) | [Sampling Videos](#)

"This email may contain privileged and confidential information and is solely for the use of the sender's intended recipient(s). **If you are not the intended recipient of this communication, you are hereby notified that any unauthorized review, use, dissemination, distribution, downloading, or copying of this communication is strictly prohibited.** If you received this email in error, please notify the sender by reply email and delete all copies and attachments. Thank you."

From: Roberts, Kevin [<mailto:KRoberts@partneresi.com>]
Sent: Monday, May 21, 2018 5:36 PM
To: Tom,Carolynn
Cc: LA Testing Lab - Huntington Beach
Subject: Re: 713 5th St. Los Angeles & 508 4th St. Los Angeles

Well it doesn't sound like we have a choice

Sent from my iPhone

On May 21, 2018, at 5:33 PM, Tom,Carolynn <ctom@EMSL.com> wrote:

Good Morning,

Unfortunately because of the high volume of samples in both projects the soonest TAT our lead dept could fulfill is by this Friday. If responding to this email on Tuesday the new TAT would be 3 days for Friday results.

Please advise.

<image001.jpg> **Carolynn Tom** | *Laboratory Analyst*

LA Testing | 5431 Industrial Drive | Huntington Beach, CA 92649
Phone: 714-828-4999 | Fax: 714-828-4944 | Toll Free: 800-755-1794
Lab Hours: Monday - Friday 8AM - 6PM, Saturday 9AM - 5PM, Sunday On-Call

Some of the resources LATesting, Inc. offers to our clients:

[LABConnect](#) | [Order Products](#) | [Client Corner](#) | [Training](#) | [Additional Resources](#) | [Sampling Videos](#)

#331810986

"This email may contain privileged and confidential information and is solely for the use of the sender's intended recipient(s). **If you are not the intended recipient of this communication, you are hereby notified that any unauthorized review, use, dissemination, distribution, downloading, or copying of this communication is strictly prohibited.** If you received this email in error, please notify the sender by reply email and delete all copies and attachments. Thank you."



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latesting.com

LA Testing Order: 331810986
CustomerID: 32PRTN78
CustomerPO:
ProjectID:

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
 Fax:
 Received: 05/21/18 6:00 PM
 Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 1 331810986-0001	5/17/2018 Site: Unit 212 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 2 331810986-0002	5/17/2018 Site: Unit 211 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 3 331810986-0003	5/17/2018 Site: Unit 210 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 4 331810986-0004	5/17/2018 Site: Unit 213 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 5 331810986-0005	5/17/2018 Site: Unit 214 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 6 331810986-0006	5/17/2018 Site: Unit 209 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 7 331810986-0007	5/17/2018 Site: Unit 215 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 8 331810986-0008	5/17/2018 Site: Unit 208 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 9 331810986-0009	5/17/2018 Site: Unit 201 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 10 331810986-0010	5/17/2018 Site: Unit 207 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²
LW 11 331810986-0011	5/17/2018 Site: Unit 202 floor	5/22/2018	144 in ²	10 µg/ft ²	<10 µg/ft ²

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Inital Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latesting.com

LA Testing Order:	331810986
CustomerID:	32PRTN78
CustomerPO:	
ProjectID:	

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
 Fax:
 Received: 05/21/18 6:00 PM
 Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 12 331810986-0012	5/17/2018	5/22/2018	144 in ² Site: Unit 204 floor	10 µg/ft ²	<10 µg/ft ²
LW 13 331810986-0013	5/17/2018	5/22/2018	144 in ² Site: Unit 203 floor	10 µg/ft ²	<10 µg/ft ²
LW 14 331810986-0014	5/17/2018	5/22/2018	144 in ² Site: Unit 205 floor	10 µg/ft ²	<10 µg/ft ²
LW 15 331810986-0015	5/17/2018	5/22/2018	144 in ² Site: Unit 206 floor	10 µg/ft ²	<10 µg/ft ²
LW 16 331810986-0016	5/17/2018	5/22/2018	144 in ² Site: Unit 312 floor	10 µg/ft ²	<10 µg/ft ²
LW 17 331810986-0017	5/17/2018	5/22/2018	144 in ² Site: Unit 311 floor	10 µg/ft ²	<10 µg/ft ²
LW 18 331810986-0018	5/17/2018	5/22/2018	144 in ² Site: Unit 310 floor	10 µg/ft ²	<10 µg/ft ²
LW 19 331810986-0019	5/17/2018	5/22/2018	144 in ² Site: Unit 313 floor	10 µg/ft ²	<10 µg/ft ²
LW 20 331810986-0020	5/17/2018	5/22/2018	144 in ² Site: Unit 315 floor	10 µg/ft ²	<10 µg/ft ²
LW 21 331810986-0021	5/17/2018	5/22/2018	144 in ² Site: Unit 314 floor	10 µg/ft ²	<10 µg/ft ²
LW 22 331810986-0022	5/17/2018	5/22/2018	144 in ² Site: Unit 309 floor	10 µg/ft ²	<10 µg/ft ²

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Inital Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latestesting.com

LA Testing Order:	331810986
CustomerID:	32PRTN78
CustomerPO:	
ProjectID:	

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
 Fax:
 Received: 05/21/18 6:00 PM
 Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 23 331810986-0023	5/17/2018	5/22/2018	144 in ² Site: Unit 308 floor	10 µg/ft ²	<10 µg/ft ²
LW 24 331810986-0024	5/17/2018	5/22/2018	144 in ² Site: Unit 301 floor	10 µg/ft ²	<10 µg/ft ²
LW 25 331810986-0025	5/17/2018	5/22/2018	144 in ² Site: Unit 302 floor	10 µg/ft ²	<10 µg/ft ²
LW 26 331810986-0026	5/17/2018	5/22/2018	144 in ² Site: Unit 305 floor	10 µg/ft ²	<10 µg/ft ²
LW 27 331810986-0027	5/17/2018	5/22/2018	144 in ² Site: Unit 307 floor	10 µg/ft ²	<10 µg/ft ²
LW 28 331810986-0028	5/17/2018	5/22/2018	144 in ² Site: Unit 306 floor	10 µg/ft ²	<10 µg/ft ²
LW 29 331810986-0029	5/17/2018	5/22/2018	144 in ² Site: Unit 304 floor	10 µg/ft ²	<10 µg/ft ²
LW 30 331810986-0030	5/17/2018	5/22/2018	144 in ² Site: Unit 303 floor	10 µg/ft ²	<10 µg/ft ²
LW 31 331810986-0031	5/17/2018	5/22/2018	108 in ² Site: Unit 212 window sill	13 µg/ft ²	<13 µg/ft ²
LW 32 331810986-0032	5/17/2018	5/22/2018	108 in ² Site: Unit 211 window sill	13 µg/ft ²	<13 µg/ft ²
LW 33 331810986-0033	5/17/2018	5/22/2018	108 in ² Site: Unit 210 window sill	13 µg/ft ²	<13 µg/ft ²

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Initial Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latestesting.com

LA Testing Order: 331810986
CustomerID: 32PRTN78
CustomerPO:
ProjectID:

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
Fax:
Received: 05/21/18 6:00 PM
Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 34 331810986-0034	5/17/2018	5/22/2018	108 in ² Site: Unit 213 window sill	13 µg/ft ²	<13 µg/ft ²
LW 35 331810986-0035	5/17/2018	5/22/2018	108 in ² Site: Unit 214 window sill	13 µg/ft ²	<13 µg/ft ²
LW 36 331810986-0036	5/17/2018	5/22/2018	108 in ² Site: Unit 209 window sill	13 µg/ft ²	<13 µg/ft ²
LW 37 331810986-0037	5/17/2018	5/22/2018	108 in ² Site: Unit 215 window sill	13 µg/ft ²	<13 µg/ft ²
LW 38 331810986-0038	5/17/2018	5/22/2018	108 in ² Site: Unit 208 window sill	13 µg/ft ²	<13 µg/ft ²
LW 39 331810986-0039	5/17/2018	5/22/2018	108 in ² Site: Unit 201 window sill	13 µg/ft ²	<13 µg/ft ²
LW 40 331810986-0040	5/17/2018	5/22/2018	108 in ² Site: Unit 207 window sill	13 µg/ft ²	<13 µg/ft ²
LW 41 331810986-0041	5/17/2018	5/22/2018	108 in ² Site: Unit 202 window sill	13 µg/ft ²	<13 µg/ft ²
LW 42 331810986-0042	5/17/2018	5/22/2018	108 in ² Site: Unit 204 window sill	13 µg/ft ²	<13 µg/ft ²
LW 43 331810986-0043	5/17/2018	5/22/2018	108 in ² Site: Unit 203 window sill	13 µg/ft ²	<13 µg/ft ²
LW 44 331810986-0044	5/17/2018	5/22/2018	108 in ² Site: Unit 205 window sill	13 µg/ft ²	<13 µg/ft ²

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Inital Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latestesting.com

LA Testing Order:	331810986
CustomerID:	32PRTN78
CustomerPO:	
ProjectID:	

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
 Fax:
 Received: 05/21/18 6:00 PM
 Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 45 331810986-0045	5/17/2018	5/22/2018	108 in ² Site: Unit 206 window sill	13 µg/ft ²	<13 µg/ft ²
LW 46 331810986-0046	5/17/2018	5/22/2018	108 in ² Site: Unit 312 window sill	13 µg/ft ²	<13 µg/ft ²
LW 47 331810986-0047	5/17/2018	5/22/2018	108 in ² Site: Unit 311 window sill	13 µg/ft ²	<13 µg/ft ²
LW 48 331810986-0048	5/17/2018	5/22/2018	108 in ² Site: Unit 310 window sill	13 µg/ft ²	<13 µg/ft ²
LW 49 331810986-0049	5/17/2018	5/22/2018	108 in ² Site: Unit 313 window sill	13 µg/ft ²	<13 µg/ft ²
LW 50 331810986-0050	5/17/2018	5/22/2018	108 in ² Site: Unit 315 window sill	13 µg/ft ²	<13 µg/ft ²
LW 51 331810986-0051	5/17/2018	5/22/2018	108 in ² Site: Unit 314 window sill	13 µg/ft ²	<13 µg/ft ²
LW 52 331810986-0052	5/17/2018	5/22/2018	108 in ² Site: Unit 309 window sill	13 µg/ft ²	<13 µg/ft ²
LW 53 331810986-0053	5/17/2018	5/22/2018	108 in ² Site: Unit 308 window sill	13 µg/ft ²	<13 µg/ft ²
LW 54 331810986-0054	5/17/2018	5/22/2018	108 in ² Site: Unit 301 window sill	13 µg/ft ²	<13 µg/ft ²
LW 55 331810986-0055	5/17/2018	5/22/2018	108 in ² Site: Unit 302 window sill	13 µg/ft ²	<13 µg/ft ²

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Inital Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location



LA Testing

5431 Industrial Drive, Huntington Beach, CA 92649

Phone/Fax: (714) 828-4999 / (714) 828-4944

<http://www.LATesting.com>

gardengrovelab@latestesting.com

LA Testing Order:	331810986
CustomerID:	32PRTN78
CustomerPO:	
ProjectID:	

Attn: **Kevin Roberts**
Partner Engineering and Science, Inc.
2154 Torrance Blvd
Suite 200
Torrance, CA 90501

Phone: (310) 615-4500
 Fax:
 Received: 05/21/18 6:00 PM
 Collected: 5/17/2018

Project: 508 4th St Los Angeles

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Collected	Analyzed	Area Sampled	RDL	Lead Concentration
LW 56 331810986-0056	5/17/2018	5/22/2018	108 in ² Site: Unit 305 window sill	13 µg/ft ²	<13 µg/ft ²
LW 57 331810986-0057	5/17/2018	5/22/2018	108 in ² Site: Unit 307 window sill	13 µg/ft ²	<13 µg/ft ²
LW 58 331810986-0058	5/17/2018	5/22/2018	108 in ² Site: Unit 306 window sill	13 µg/ft ²	<13 µg/ft ²
LW 59 331810986-0059	5/17/2018	5/22/2018	108 in ² Site: Unit 304 window sill	13 µg/ft ²	<13 µg/ft ²
LW 60 331810986-0060	5/17/2018	5/22/2018	108 in ² Site: Unit 303 window sill	13 µg/ft ²	<13 µg/ft ²
Blk 1 331810986-0061	5/17/2018	5/22/2018	n/a Site: Blank	10 µg/wipe	<10 µg/wipe
Blk 2 331810986-0062	5/17/2018	5/22/2018	n/a Site: Blank	10 µg/wipe	<10 µg/wipe

Michael Chapman, Laboratory Manager
or other approved signatory

Sample received in acceptable condition unless otherwise noted. Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

Samples analyzed by LA Testing Huntington Beach, CA AIHA-LAP, LLC--ELLAP Accredited #101650, CA ELAP 1406

Report Amended: 05/24/2018 15:53:02 Replaces the Initial Report 05/23/2018 17:06:42. Reason Code: Client-Change to Location

508 4th Street Los Angeles, California

Shot	Date	Room	Component	Substrate	Side	Condition	Results	PbC
1	5/17/2018	Calibration					Positive	1.2
2	5/17/2018	Calibration					Positive	1.1
3	5/17/2018	Calibration					Positive	1.1
4	5/17/2018	212	Wall	Drywall	A	Intact	Negative	0.02
5	5/17/2018	212	Wall	Drywall	B	Intact	Negative	0.06
6	5/17/2018	212	Wall	Drywall	C	Intact	Negative	0.17
7	5/17/2018	212	Wall	Drywall	D	Intact	Negative	0.01
8	5/17/2018	212	Ceiling	Drywall		Intact	Negative	0.05
9	5/17/2018	212	Door Frame	Metal	A	Intact	Negative	0.06
10	5/17/2018	211	Wall	Drywall	A	Intact	Negative	0.02
11	5/17/2018	211	Wall	Drywall	B	Intact	Negative	0.15
12	5/17/2018	211	Wall	Drywall	C	Intact	Negative	0.04
13	5/17/2018	211	Wall	Drywall	D	Intact	Negative	0
14	5/17/2018	211	Ceiling	Drywall		Intact	Negative	0.02
15	5/17/2018	211	Door Frame	Metal	A	Intact	Negative	0
16	5/17/2018	210	Wall	Drywall	A	Intact	Negative	0.3
17	5/17/2018	210	Wall	Drywall	B	Intact	Negative	0
18	5/17/2018	210	Wall	Drywall	C	Intact	Negative	0.04
19	5/17/2018	210	Wall	Drywall	D	Intact	Negative	0
20	5/17/2018	210	Ceiling	Drywall		Intact	Negative	0
21	5/17/2018	210	Door Frame	Metal	A	Intact	Negative	0.14
22	5/17/2018	213	Wall	Drywall	A	Intact	Negative	0
23	5/17/2018	213	Wall	Drywall	B	Intact	Negative	0.06
24	5/17/2018	213	Wall	Drywall	C	Intact	Negative	0.02
25	5/17/2018	213	Wall	Drywall	D	Intact	Negative	0.2
26	5/17/2018	213	Ceiling	Drywall		Intact	Negative	0
27	5/17/2018	213	Door Frame	Metal	A	Intact	Negative	0.22
28	5/17/2018	214	Wall	Drywall	A	Intact	Negative	0
29	5/17/2018	214	Wall	Drywall	B	Intact	Negative	0
30	5/17/2018	214	Wall	Drywall	C	Intact	Negative	0.03
31	5/17/2018	214	Wall	Drywall	D	Intact	Negative	0.09
32	5/17/2018	214	Ceiling	Drywall		Intact	Negative	0.12
33	5/17/2018	214	Door Frame	Metal	A	Intact	Negative	0

508 4th Street Los Angeles, California

34	5/17/2018	209	Wall	Drywall	A	Intact	Negative	0.01
35	5/17/2018	209	Wall	Drywall	B	Intact	Negative	0
36	5/17/2018	209	Wall	Drywall	C	Intact	Negative	0.01
37	5/17/2018	209	Wall	Drywall	D	Intact	Negative	0.13
38	5/17/2018	209	Ceiling	Drywall		Intact	Negative	0
39	5/17/2018	209	Door Frame	Metal	A	Intact	Negative	0.16
40	5/17/2018	215	Wall	Drywall	A	Intact	Negative	0
41	5/17/2018	215	Wall	Drywall	B	Intact	Negative	0.01
42	5/17/2018	215	Wall	Drywall	C	Intact	Negative	0
43	5/17/2018	215	Wall	Drywall	D	Intact	Negative	0
44	5/17/2018	215	Ceiling	Drywall		Intact	Negative	0.05
45	5/17/2018	215	Door Frame	Metal	A	Intact	Negative	0.01
46	5/17/2018	208	Wall	Drywall	A	Intact	Negative	0
47	5/17/2018	208	Wall	Drywall	B	Intact	Negative	0.28
48	5/17/2018	208	Wall	Drywall	C	Intact	Negative	0.09
49	5/17/2018	208	Wall	Drywall	D	Intact	Negative	0.3
50	5/17/2018	208	Ceiling	Drywall		Intact	Negative	0.01
51	5/17/2018	208	Door Frame	Metal	A	Intact	Negative	0
52	5/17/2018	201	Wall	Drywall	A	Intact	Negative	0.1
53	5/17/2018	201	Wall	Drywall	B	Intact	Negative	0
54	5/17/2018	201	Wall	Drywall	C	Intact	Negative	0
55	5/17/2018	201	Wall	Drywall	D	Intact	Negative	0
56	5/17/2018	201	Ceiling	Drywall		Intact	Negative	0.06
57	5/17/2018	201	Door Frame	Metal	A	Intact	Negative	0.01
58	5/17/2018	207	Wall	Drywall	A	Intact	Negative	0.12
59	5/17/2018	207	Wall	Drywall	B	Intact	Negative	0
60	5/17/2018	207	Wall	Drywall	C	Intact	Negative	0.02
61	5/17/2018	207	Wall	Drywall	D	Intact	Negative	0.3
62	5/17/2018	207	Ceiling	Drywall		Intact	Negative	0.03
63	5/17/2018	207	Door Frame	Metal	A	Intact	Negative	0.01
64	5/17/2018	202	Wall	Drywall	A	Intact	Negative	0.02
65	5/17/2018	202	Wall	Drywall	B	Intact	Negative	0.05
66	5/17/2018	202	Wall	Drywall	C	Intact	Negative	0.11
67	5/17/2018	202	Wall	Drywall	D	Intact	Negative	0.01

508 4th Street Los Angeles, California

68	5/17/2018	202	Ceiling	Drywall		Intact	Negative	0.04
69	5/17/2018	202	Door Frame	Metal	A	Intact	Negative	0.03
70	5/17/2018	204	Wall	Drywall	A	Intact	Negative	0
71	5/17/2018	204	Wall	Drywall	B	Intact	Negative	0
72	5/17/2018	204	Wall	Drywall	C	Intact	Negative	0.03
73	5/17/2018	204	Wall	Drywall	D	Intact	Negative	0
74	5/17/2018	204	Ceiling	Drywall		Intact	Negative	0.5
75	5/17/2018	204	Door Frame	Metal	A	Intact	Negative	0.01
76	5/17/2018	203	Wall	Drywall	A	Intact	Negative	0.05
77	5/17/2018	203	Wall	Drywall	B	Intact	Negative	0
78	5/17/2018	203	Wall	Drywall	C	Intact	Negative	0.01
79	5/17/2018	203	Wall	Drywall	D	Intact	Negative	0
80	5/17/2018	203	Ceiling	Drywall		Intact	Negative	0.01
81	5/17/2018	203	Door Frame	Metal	A	Intact	Negative	0
82	5/17/2018	205	Wall	Drywall	A	Intact	Negative	0.02
83	5/17/2018	205	Wall	Drywall	B	Intact	Negative	0
84	5/17/2018	205	Wall	Drywall	C	Intact	Negative	0
85	5/17/2018	205	Wall	Drywall	D	Intact	Negative	0.06
86	5/17/2018	205	Ceiling	Drywall		Intact	Negative	0.15
87	5/17/2018	205	Door Frame	Metal	A	Intact	Negative	0.14
88	5/17/2018	206	Wall	Drywall	A	Intact	Negative	0.05
89	5/17/2018	206	Wall	Drywall	B	Intact	Negative	0.03
90	5/17/2018	206	Wall	Drywall	C	Intact	Negative	0
91	5/17/2018	206	Wall	Drywall	D	Intact	Negative	0
92	5/17/2018	206	Ceiling	Drywall		Intact	Negative	0.28
93	5/17/2018	206	Door Frame	Metal	A	Intact	Negative	0
94	5/17/2018	312	Wall	Drywall	A	Intact	Negative	0.01
95	5/17/2018	312	Wall	Drywall	B	Intact	Negative	0.02
96	5/17/2018	312	Wall	Drywall	C	Intact	Negative	0
97	5/17/2018	312	Wall	Drywall	D	Intact	Negative	0.01
98	5/17/2018	312	Ceiling	Drywall		Intact	Negative	0
99	5/17/2018	312	Door Frame	Metal	A	Intact	Negative	0.03
100	5/17/2018	311	Wall	Drywall	A	Intact	Negative	0.02
101	5/17/2018	311	Wall	Drywall	B	Intact	Negative	0.01

508 4th Street Los Angeles, California

102	5/17/2018	311	Wall	Drywall	C	Intact	Negative	0
103	5/17/2018	311	Wall	Drywall	D	Intact	Negative	0
104	5/17/2018	311	Ceiling	Drywall		Intact	Negative	0.07
105	5/17/2018	311	Door Frame	Metal	A	Intact	Negative	0
106	5/17/2018	310	Wall	Drywall	A	Intact	Negative	0.04
107	5/17/2018	310	Wall	Drywall	B	Intact	Negative	0
108	5/17/2018	310	Wall	Drywall	C	Intact	Negative	0.01
109	5/17/2018	310	Wall	Drywall	D	Intact	Negative	0.02
110	5/17/2018	310	Ceiling	Drywall		Intact	Negative	0.02
111	5/17/2018	310	Door Frame	Metal	A	Intact	Negative	0
112	5/17/2018	313	Wall	Drywall	A	Intact	Negative	0
113	5/17/2018	313	Wall	Drywall	B	Intact	Negative	0.27
114	5/17/2018	313	Wall	Drywall	C	Intact	Negative	0.03
115	5/17/2018	313	Wall	Drywall	D	Intact	Negative	0.3
116	5/17/2018	313	Ceiling	Drywall		Intact	Negative	0.03
117	5/17/2018	313	Door Frame	Metal	A	Intact	Negative	0
118	5/17/2018	314	Wall	Drywall	A	Intact	Negative	0.02
119	5/17/2018	314	Wall	Drywall	B	Intact	Negative	0.07
120	5/17/2018	314	Wall	Drywall	C	Intact	Negative	0
121	5/17/2018	314	Wall	Drywall	D	Intact	Negative	0.3
122	5/17/2018	314	Ceiling	Drywall		Intact	Negative	0.3
123	5/17/2018	314	Door Frame	Metal	A	Intact	Negative	0
124	5/17/2018	309	Wall	Drywall	A	Intact	Negative	0.02
125	5/17/2018	309	Wall	Drywall	B	Intact	Negative	0.01
126	5/17/2018	309	Wall	Drywall	C	Intact	Negative	0
127	5/17/2018	309	Wall	Drywall	D	Intact	Negative	0
128	5/17/2018	309	Ceiling	Drywall		Intact	Negative	0.01
129	5/17/2018	309	Door Frame	Metal	A	Intact	Negative	0.3
130	5/17/2018	308	Wall	Drywall	A	Intact	Negative	0.06
131	5/17/2018	308	Wall	Drywall	B	Intact	Negative	0
132	5/17/2018	308	Wall	Drywall	C	Intact	Negative	0
133	5/17/2018	308	Wall	Drywall	D	Intact	Negative	0.01
134	5/17/2018	308	Ceiling	Drywall		Intact	Negative	0.02
135	5/17/2018	308	Door Frame	Metal	A	Intact	Negative	0.12

508 4th Street Los Angeles, California

136	5/17/2018	301	Wall	Drywall	A	Intact	Negative	0.08
137	5/17/2018	301	Wall	Drywall	B	Intact	Negative	0
138	5/17/2018	301	Wall	Drywall	C	Intact	Negative	0
139	5/17/2018	301	Wall	Drywall	D	Intact	Negative	0.1
140	5/17/2018	301	Ceiling	Drywall		Intact	Negative	0.02
141	5/17/2018	301	Door Frame	Metal	A	Intact	Negative	0.06
142	5/17/2018	302	Wall	Drywall	A	Intact	Negative	0.05
143	5/17/2018	302	Wall	Drywall	B	Intact	Negative	0
144	5/17/2018	302	Wall	Drywall	C	Intact	Negative	0.4
145	5/17/2018	302	Wall	Drywall	D	Intact	Negative	0.21
146	5/17/2018	302	Ceiling	Drywall		Intact	Negative	0
147	5/17/2018	302	Door Frame	Metal	A	Intact	Negative	0
148	5/17/2018	305	Wall	Drywall	A	Intact	Negative	0.01
149	5/17/2018	305	Wall	Drywall	B	Intact	Negative	0.03
150	5/17/2018	305	Wall	Drywall	C	Intact	Negative	0
151	5/17/2018	305	Wall	Drywall	D	Intact	Negative	0.02
152	5/17/2018	305	Ceiling	Drywall		Intact	Negative	0
153	5/17/2018	305	Door Frame	Metal	A	Intact	Negative	0.11
154	5/17/2018	307	Wall	Drywall	A	Intact	Negative	0.05
155	5/17/2018	307	Wall	Drywall	B	Intact	Negative	0.02
156	5/17/2018	307	Wall	Drywall	C	Intact	Negative	0
157	5/17/2018	307	Wall	Drywall	D	Intact	Negative	0.13
158	5/17/2018	307	Ceiling	Drywall		Intact	Negative	0.04
159	5/17/2018	307	Door Frame	Metal	A	Intact	Negative	0
160	5/17/2018	306	Wall	Drywall	A	Intact	Negative	0.01
161	5/17/2018	306	Wall	Drywall	B	Intact	Negative	0
162	5/17/2018	306	Wall	Drywall	C	Intact	Negative	0.11
163	5/17/2018	306	Wall	Drywall	D	Intact	Negative	0.02
164	5/17/2018	306	Ceiling	Drywall		Intact	Negative	0.08
165	5/17/2018	306	Door Frame	Metal	A	Intact	Negative	0
166	5/17/2018	304	Wall	Drywall	A	Intact	Negative	0
167	5/17/2018	304	Wall	Drywall	B	Intact	Negative	0.2
168	5/17/2018	304	Wall	Drywall	C	Intact	Negative	0.04
169	5/17/2018	304	Wall	Drywall	D	Intact	Negative	0

508 4th Street Los Angeles, California

170	5/17/2018	304	Ceiling	Drywall		Intact	Negative	0.08
171	5/17/2018	304	Door Frame	Metal	A	Intact	Negative	0.06
172	5/17/2018	303	Wall	Drywall	A	Intact	Negative	0.02
173	5/17/2018	303	Wall	Drywall	B	Intact	Negative	0.03
174	5/17/2018	303	Wall	Drywall	C	Intact	Negative	0
175	5/17/2018	303	Wall	Drywall	D	Intact	Negative	0.18
176	5/17/2018	303	Ceiling	Drywall		Intact	Negative	0.01
177	5/17/2018	303	Door Frame	Metal	A	Intact	Negative	0.02
178	5/17/2018	315	Wall	Drywall	A	Intact	Negative	0.22
179	5/17/2018	315	Wall	Drywall	B	Intact	Negative	0.16
180	5/17/2018	315	Wall	Drywall	C	Intact	Negative	0.16
181	5/17/2018	315	Wall	Drywall	D	Intact	Negative	0.05
182	5/17/2018	315	Ceiling	Drywall		Intact	Negative	0
183	5/17/2018	315	Door Frame	Metal	A	Intact	Negative	0.01
184	5/17/2018	Community Room	Wall	Drywall	A	Intact	Negative	0
185	5/17/2018	Community Room	Wall	Drywall	B	Intact	Negative	0.2
186	5/17/2018	Community Room	Wall	Drywall	C	Intact	Negative	0
187	5/17/2018	Community Room	Wall	Drywall	D	Intact	Negative	0.01
188	5/17/2018	Community Room	Ceiling	Drywall		Intact	Negative	0
189	5/17/2018	Community Room	Door Frame	Metal	B	Intact	Negative	0.03
190	5/17/2018	2nd Floor Hallway	Wall	Drywall	A	Intact	Negative	0
191	5/17/2018	2nd Floor Hallway	Wall	Drywall	B	Intact	Negative	0.13
192	5/17/2018	2nd Floor Hallway	Wall	Drywall	C	Intact	Negative	0
193	5/17/2018	2nd Floor Hallway	Wall	Drywall	D	Intact	Negative	0.1
194	5/17/2018	2nd Floor Hallway	Ceiling	Drywall		Intact	Negative	0.3
195	5/17/2018	2nd Floor Hallway	Molding	Wood	C	Intact	Negative	0.4
196	5/17/2018	2nd Floor Hallway	Door Frame	Metal	C	Intact	Negative	0.08
197	5/17/2018	2nd Floor Hallway	Window Frame	Metal	B	Intact	Negative	0.1
198	5/17/2018	Laundry Room	Wall	Drywall	A	Intact	Negative	0.13
199	5/17/2018	Laundry Room	Wall	Drywall	B	Intact	Negative	0
200	5/17/2018	Laundry Room	Wall	Drywall	C	Intact	Negative	0
201	5/17/2018	Laundry Room	Wall	Drywall	D	Intact	Negative	0.07
202	5/17/2018	Laundry Room	Ceiling	Drywall		Intact	Negative	0.02
203	5/17/2018	Laundry Room	Door Frame	Metal	A	Intact	Negative	0.07

508 4th Street Los Angeles, California

204	5/17/2018	3rd Floor Hallway	Wall	Drywall	A	Intact	Negative	0
205	5/17/2018	3rd Floor Hallway	Wall	Drywall	B	Intact	Negative	0
206	5/17/2018	3rd Floor Hallway	Wall	Drywall	C	Intact	Negative	0.02
207	5/17/2018	3rd Floor Hallway	Wall	Drywall	D	Intact	Negative	0
208	5/17/2018	3rd Floor Hallway	Door Frame	Metal	A	Intact	Negative	0.08
209	5/17/2018	3rd Floor Hallway	Molding	Wood	A	Intact	Negative	0.07
210	5/17/2018	3rd Floor Hallway	Window Frame	Metal	D	Intact	Negative	0.03
211	5/17/2018	North Stairwell	Wall	Drywall	A	Intact	Negative	0.06
212	5/17/2018	North Stairwell	Wall	Drywall	B	Intact	Negative	0.06
213	5/17/2018	North Stairwell	Wall	Drywall	C	Intact	Negative	0.03
214	5/17/2018	North Stairwell	Wall	Drywall	D	Intact	Negative	0
215	5/17/2018	North Stairwell	Door Frame	Metal	A	Intact	Negative	0.01
216	5/17/2018	North Stairwell	Ceiling	Drywall		Intact	Negative	0
217	5/17/2018	North Stairwell	Railing	Wood	C	Intact	Negative	0.05
218	5/17/2018	2nd Floor RR 1	Wall	Drywall	A	Intact	Negative	0.07
219	5/17/2018	2nd Floor RR 1	Wall	Drywall	B	Intact	Negative	0.3
220	5/17/2018	2nd Floor RR 1	Wall	Drywall	C	Intact	Negative	0.5
221	5/17/2018	2nd Floor RR 1	Wall	Drywall	D	Intact	Negative	0
222	5/17/2018	2nd Floor RR 1	Ceiling	Drywall		Intact	Negative	0
223	5/17/2018	2nd Floor RR 1	Door Frame	Metal	B	Intact	Negative	0.07
224	5/17/2018	2nd Floor RR 2	Wall	Drywall	A	Intact	Negative	0.07
225	5/17/2018	2nd Floor RR 2	Wall	Drywall	B	Intact	Negative	0.29
226	5/17/2018	2nd Floor RR 2	Wall	Drywall	C	Intact	Negative	0.08
227	5/17/2018	2nd Floor RR 2	Wall	Drywall	D	Intact	Negative	0.1
228	5/17/2018	2nd Floor RR 2	Ceiling	Drywall		Intact	Negative	0.06
229	5/17/2018	2nd Floor RR 2	Door Frame	Metal	B	Intact	Negative	0.01
230	5/17/2018	3rd Floor RR 1	Wall	Drywall	A	Intact	Negative	0.03
231	5/17/2018	3rd Floor RR 1	Wall	Drywall	B	Intact	Negative	0.01
232	5/17/2018	3rd Floor RR 1	Wall	Drywall	C	Intact	Negative	0.08
233	5/17/2018	3rd Floor RR 1	Wall	Drywall	D	Intact	Negative	0.07
234	5/17/2018	3rd Floor RR 1	Ceiling	Drywall		Intact	Negative	0.11
235	5/17/2018	3rd Floor RR 1	Door Frame	Metal	B	Intact	Negative	0.11
236	5/17/2018	3rd Floor RR 2	Wall	Drywall	A	Intact	Negative	0.02
237	5/17/2018	3rd Floor RR 2	Wall	Drywall	B	Intact	Negative	0.01

508 4th Street Los Angeles, California

238	5/17/2018	3rd Floor RR 2	Wall	Drywall	C	Intact	Negative	0.01
239	5/17/2018	3rd Floor RR 2	Wall	Drywall	D	Intact	Negative	0.2
240	5/17/2018	3rd Floor RR 2	Ceiling	Drywall		Intact	Negative	0.02
241	5/17/2018	3rd Floor RR 2	Door Frame	Metal	B	Intact	Negative	0
242	5/17/2018	2nd Floor Office	Wall	Drywall	A	Intact	Negative	0.4
243	5/17/2018	2nd Floor Office	Wall	Drywall	B	Intact	Negative	0.15
244	5/17/2018	2nd Floor Office	Wall	Drywall	C	Intact	Negative	0.02
245	5/17/2018	2nd Floor Office	Wall	Drywall	D	Intact	Negative	0
246	5/17/2018	2nd Floor Office	Door Frame	Metal	A	Intact	Negative	0.07
247	5/17/2018	2nd Floor Office	Window Frame	Metal	C	Intact	Negative	0.01
248	5/17/2018	2nd Floor Office	Ceiling	Drywall		Intact	Negative	0.05
249	5/17/2018	Exterior	Wall	Brick	A	Intact	Negative	0.01
250	5/17/2018	Exterior	Wall	Brick	C	Intact	Negative	0.09
251	5/17/2018	Exterior	Door Frame	Metal	A	Intact	Negative	0.01
252	5/17/2018	Exterior	Window Frame	Metal	A	Intact	Negative	0
253	5/17/2018	Exterior	Drain	Metal	A	Intact	Negative	0.4
254	5/17/2018	Exterior	Pipe	Metal	A	Intact	Negative	0.02
255	5/17/2018	Exterior	Roller Door	Metal	A	Intact	Negative	0.23
256	5/17/2018	Calibration					Positive	1.1
257	5/17/2018	Calibration					Positive	1.1
258	5/17/2018	Calibration					Positive	1
Total Readings		258	Action Level -			0.7		
Positive Reading		0	Units			mg/cm^2		

APPENDIX B: SITE LOCATION DIAGRAM




APPENDIX C: CERTIFICATIONS

Alfredo Torres

California DOSH **Certified Asbestos Consultant (CAC) #10-4593**

California DPH **Certified Lead Inspector Assessor (CLIA) #17424**



APPENDIX D: SITE PHOTOGRAPHS



1. View of the exterior facade.



2. View of the interior drywall walls & ceilings.



3. View of the fiberglass pipe insulation.



4. View of the grey and green 12x12 vinyl floor tile.



5. View of the beige sheet vinyl flooring.



6. View of the white and grey 12x12 vinyl floor tile.

APPENDIX E: CALIFORNIA DPH FORM 8552

LEAD HAZARD EVALUATION REPORT

Section 1 – Date of Lead Hazard Evaluation 5-17-2018

Section 2 – Type of Lead Hazard Evaluation (Check one box only)

Lead Inspection Risk assessment Clearance Inspection Other (specify) _____

Section 3 – Structure Where Lead Hazard Evaluation Was Conducted

Address [number, street, apartment (if applicable)] 508 4th Street		City Los Angeles	County Los Angeles	Zip Code 90013
Construction date (year) of structure 	Type of structure <input checked="" type="checkbox"/> Multi-unit building <input type="checkbox"/> School or daycare <input type="checkbox"/> Single family dwelling <input type="checkbox"/> Other _____		Children living in structure? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Don't Know	

Section 4 – Owner of Structure (if business/agency, list contact person)

Name _____		Telephone number _____		
Address [number, street, apartment (if applicable)] _____		City _____	State _____	Zip Code _____

Section 5 – Results of Lead Hazard Evaluation (check all that apply)

No lead-based paint detected Intact lead-based paint detected Deteriorated lead-based paint detected
 No lead hazards detected Lead-contaminated dust found Lead-contaminated soil found Other _____

Section 6 – Individual Conducting Lead Hazard Evaluation

Name Alfredo Torres		Telephone number 310-200-4006		
Address [number, street, apartment (if applicable)] 1027 Oakdale Street		City Corona	State Ca	Zip Code 92880
CDPH certification number 17424	Signature 			Date 5-24-2018

Name and CDPH certification number of any other individuals conducting sampling or testing (if applicable)

Section 7 – Attachments

- A. A foundation diagram or sketch of the structure indicating the specific locations of each lead hazard or presence of lead-based paint;
- B. Each testing method, device, and sampling procedure used;
- C. All data collected, including quality control data, laboratory results, including laboratory name, address, and phone number.

First copy and attachments retained by inspector
 Second copy and attachments retained by owner

Third copy only (no attachments) mailed or faxed to:
 California Department of Public Health
 Childhood Lead Poisoning Prevention Branch Reports
 850 Marina Bay Parkway, Building P, Third Floor
 Richmond, CA 94804-6403
 Fax: (510) 620-5656

Alfredo Torres

California DOSH **Certified Asbestos Consultant (CAC) #10-4593**

California DPH **Certified Lead Inspector Assessor (CLIA) #17424**


State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Alfredo A Torres
Name

Certification No. **10-4593**

Expires on **01/20/20**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



State of California Department of Public Health

Lead-Related Construction Certificate	Certificate Type	Expiration Date
	Inspector/Assessor ★	08/01/2019

17437

Alfredo A. Torres ID #: **17424**

