Sunshine Canyon Landfill Independent Monitor Quarterly Site Monitoring Status Report April 1, 2014 – June 30, 2014

Prepared For:

City of Los Angeles Department of City Planning

And

County of Los Angeles Department of Regional Planning




Prepared By:



16431 Scientific Way Irvine, California 92618

Prepared On:

December 5, 2014





CERTIFICATION STATEMENT

December 5, 2014


The attached Quarterly Site Monitoring Status Report for the Sunshine Canyon Landfill dated December 5, 2014 is the Second Quarterly Report for 2014, issued by UltraSystems. This report covers the monitoring period from April 1, 2014 through June 30, 2014 and is prepared for the City of Los Angeles Department of City Planning and the County of Los Angeles Department of Regional Planning.

I, James T. Aidukas, Project Manager for the Mitigation Monitoring Services of the Sunshine Canyon Landfill, certify that the statements in the Quarterly Report and the referenced monthly reports reflect the site conditions observed and compliance status noted by me and other qualified experts during the stated site visits.

Signed,

James T. Aidukas

Project Manager



Contents

Quarterly Status Report	1
Site Visits During the Quarter	2
Definition of Terms	2
Status Summary	2
Compliant	2
Non-Compliant	3
Further Review Needed	3
Summary of Requested Documents	17
Conclusions	17

Sunshine Canyon Landfill Mitigation Monitoring – 2014 Second Quarter Summary/ City (see Excel spreadsheets)

Sunshine Canyon Landfill Mitigation Monitoring – 2014 Second Quarter Summary/ County (see Excel spreadsheets)

Appendices

Appendix I – Excel Summary Further Review Needed Comments Reference I-e through I-i

Appendix II – Photo Location Map and Relevant Site Photos

Appendix III - Quarterly Site Visits

Attendees by Date and Monitoring Site Reports

Appendix IV - Meeting Logs

Appendix V – Landfill GPS Data

GPS Data Logs

GPS Maps

GPS Elevation Data Tables

Quarterly Status Report

This Quarterly Status Report is a compilation of the period's monthly Site Monitoring. After each site visit, the UltraSystems monitors who went to the Sunshine Canyon Landfill site each wrote a Mitigation Monitoring Site Report, updated the Mitigation Monitoring Summary Excel Tables for the City and County of Los Angeles noting any conditions and/or mitigation measures that need further review, and documented these areas in an appendix for that site visit date. Any issues that required immediate attention were reported to Republic staff and the appropriate staff at the City of Los Angeles Planning Department, the County of Los Angeles Department of Regional Planning, the County of Los Angeles Department of Public Works and the Sunshine Canyon Landfill Local Enforcement Agency (SCL-LEA).

The Sunshine Canyon Landfill City and County Summary Tables record each site visit and frequency of monitoring of specific conditions and/or mitigation measures, by date. When a condition and/or mitigation measure is monitored, a check mark is made under the date that it was monitored, and the status of being compliant with the conditions and/or mitigation measures' requirements observed during monitoring is recorded. Tasks with a yearly or non-ongoing monitoring frequency are denoted by a forward slash (/) in subsequent date columns. In the status column, the letter "C" is put next to the task if it is Compliant; the letters "NC" are noted if the task status is Non-Compliant; and the letters "FRN" are used if Further Review is Needed for meeting the requirements of the conditions and/or mitigation measures.

Under the Further Review Needed/ Comment column, observed conditions that have been noted as "FRN" in the status column refer to appendices which detail what was observed during the site monitoring. When the conditions and/or mitigation measures that were previously noted as "FRN" are fully compliant, an "R" is placed in the Resolved column and a "C" replaces the "FRN" in the status column. Also noted in the FRN-Comment column are those action items that would improve monitoring efficiency by having reports and documents readily available. These are summarized in the Compliant with Comments section of the monthly monitoring records and the Summary of Requested Documents of the Quarterly Reports. The City and County Excel Spreadsheets record the site conditions observed during monitoring.

This Quarterly Report provides the City of Los Angeles Department of Planning and the County of Los Angeles Department of Regional Planning with a concise status of the Mitigation Measure Monitoring for the period of April 1, 2014 to June 30, 2014. It includes:

- 1. The City and County Mitigation Monitoring Summary Excel Tables for June 2014. These tables record the areas of monitoring completed during the second quarter of 2014 and the status of being compliant;
- 2. A Status Summary of Non-Compliant, Further Review Needed and Compliant with the requirements of the conditions and/or mitigation measures;
- 3. Photo Location Map and Relevant Site Photos showing site conditions of key areas of the landfill during the quarter;
- 4. Site visit attendees by date of site visit and the mitigation monitoring report for each monitor;

- 5. Meeting logs documenting any meetings with Republic Services staff and/or public agencies and the topics discussed; and
- 6. Any site monitoring documenting site changes.

Site Visits During the Quarter

Five site visits were performed by UltraSystems during the April through June 2014 quarter in order to observe operational site activities and determine compliant status with conditions and/or mitigation measures. They were performed on April 2, 2014; April 16, 2014; May 7, 2014; June 11, 2014; and June 24, 2014. The previously discussed conditions and/or mitigation measures were tracked by each specialist who visited, and observations were documented. Site conditions were noted to be: Compliant, Non-Compliant, or Further Review Needed. If a Condition was found to be Non-Compliant or observed as having Further Review Needed, a reference was made to an appendix which details what was observed by the monitor.

Definition of Terms

<u>Compliant</u> is defined as complying with the City and County conditions and/or mitigation measures.

<u>Non-compliant</u> is defined as not complying with the City and County conditions and/or mitigation measures.

<u>Further Review Needed</u> is defined as implementing plans (agency-approved, if required) to fully comply with a condition and/or mitigation measure. Some plans, especially vegetation, require an extended time frame, and immediate compliance is not possible.

<u>Further Review Needed/ Comments</u> is defined as comments documenting site conditions observed during monitoring visits that are not fully compliant but action is being taken in order to obtain full compliance with conditions and/or mitigation measures. Recommendations from the monitor, as appropriate, and status from Republic Services (Republic) may also be given. Comments are also made for compliant conditions where the comment notes action that may be taken to provide documents to improve monitoring efficiency and/or document issues observed during the monitoring.

<u>Resolved</u> is defined as action taken or activities completed to fully comply with conditions and/or mitigation measures.

Status Summary

This section summarizes the conditions and/or mitigation measures that were monitored during the quarterly reporting period and their respective statuses. The Sunshine Canyon Mitigation Monitoring Spreadsheets for the City and County show the conditions and/or mitigation measures monitored during the quarter. Also included in this report are relevant photos in Appendix II.

Compliant

The majority of the conditions and/or mitigation measures monitored were observed to be compliant. There are City and County conditions which are compliant, but are noted as

having corresponding comments that refer to the appendices. The Compliant with Comments section of the monthly monitoring records provide a summary of these comments where monitoring efficiency would be improved by having reports and documents readily available and/or document issues observed during monitoring. These are summarized in the Summary of Requested Documents in the Quarterly Report.

Non-Compliant

During UltraSystems' five site visits, no Non-Compliant conditions and/or mitigation measures were noted. Also, it must be understood that any monitoring related to landfill gas and odors are not part of the UltraSystems Monitoring Program at this time. These issues are currently being handled by a multi-agency team, which is led by the South Coast Air Quality Management District (SCAQMD).

Further Review Needed

The following conditions and/or mitigation measures were found not to be fully compliant, but were being worked on in order to obtain full compliance. This section summarizes the progress being made toward being fully compliant. When a condition and/or mitigation measure progresses from FRN to fully compliant, it is noted as Resolved in this section.

Q-B.2.c (City)

Ancillary Uses and Facilities. The subject property may only be used for the following uses and facilities. These ancillary uses and facilities described in the July 1997 Draft Subsequent EIR, pages 2-38 through 2-43, and may be located on the applicant's property generally in conformance with the diagram attached as Exhibit e-4, and during the life of the landfill, may be moved or relocated following commencement of landfilling operations as necessary to accommodate development of the ultimate landfill footprint.

<u>Current Status/Comments</u> – In April, the County Department of Public Works was given for review the drainage design for the permanent westside drainage system that will be installed below the Old City South Landfill.

Q-C.5.c (City)

The operator Graffiti removal and deterrence on building and structures in public view. The property owners and all successors shall acknowledge the applicability of the graffiti removal and deterrence requirements pursuant to Municipal Code Sections 91.8101-F, 91.8904.1 and 91.1707-E relative to the subject project.

Landfill Operation - 18.7 (County)

The permittee shall remove all graffiti in public view on public buildings and structures at the Facility within 48 hours of its placement. The permittee shall also establish and maintain a graffiti deterrent program approved by the DPH-LEA and submitted to the Graffiti Abatement Section of the Department of Public Works.

<u>Current Status/Comments</u> – In mid-April, graffiti was observed on the long downward sloping eastside concrete drainage channel that discharges into the terminal basin. This channel is visible from outside the landfill. Republic staff was procuring paint and scheduling removal. By the May

7th monitoring, the graffiti observed on the prior monitoring visit on the eastside drainage channel was covered with paint.

Q-C.10.c (City)

The operator shall submit, as part of its annual report, an evaluation of the feasibility of beneficial uses of the landfill gas collected at the site such as landfill-gas-to-energy.

Odor/Landfill Gas - 7.07 (County)

The permittee will recover and sell as much gas as is technically and economically feasible to reduce total air quality emissions from the landfill operations. It is expected that the technical and economic feasibility of commercial recovery and sale of landfill gas as a renewable energy resource will occur at levels below 40 MMCFD. The gas collection system will be installed in increments to allow for maximum gas recovery.

Gas - 52 (County)

To the extent technically and economically feasible, the Permittee shall use Landfill gas for energy generation at the Facility or other beneficial uses, rather than flaring, and shall obtain all applicable local, state, and/or federal approvals for any such use. Notwithstanding the forgoing, the Permittee shall be exempt from this Condition No. 52 if, as a 'part of its annual report required by Part X of the IMP, the Permittee determines that any such activity or project is infeasible, which determination shall be subject to the review and approval of the Director of Public Works.

The Permittee shall also install and maintain a landfill gas collection system complying with SCAQMD requirements, which uses best available control technology to control the lateral migration of gases to the satisfaction of the Director of Public Works, County LEA, and SCAQMD. In addition to the other requirements of this Condition No. 52, Landfill gas flares shall be installed below the adjacent interior ridges of the site, unless otherwise required by the SCAQMD, and the flames shall be totally contained within the stacks. Flame arrestors shall be provided to the satisfaction of the County Forester and Fire Warden.

<u>Current Status/Comments</u> -The installation of equipment for the gas-to-energy facility and the commissioning of individual systems were close to completion in early May. In late June, on-line tests and temporary power sales was anticipated to occur as early as late July.

T-4 (City)

Prepare a plot plan ["fire plan"] to the satisfaction of the Fire Department. a. immediate access fire plan [now]

b. plot plan for the future facilities will be submitted when these are implemented

Fire Service - 12.03 (County)

The permittee shall maintain onsite fire response capabilities, construct access road, provide water tanks, water mains, fire hydrants and fire flows and perform brush clearance to the satisfaction of the County Forester and Fire Warden. The landfill will comply with all applicable County codes and ordinances which delineated the requirements for fire access, water mains, fire flows and fire hydrants, specifically defined by the County Fire Department. New construction water tanks, water mains and fire hydrants will be completed to meet the fire flow requirements of the Fire Department.

<u>Current Status/Comments</u> – In mid-April it was observed that the City south top deck dirt road to the oil field road had some of the deep holes filled and high-center vehicles can use this as a

secondary access. Republic is considering improvements so that passenger cars could use this access in an emergency.

Alternative Fuel Vehicles - 77.D (County)

Within the first year after the Effective Date, the Permittee shall design and implement at least one heavy-duty, alternative fuel off-road equipment pilot program, to the extent deemed technologically and economically feasible by the TAC.

<u>Current Status/Comments</u> – Republic should include, as part of its annual report to the TAC, an ongoing evaluation of the feasibility of the use of alternative fuel for off-road equipment.

Alternative Fuel Vehicles - 77.E (County)

- E. Within the three years after the TAC determines that non-diesel, alternative fuel vehicles are technologically and economically feasible:
- 1. The Permittee shall require all transfer trucks entering the Facility to be non-diesel alternative fuel vehicles: and
- 2. All transfer trucks and collection trucks owned or leased by the Permittee and used at the Facility shall be non-diesel alternative fuel vehicles.

<u>Current Status/Comments</u> – Republic should include, as part of its annual report to the TAC, an ongoing evaluation of the feasibility of the use of alternative fuel for transfer and collection trucks. M-4.1.1(2) (City)

Areas outside of and above the cut and fill as shown on the conceptual grading plan shall not be graded, except for the development of ancillary facilities or other related improvements. Additional grading may be necessary for slope stability or drainage purposes. Prior to undertaking any grading activities, the Department of Building and Safety shall be notified and approve any additional grading based on engineering studies (in accordance with CCR Title 27) provided by the project proponent and independently evaluated by the Department of Building and Safety.

M-4.1.1(4) (City)

Grading that allows for construction of ancillary facilities outside of the landfill footprint or that has the potential to impact property beyond the boundary of the landfill shall be approved by the Department of Building and Safety.

M-4.1.1(5) (City)

All grading activities shall be in compliance with specific requirements provided in a comprehensive geotechnical report prepared specifically for the proposed project, including provisions for excavation approved by the Department of Building and Safety, City Engineer, City LEA and other Responsible Agencies.

<u>Current Status/Comments</u> – The excavation plans for the access road realignment has portions outside of the landfill footprint. The plans should be provided to be approved by the City of Los Angeles Department of Building and Safety and the County Department of Public Works for those areas.

Geology-1.02 (County)

Final designs for major engineered structures will be based on the results of the detailed stability analyses of potential seismic events. Final cut slopes shall be no steeper than 1.5:1 (horizontal to vertical ration excluding benches).

<u>Current Status/Comments</u> – It was observed by the monitor that the access road realignment had numerous areas of natural sand deposits in the formation. A detailed stability analysis considering potential seismic events should be performed.

Geology-1.07 (County)

All grading activities shall be in compliance with specific requirements provided in a comprehensive geotechnical report prepared specifically for the proposed Project, including provisions for excavation approved by the County Department of Public Works, the County Local Enforcement Agency (LEA) and other Responsible Agencies.

<u>Current Status/Comments</u> – It is the monitor's understanding that in lieu of material removal, the stability buttress built was approved by the RWQCB as a remedial measure. Areas outside of the landfill footprint should be provided to be approved by the City Department of Building and Safety and the County Department of Public Works.

M-4.1.1(6) (City)

Revegetation and erosion control procedures on all exposed slopes shall be implemented. The erosion controls to be implemented at the site shall include soil stabilization measures and revegetation in accordance with the approved revegetation plan as approved by the City Building and Safety Department. Interceptor ditches shall be designed to divert storm runoff to a sedimentation basin.

M-4.2.11(23) (City)

Disturbed areas shall be revegetated with an interim ground cover as specified in the proposed revegetation program. Excavation will proceed in a manner to reduce the amount of graded areas at any given time.

M-4.2.12 (City)

Site Erosion

c. A temporary vegetation cover shall be established on all slopes that are to remain inactive for a period longer than 180 days.

Geology-1.13 (County)

Revegetation and erosion control of all exposed slopes will be an ongoing process. The erosion controls to be implemented at the site will include soil stabilization measures and revegetation in accordance with the approved Revegetation Program. The installation of interceptor ditches shall be designed for the diversion of storm runoff to sedimentation basins. Sediment traps will be used at points of runoff concentration along the perimeter of exposed slopes surfaces.

Condition: Approval of drainage plan. Retention of a consulting horticulturalist/Registered Professional Forester and an independent qualified biologist by the permittee for ongoing supervision of revegetation programs. Review and monitoring of planting programs by County Forester.

Geology-1.14 (County)

To prevent soil erosion on the face of the landfill, interim vegetation measures will be taken after placement of the temporary soil layer (even though the area may be disturbed by future filling operations). Vegetative cover will be placed as in the approved Revegetation Program.

Condition: Retention of a consulting horticulturalist/Registered Professional Forester and an independent qualified biologist by the permittee for ongoing supervision of revegetation programs. Review and monitoring of planting programs by County Forester.

Biota - 4.42 (County)

Areas inactive for 180 days or longer will be planted with interim vegetation as approved by County biologist. Records will be kept to track fill areas of the site which are transferred to an inactive status so that appropriate dust control and revegetation measures can be implemented.

Visual-10.08 (County)

Cover/Revegetation Requirements

The permittee shall comply with the following cover and re-vegetation requirements at the Landfill:

(1). The permittee shall apply a temporary hydroseed vegetation cover on any slope or other Landfill area that is projected to be inactive for a period greater than 180 days, as set forth in the IMP. The permittee shall promptly notify the County LEA and the Department of Public Works of any such slope or area;

Revegetation Requirements

- (5) Notwithstanding the foregoing, the permittee shall not be bound by the previous provisions of this Condition No. 44, but instead by the requirements of the County LEA, so long as the Limits of Fill are not exceeded, if in consultation with the Department of Public Works, the County LEA determines that a different re-vegetation design or plan:
- (1) would better protect public health and safety;
- (2) would enable revegetation of the final slopes at least as well as shown in Exhibit "B" described in subsection D, above; and/or experts, including an independent, qualified bio(3) would be required because the minimum standards adopted by the CIWMB have been amended;
- (6) the permittee shall employ an expert or biologist, to satisfy this Condition No. 44. Soil sampling and laboratory analysis shall be conducted in all areas that are required to be re-vegetated before any re-vegetation occurs to identify chemical or physical soil properties that may adversely affect plant growth or establishment. Soil amendments and fertilizer recommendations shall be applied and plant materials selected, based on the above referenced testing procedures and results. To the extent possible, plant types shall blend with species indigenous to the area, be drought tolerant, and be capable of rapid growth. The selected plants shall not include nonindigenous species that are likely to be invasive of adjacent natural areas.

Biota - Revegetation - 44.A (County)

A. The Permittee shall apply a temporary hydroseed vegetation cover on any slope or other Landfill area that is projected to be inactive for a period greater than 180 days, as set forth in the IMP. The Permittee shall promptly notify the SCL-LEA and the Department of Public Works of any such slope or area.

Revegetation - 44.F (County)

F. The Permittee shall employ an expert or experts, including an independent, qualified biologist, to satisfy this Condition No. 44. Soil sampling and laboratory analysis shall be conducted in all areas that are required to be re-vegetated before any re-vegetation occurs to identify chemical or physical soil properties that may adversely affect plant growth or establishment. Soil amendments and fertilizer recommendations shall be applied and plant materials selected, based on the above-referenced testing procedures and results. To the extent possible, plant types shall blend with species indigenous to the area, be drought tolerant, and be capable of rapid growth. The selected plants shall not include non-indigenous species that are likely to be invasive of adjacent natural areas.

<u>Current Status/Comments</u> – It was observed during the April 2nd monitoring that hydroseeding of interim or inactive slopes had not started. The hydroseeding contractor was awaiting delivery of seed and soil conditioning supplies. Hydroseeding of interim or inactive slopes started in early April

and was completed by the June 11th site monitoring. It was observed on the June 24th monitoring that due to the lack of rain and no irrigation, the hydroseeding did not germinate.

M-4.1.4(11) (City)

An operations checklist shall be used by a registered engineering geologist for surveys following all earthquake events measuring 5.0 on the Richter Scale or greater near the project site. A comparison of operating parameters and site conditions before and after major earthquake events shall be made to verify that systems are operational as designed. Final designs for major engineered structures shall be based on the results of the detailed stability analyses of potential seismic events.

Geology - 1.16 (County)

An operations checklist will be used by a certified engineering geologist, registered civil engineer or licensed surveyor for surveys following all earthquake events measuring 5.0 magnitude or greater wherein significant shaking or rolling movement was experience at the landfill. All environmental protection and control systems for the landfill will use the best available control technology (BACT) and will be designed to withstand a maximum probable earthquake in accordance with Title 23, Division 3 Chapter 15 §Article 4 2547 of the California Code of Regulations (CCR). A comparison of operating parameters and site conditions before and after major earthquake events (5.0 magnitude or greater) will be made to verify that the designed systems are operational.

<u>Current Status/Comments</u> – The seismic detector/ monitor recorder was relocated on a new concrete pad at the entrance near the recovered/ recycled water facility. Upon evaluation of the equipment, Republic ordered a new, updated detector/ recorder.

M-4.2.13/29, 30, 32, 33, 34 (City)

The natural biological processes that generate odors in a landfill through anaerobic decomposition cannot be prevented or avoided. However, the LFGs shall be prevented from escaping to the atmosphere through the use of control measures. These measures include using daily and intermediate cover material over deposited wastes, filling any surface cracks with clean dirt as necessary, and extracting LFG through the use of an LFG collection and recovery system and destroying collected gases by combustion.

Operational techniques shall be utilized to control odor sources at the landfill. The size of the working face shall be limited so that the area of waste exposed to the atmosphere is kept to a minimum.

The LFG collection and recovery system shall be installed in phases as each portion of the landfill site is filled. The final system shall contain a network of gas extraction wells, collection system piping, and flaring facilities. Because the LFG generation begins at lower levels of volume and increases during the landfill site life, the gas will be flared initially until sufficient quantities are available for processing into electricity.

If an odor problem should develop, appropriate control measures shall be implemented. These measures include the application of additional dirt daily cover material or more frequent application of the cover material to seal the landfill surface, or adjustments to the wells, equipment, and operation of the LFG collection and recovery system.

To ensure that odors are kept to a minimum, the following odor/LFG monitoring program shall be implemented for the proposed landfill project. The monitoring program shall comply with the requirements of SCAQMD Rule 1150.1 and include:

a. Sample Probe Installation: One monitoring probe per 1,000 feet or as identified by South Coast Air Quality Management District (SCAQMD) and/or Local Enforcement Agency (LEA) in the landfill expansion, and one probe per 650 feet or as identified by SCAQMD and/or LEA in the City Inactive landfill along the landfill perimeter, or whichever is more restrictive shall be installed to identify potential areas of subsurface landfill gas (LFG) migration. These probes shall be monitored to ensure that quantities of LFG beyond regulatory standards do not vent offsite through subsurface soils.

- b. Integrated Landfill Surface Sampling: The landfill surface shall be monitored to ensure that the average concentration of total organic compounds over the landfill surface does not exceed SCAQMD's standard of 25 ppm.
- c. Ambient Air Samples: 24-hour integrated gas samples and required meteorological data shall be taken to assess any impact the landfill is having on the ambient air quality at the landfill perimeter.
- d. Instantaneous Landfill Surface Monitoring: Spot checks on the landfill surface shall be made to determine the maximum concentration of total organic compounds measured as methane, measured at any one point on the surface of the landfill does not exceed the SCAQMD's standard of 500 ppm.
- e. Regular Monitoring and Annual Testing: LFG concentrations at perimeter probes, gas collection system headers, the landfill surface, and in ambient air downwind of the landfill shall be monitored once per month or less frequently (but no less than quarterly) as required by the SCAQMD. The LFG collection system shall be adjusted and improved based on quarterly monitoring data and annual stack testing results.

Odor/Landfill Gas - 7.06 (County)

If an odor problem should develop, appropriate control measures shall be implemented. These measures include the application of daily cover material or more frequent applicant of the cover material to seal the landfill surface, or adjustments to the wells, equipment, and operation of the LFG collection and recover system.

Amendment 45.N - 4.a, 4.c, 4.d (County)

Identify and provide status on the measures currently being implemented as required by the AQMD's Order for Abatement.

An odor patrol program, which would include the following at a minimum:

- Provide a trained technician to conduct odor patrols in the surrounding neighborhoods at a frequency of one patrol per hour from 6 a.m. to 10 a.m., Monday through Saturday, and during adverse wind conditions.
- If odor is detected, identify its potential and/or actual source, including those that may not be related to the Landfill's operation, such as an odorous trash dumpster or transfer trucks.
- If odor is determined to be related to the Landfill's operation, take immediate action to reduce the odor. Document the streets patrolled on a map, time of the patrol, potential source of odor, and immediate actions taken by the Landfill.
- A landfill gas mitigation plan in preparation for the next rainy season since landfill gas emissions from either the landfill surface or landfill gas control equipment is cited as a potential contributor in the AQMD's Order for Abatement. The plan should include the following at a minimum:
- Description of the site's current Gas Monitoring and Control Plan, including a map showing locations of gas monitoring probes, gas extraction wells, horizontal and vertical gas collection lines, etc.
- Compliance history of the site's landfill gas migration control program from January 1, 2009, to the present quarter as well as any corrective actions.
- Discuss the impacts of the most recent heavy rains on the landfill gas collection system, including identifying locations of damage due to soil erosion, as well as any corrective actions or mitigation measures.
- A work plan that includes preventive measures, such as identifying and filling any surface cracks and installing additional extraction wells, as well as contingency measures.
- An implementation schedule for the above work plan.

Amendment 45.N - 5 (County)

Include in the Quarterly Dust and Odor Reports, which are required by CUP Condition No. 45.N, the status and effectiveness of mitigation measures 1 through 3 above, and the Odor Mitigation Plan.

<u>Current Status/Comments</u> – Compliance with these mitigation measures, concerning landfill gas monitoring and odor control and detection, is being monitored by a multi-agency team led by the SCAQMD. Only obvious gas emission sources, lack of cover, or exposed trash resulting in odor and gas emissions observed during the monitoring visit will be reported. None of these were observed during the quarterly monitoring visits this period.

M-4.3.1(36) (City)

To ensure that infiltration of surface water into the closed landfill cells is minimized, surface runoff shall be intercepted and diverted around the landfill. The method of diversion used at the project site shall include the use of lined interceptor ditches placed along the edges of the landfill areas. This system of ditches shall flow into monitored sedimentation basins. After sediment content has been reduced, surface waters shall flow into the existing flood control channel directly east of the project site entrance.

Surface Water - 2.03 (County)

As development of the site proceeds, surface drainage control facilities will be maintained so that surface water runoff is diverted from the working faces and isolated from contact with the waste. Onsite drainage control channels will be designed per CCR, Title 23, Division 3, Chapter 15, Article 3, § 2546, which mandates the requirements for a capital storm event (100 year, 24-hour precipitation).

<u>Current Status/Comments</u> – On the April 2nd site monitoring, ponding was observed on the road to Deck C, along the southern perimeter road, in the bottom of Cell C-3A Part II, and on a couple of low spots on the County top deck. This was the result of the last rainstorm. The ponding observed was reported to Republic by the independent monitor. Republic was scheduling crews to fix these areas.

M-4.3.1(38) (City)

Permanent bench drainage ditches shall be installed when final cover is placed on completed portions of the landfill. These ditches shall be lined. Temporary unlined drainage facilities consisting of diversion ditches (V-ditches) where necessary shall directly intercept natural surface runoff. Any intermittent channel flow in the existing canyon bottom shall be captured, channeled, and conveyed into a sedimentation basin. Diversion ditches shall convey surface runoff from the undisturbed areas to the permanent perimeter ditches for safe transport around the landfill footprint. Surface covers of various types, from mulches to vegetation, shall be used to retard erosion from areas of disturbance. In addition, areas of disturbance shall be kept at a minimum during active filling operations.

Surface Water - 2.12 (County)

Permanent bench drainage ditches shall be installed when final cover is placed on completed portions of the landfill. These ditches shall be lined. Temporary unlined drainage facilities consisting of diversion ditches (V-ditches) where necessary shall directly intercept natural surface runoff. Any intermittent channel flow in the existing canyon bottom shall be captured, channeled, and conveyed into a sedimentation basin. Diversion ditches shall convey surface runoff from the undisturbed areas to the permanent perimeter ditches for safe transport around the landfill footprint. Surface covers of various types, from mulches to vegetation, shall be used to retard erosion from areas of disturbance. In addition, areas of disturbance shall be kept at a minimum during active filling operations.

<u>Current Status/Comments</u> – Temporary and permanent drainage ditches have been installed to convey water to the basins. The majority of inactive and/or areas that have been disturbed have no temporary or permanent vegetation or other surface cover to retard erosion.

M-4.3.1(45) (City)

An erosion control plan would be implemented by the project proponent to prevent stormwater pollution from construction activity. Construction materials, equipments and vehicles would be stored or parked in areas protected from stormwater runoff. Construction material loading and unloading would be in designated areas to minimize any washout due to stormwater runoff. Pre-construction controls would be implemented to include the use of a sandbagging system, including sandbag check dams and sandbag desilting basins, which would used to limit runoff velocities and minimize sediment in storm water runoff.

Surface Water 2.14 (County)

An erosion control plan would be implemented by the project proponent to prevent stormwater pollution from construction activity. Construction materials, equipments and vehicles would be stored or parked in areas protected from stormwater runoff. Construction material loading and unloading would be in designated areas to minimize any washout due to stormwater runoff. Pre-construction controls would be implemented to include the use of a sandbagging system, including sandbag check dams and sandbag desilting basins, which would used to limit runoff velocities and minimize sediment in storm water runoff.

<u>Current Status/Comments</u> – Republic staff informed the monitoring staff during the June 24th monitoring that a State Water Resources Control Board stormwater management plan was prepared and submitted to the water board for approval. The plan is being implemented and all control measures will be in place before October 15th.

M-4.3.1(46) (City)

A preventive maintenance program would be implemented by the project proponent, including inspection of facility equipment, systems, and stormwater management devices to detect conditions that may cause breakdowns or failures resulting in discharge of materials into stormwater. This program applies to the onsite drainage ditches; rip-rap; berms and dikes; dust control; silt fences; diversion grading; and pavement surfaces. Each system and piece of stationary equipment would be inspected monthly. Procedures for inspection would vary, due to the piece of equipment or system. However, the major elements of the inspection program would include checking for cracks or structural failures, inspecting parts or pieces of equipment nonfunctioning, checking for the degradation or deterioration of operating units, and investigating the need for cleaning or emptying units. A summary report of these monitoring results and the corrective actions taken will be disseminated in each newsletter with a more detailed report on the web site and in the annual report.

Surface Water 2.15 (County)

Surface Water Preventive Maintenance Program

A preventive maintenance program will be implemented by the permittee, including inspection of facility equipment, systems, and stormwater management devices to detect conditions that may cause breakdowns or failures resulting in discharge of materials into stormwater. This program applies to the onsite drainage ditches, rip-rap, berms and dikes, dust control, silt fences, diversion grading, and pavement surfaces. Each system and piece of equipment will be inspected monthly.

Procedures for inspection would vary based on the piece of equipment or system. However, the major elements of the inspection program will include checking for cracks or structural failures, inspecting parts or pieces of equipment nonfunctioning, checking for the degradation or deterioration of operating units, and investigating the need for cleaning or emptying units.

<u>Current Status/Comments</u> – It was observed on the June 24th monitoring that along a portion of the westside drainage channel between Basin A and Basin D, the floor of the basin is uplifted in the middle with large cracks and weeds growing. This indicates the presence of moisture interacting with possible swelling soils. This was previously observed and noted. At the connection between the V-ditch feeding the channel, there is a gap between shotcrete and soil which is a conduit for water to infiltrate beneath the channel shotcrete into the subbase soil. Cracks mentioned in previous visits on the westside (native soil side) of the channel and eastside (landfill side) are getting worse with concrete spalling and pieces falling off.

M-4.3.2(49) (City)

Areas of natural groundwater seepage shall be intercepted by the installation of a subgrade gravel drainage blanket. A series of underdrains shall be placed in areas where seeps and springs have been identified, and they shall collect and convey any water from these sources to the sedimentation basin. In the event any chemical constituents are in the seep water, the seep waters will be sampled, analyzed, collected, and then sent either to the onsite leachate treatment facility or offsite for proper treatment and disposal. The nature and the source of the seep would be investigated including additional sampling and laboratory testing.

Surface Water 2.05 (County)

Placement of a series of underdrains in areas where seeps and springs have been identified will collect and convey any water from these sources.

<u>Current Status/Comments</u> – During the June 24th monitoring, the large-diameter corrugated steel drain pipe that was unearthed in the City south soil stockpile in January was completely uncovered, and the seep that was feeding this drain pipe was intercepted and eliminated.

A smaller seep coming from around an abandoned gas pipeline on the slope was also intercepted and eliminated.

M-4.4.1(60) (City)

Venturan Coastal Sage Scrub

A detailed conceptual mitigation plan shall be prepared by the project proponent and contain specific information on planting, maintenance, and monitoring. A revegetation plan that includes Coastal sage scrub restoration can feasibly occur onsite. The implementation of this plan will provide onsite mitigation greater than 1:1 to offset the loss of coastal sage scrub.

Biota - 4.27 (County)

Venturan Coastal Sage Scrub: A detailed conceptual mitigation plan shall be prepared by the permittee and shall contain specific information on planting, maintenance, and monitoring. A revegetation plan that includes coastal sage scrub restoration can feasibly occur onsite. The implementation of this plan will provide onsite mitigation greater than 1:1 to offset the loss of coastal sage scrub.

<u>Current Status/Comments</u> – The following conditions at the Deck C sage mitigation area were observed:

On April 2nd, the Deck C vegetation was getting established, with good plant coverage on the deck. Approximately 70-80% of the plants were salt bush. Black sage did not survive. Other native plants and sage were doing fair.

On April 16th, the salt bush was growing faster and taller than other plants. Republic's biological consultant and vegetation contractor are monitoring the mitigation site.

On May 7th, it was observed that the salt bush was providing cover for plants to grow in their understory. The area appeared to be over-watered for the sage and summer heat.

On June 11th, the sage and other native plants were going through their summer die-back. The salt bush was growing and spreading.

On June 24th, the area irrigation was cut back. Some salt bush was cut back to allow understory plants to grow. California Fish and Wildlife should be consulted to confirm the mitigation plants growing will meet the requirements of the sage mitigation for the agency.

Biota-4.29 (County)

San Diego Horned Lizard: Impact on the San Diego horned lizard can be mitigated to a level of less than significant by restoring coastal sage scrub habitat. This will create a temporal loss of the species, but the population should recover following restoration of this habitat. Topsoils should be selected that are friable to suit lizard habitat requirements.

<u>Current Status/Comments</u> – The monitor was informed that the mitigation sites for the San Fernando Horned Lizard will be included in the County and City Sage Mitigation.

M-4.4.1/67 (City)

Migratory Bird Treaty Act

To prevent the loss of an active migratory bird nest, vegetation shall not be cleared during the breeding season (i.e., March 15 to August 1). If vegetation clearing needs to occur, surveys shall be conducted by biologists to determine active migratory bird nests. All active migratory bird nests shall be protected until the young become independent.

Biota-4.13 (County)

All oak trees will be counted when removed to verify that adequate mitigation has been provided in accordance with the Oak Tree Mitigation Plan.

Biota-4.30 (County)

California Gnatcatcher: Surveys shall be conducted for California gnatcatchers prior to Game Permit onsite grading to determine the status of this Game species within development areas.

Biota - 4.33 (County)

Migratory Bird Treaty Act

To prevent the loss of an active migratory bird nest, vegetation shall not be cleared during the breeding season (i.e., March 15 to August 1). If vegetation clearing needs to occur, surveys shall be conducted by biologists to determine active migratory bird nests. All active migratory bird nests shall be protected until the young become independent.

<u>Current Status/Comments</u> – During the May 7th monitoring the tree and vegetation removal along the landfill entrance road for the access road realignment was observed. Numerous oak trees were removed along with some coastal sage vegetation. Biological monitoring was done by Republic before the start of tree and vegetation removal. The vegetation was previously evaluated, accounted for, and part of prior mitigation plans. Republic biological consultant stated that no additional biological assessment was required.

M-4.9.3(109) (City)

On a once-a-week basis, or as needed, the landfill operator shall mobilize cleanup crews to provide litter pickup services within the O'Melveny Park area, along Balboa Boulevard and San Fernando Road, and in other residential areas located in proximity to the landfill, that may be affected by offsite litter migration. On a daily basis, the cleanup crews shall inspect the surrounding area to assess if more frequent cleanups are required. Fences outside of the landfill perimeter may be visible to the surrounding community.

M-4.9.3(112) (City)

The City LEA shall inspect the landfill on a regular basis, at which time the effectiveness of the litter control program shall be documented and any necessary improvements shall be made, including:

- a. Landfill personnel shall continuously patrol the access road to the scales from the time the landfill opens until the time of closure in the evening.
- b. Improperly covered or contained loads that may result in a significant release of litter shall be immediately detained and the condition corrected, if practical, before the load proceeds to the active working face areas. If correction cannot be made, the load shall be conducted under escort to the working face.
- c. All debris found on or along the landfill entrance and working face access road shall be immediately removed.
- d. Operating areas shall be located in wind-shielded portions of the landfill during windy periods.
- e. Litter fences shall be installed in operating active working face areas, as deemed necessary by the LEA.

Visual 10.11 (County)

The permittee's onsite Litter Control Program will include continuous patrol of the access road and working face during hours of operations and mobilize clean-up crews on a regular basis for litter pick-up along designated public access routes, O'Melveny Park and the adjacent neighborhood.

<u>Current Status/Comments</u> – During this quarterly monitoring period, no wind-blown litter was observed in the adjacent neighborhood.

On the April 2nd monitoring, wind-blown litter was observed in the eastside drainage channel and on the back hillsides of Basins A and B. The terminal basin front exterior wall had wind-blown and illegally-dumped debris.

On the April 16th and May 7th monitoring, wind-blown litter was observed on the back hillsides of Basin A and Basin B.

On the April 16th monitoring, illegal dumping was observed on Sierra Highway north of the I-14 overpass. The area appeared to have been cleaned of wind-blown litter by Republic.

On the June 11th monitoring, wind-blown litter was observed on the back hillsides of Basin A. The back hillsides of Basin B were cleared of litter.

On the June 11th monitoring, illegal dumping was observed on Sierra Highway north of the I-14 overpass and on San Fernando Road south of the Old Road. All areas appeared to have been cleared of wind-blown litter.

M-4.9.4(121) (City)

The landfill operator shall implement a fire prevention plan in compliance with CCR, Title 8, § 3221. Components of this written fire prevention plan shall include potential fire hazards and their proper

handling and storage procedures; potential ignition sources (i.e., welding or smoking), their control procedures, and the type of fire protection equipment or systems that can control a fire involving them; names or regular job titles of those responsible for maintenance of equipment and systems installed to prevent or control ignitions or fires; and names or regular job titles of those responsible for the control of accumulation of flammable or combustible waste materials.

Fire Service - 12.03 (County)

The permittee shall maintain onsite fire response capabilities, construct access road, provide water tanks, water mains, fire hydrants and fire flows and perform brush clearance to the satisfaction of the County Forester and Fire Warden. The landfill will comply with all applicable County codes and ordinances which delineated the requirements for fire access, water mains, fire flows and fire hydrants, specifically defined by the County Fire Department. New construction water tanks, water mains and fire hydrants will be completed to meet the fire flow requirements of the Fire Department.

<u>Current Status/Comments</u> – On April 2nd, it was observed that all the tree branches at the leachate treatment facility had been trimmed to clear the power lines.

M-4.9.4(125) (City)

The landfill operator shall maintain perimeter fencing in and around the site in accordance with CCR, Title 14, § 17658 to discourage illegal entry to the landfill. Where existing topography conditions create an effective barrier, no perimeter fencing shall be installed. Entrance and access gates shall remain locked when the landfill facility is not in operation. All existing perimeter fencing shall be inspected on a routine basis by the landfill operator, and necessary repairs shall be made to ensure a continued deterrent for unauthorized entry to the project site. Additionally, the landfill operator shall maintain posted "no trespassing" signage at the exterior perimeter fencing nearest the project site entrance.

<u>Current Status/Comments</u> – On April 16th, the southern oil field perimeter gate was unlocked and standing open.

M-4.19.1(183) (City)

Prior to the commencement of initial earth excavation, specific sections of the project area shall be resurveyed as a precautionary measure to minimize potential loss of undiscovered archaeological resources. Specific areas within the project site to be resurveyed shall be determined by the intended cut-and-fill areas proposed for landfill development. As new areas for excavation are identified, an evaluation of those areas shall be made based on the prior survey results and consultation with appropriate technical specialists. Factors to be considered for delineation of areas to be resurveyed will be known site selection factors associated with aboriginal groups suspected of having inhabited the general area. These factors include proximity to water, the type of vegetation (e.g., food source, shelter, and fuel), and the topography (e.g., slope and aspect).

Ecological Significance 62 (County)

The Permittee shall develop and implement a program to identify and conserve all significant archaeological and paleontological materials found onsite pursuant to Part VII of the IMP. If the Permittee finds any evidence of aboriginal habitation or fossils during earthmoving activities, Landfill operations shall immediately cease in that immediate area, and the evidence and area shall be preserved until a qualified archaeologist or paleontologist, as appropriate, makes a determination as to the significance of the evidence. If the determination indicates that the archaeological or paleontological resources are significant, the resources shall be recovered to the extent practicable prior to resuming Landfill operations in that immediate area of the Landfill.

<u>Current Status/Comments</u> – Prior to the April 2nd monitoring, an archaeological survey was performed on the main access road realignment area. No items of concern were found. Prior to the June 16th monitoring, an archaeological survey was performed on the area where site grading was being done west of the landfill office. No items of concern were found. Archaeological reports are on file and are available in Republic's offices.

M-4.19.2(187) (City)

Prior to the commencement of initial earth excavation, specific sections of the City/County Landfill Project area shall be resurveyed as a precautionary measure to minimize potential loss of undiscovered paleontological resources. Specific sections of the project area to be resurveyed shall be as determined by the intended cut-and-fill areas proposed for landfill development. As new areas for excavation are identified by the project proponent, an evaluation of those areas shall be made based on the prior survey results and consultation with appropriate technical specialists.

Ecological Significance 62 (County)

The Permittee shall develop and implement a program to identify and conserve all significant archaeological and paleontological materials found onsite pursuant to Part VII of the IMP. If the Permittee finds any evidence of aboriginal habitation or fossils during earthmoving activities, Landfill operations shall immediately cease in that immediate area, and the evidence and area shall be preserved until a qualified archaeologist or paleontologist, as appropriate, makes a determination as to the significance of the evidence. If the determination indicates that the archaeological or paleontological resources are significant, the resources shall be recovered to the extent practicable prior to resuming Landfill operations in that immediate area of the Landfill.

<u>Current Status/Comments</u> – On the April 2nd monitoring it was confirmed that a paleontological survey was performed on the main access road realignment area. Minor non-recoverable marine fragments were observed and pieces saved for Republic. On June 11th and June 24th monitoring, it was observed that paleontological surveys were being performed on the area where site grading was being done west of the landfill offices. Whale bone and other marine fragments were found. No items were recoverable in one piece. Paleontological reports are on file and are available in Republic's offices.

Summary of Requested Documents

The following documents, reports and plans are recommended to be made available at the site for agency and monitor review in order to assist in streamlining the monitoring process.

- a) Design report for the Leachate Collection and Treatment Facility (LCTF).
- b) Current Fill Sequence Plan.
- c) A plan showing areas inactive for 180 days or longer with records tracking fill areas and interim reclamation and revegetation, including the timing of proposed work, as well as a plan showing current and projected areas to be within ten feet of the limits of fill.
- d) Maps showing areas that are at final elevation and bench ditches that will connect to drainage ditches to protect against natural surface runoff.
- e) The current erosion control plans should be available for agency and monitor review.
- f) Site drainage plans, including surface and underdrain systems with complementing revegetation plan.
- g) A plan/ report of the liner interceptor ditches design/ installation to ensure that surface runoff is appropriately conveyed to the existing flood control channel directly east of the project site entrance.
- h) Comprehensive geotechnical reports.
- i) A preventative maintenance plan and summary of monitoring reports of inspections of facility equipment, systems and stormwater management devices to detect conditions that may cause breakdowns or failures resulting in discharge of materials into stormwater.

Conclusions

In this reporting period, UltraSystems has monitored the conditions and/or mitigation measures for the City/ County, as shown on the Mitigation Monitoring Summary Excel spreadsheets.

As shown by the Non-Compliant and Further Review Needed sections above, the landfill is actively working toward being fully compliant with conditions and/or mitigation measures, with no non-compliant conditions observed. Furthermore, monitoring of the tasks on these Excel spreadsheets tracks progress toward being fully compliant. Notwithstanding the above, air quality issues are not being actively monitored by UltraSystems, and may not be compliant.

The 2014 Second Quarter Mitigation Monitoring Summary Excel spreadsheets track the progress and completion of tasks as they were accomplished during this quarterly period.

										Firs		arte					11 00				,					Se	cond	l Qua	rter	<u> </u>						
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	rurner keview Needed/Comments**	Resolved*	Status*	Further Review	Needed/Comments	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments** Resolved*
Project Mar	nager																																			
Q - A.3.		Definitions	info	/				/			,	/			/				/			,	/			/				/				/		
Q - A.6.		Submit Annual Reports	June yearly	/				/			,	/			/				/			,	/			/				/				/		
Q - A.10.		Provision of Fees	yearly	/				/			,	/			/				/			,	/			/				/				/		
Q - B.1.		Permitted/Prohibited Landfill Uses	yearly	/				/			,	/			/				/			,	/			/				/				/		
Q - B.2		Approval of Landfill	ongoing	√	С	I-a		✓	C N	ONE	,	/ C	NON	ΙE	√	С	I-d		~	С	NONE	,	/ C	NON	Е	✓	С	NONE		√	С	NONE		✓	C	NONE
Q - B.2.c.		Ancillary Uses and Facilities	ongoing	✓	С	NONE		√	C N	ONE	,	⁄ C	NON	ΙE	✓	С	NONE		√	С	I-e	,	/ C	NON	E	✓	С	NONE		✓	С	NONE		✓	С	I-i
		Ancillary Uses and Facilities																																		
Q - B.2.d (3)		10 Year Phase Review	2015	/				/			,	/			/				/			,	/			/				/				/		
		10 Year Phase Review																																		
Q - B.4.d.		Inert/Exempt Materials	info	/				/			,	/			/				/			,	/			/				/				/		
Q - B.5.a.		Prohibited Waste	info	/				/			,	/			/				/			,	/			/				/				/		
Q - B.6.		Waste Diversion	ongoing	✓	С	NONE		✓	C N	ONE	,	C	NON	ΙE	✓	С	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	С	NONE		✓	C	NONE
Q - C.3.g.		Paved Access Roads	ongoing	✓	С	NONE		√	C N	ONE	,	/ C	NON	ΙE	✓	С	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	С	NONE		✓	C	NONE
Q - C.3.h.		Surfacing of Access Roads	ongoing	✓	С	NONE		✓	C N	ONE	,	/ C	NON	ΙE	✓	С	NONE		✓	С	NONE	,	/ C	NON	Е	~	С	NONE		✓	С	NONE		✓	C	NONE
Q - C.5.		Graffiti Removal and Deterrence	ongoing	√	С	NONE		✓	C N	ONE	,	⁄ C	NON	ΙE	✓	С	NONE		✓	С	NONE	,	∕ FR	N I-f		√	С	I-g		√	С	NONE		✓	C I	NONE
Q - C.10.c.		Evaluation of Beneficial Gas Usage	June yearly	√	С	I-a					,	/ C	I-c													✓	С	I-g						√	С	I-i
Q - C.10.d. (1)		Alternative Fuel Vehicles	status																									Ĭ								
Q - C.10.d. (2)		Alternative Fuel Refuse Collection Trucks	status																																	
Q - C.12.a.		Technical Advisory Committee	info	/				/			,	/			/				/			,	/			/				/				/		

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

			,						Fir	st Qu	artei	•											S	econ	d Qua	rter						
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved* 4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review	Needed/Comments** Resolved*
Q - C.12.c.		Contract for Mitigation Monitoring	info	/			,	,			/			/			/			/			,	,		,	/			/		
Q - C.12.c.		Contract for Mitigation Monitoring-5 years	info	/			,	/			/			/			/			/			/	/		,	/			/		
T - 4		Fire Plan	status								/ FRN	I-c								✓	FRN	I-f										
T - 5.j.		Trip Diversion	status	✓	С	NONE	,	C	NONE		C	NONE		✓ C	NONE		✓	С	NONE	✓	С	NONE	,	C	NONE	,	/ C	NONE		✓ C	NON	ΙE
T - 6		Satisfactory Street Lighting	status	/			,	/		,	/			/			/			/			/	/		,	/			/		
M - 4.1.1	7	Reabandonment Procedures	status	√	С	NONE	,	C	NONE	,	C	NONE		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ C	NON	ΙE
M - 4.1.4	11	Post-5.0 Earthquake Analysis	upon event	/	NA	NONE	,	/ NA	NONE	,	/ NA	NONE		/ NA	NONE		/	NA	NONE	/	NA	NONE	/	/ NA	NONE	,	/ NA	NONE		/ NA	NON	ΙE
M - 4.2.12	27	Heavy Equipment Operations	ongoing	√	С	NONE	,	/ C	NONE		/ C	NONE		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ C	NON	ΙE
M - 4.2.12		Heavy Equipment Operations	ongoing	✓	С	NONE	,	C	NONE	,	C	NONE		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ C	NON	ΙE
M - 4.2.12	28	Site Erosion-Cover	ongoing	√	С	NONE	,	/ FRN	I-b		C	NONE		✓ C	NONE		✓	С	NONE	~	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ c	NON	ΙE
M - 4.2.12		Site Erosion-Cell Height	ongoing	√	С	NONE	,	/ C	NONE		/ C	NONE		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ C	NON	ΙE
M - 4.2.12		Site Erosion-Sealant	ongoing	√	FRN	I-a	,	/ C	NONE		FRN	I-c		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ c	NON	ΙE
M - 4.2.13	29	LFG Control Measures	ongoing	/		I-a	,	/	I-b	,	/	I-c		/	I-d		/		I-e	/		I-f	/	/	I-g	,	/	I-h		/	I-i	
M - 4.2.13	30	Operational Odor Control Techniques	ongoing	✓	С	NONE	,	C	NONE	,	C	NONE		✓ C	NONE		√	С	NONE	✓	С	NONE	,	/ C	NONE	,	/ C	NONE		✓ C	NON	ΙE
M - 4.2.13	31	Solid Waste Compaction	ongoing	√	С	NONE		C	NONE		C	NONE		✓ C	NONE		✓	С	NONE	~	С	NONE	,	C	NONE	,	/ C	NONE		✓ C	NON	ΙΕ
M - 4.2.13	32	LFG Collection and Recovery System	ongoing	/		I-a		/	I-b		/	I-c		/	I-d		/		I-e	/		I-f		/	I-g	,	/	I-h		/	I-i	
M - 4.2.13	33	Odor Control Measures	ongoing	/		I-a	,	FRN	I-b		/	I-c		/	I-d		/		I-e	/		I-f	/	/	I-g	,	/	I-h		/	I-i	
M - 4.2.13	34	Odor/LFG Monitoring	ongoing	/		I-a		/	I-b		/	I-c		/	I-d		/		I-e	/		I-f	/	/	I-g	,	/	I-h		/	I-i	
		Periodic LFG Monitoring		/		I-a	,	/	I-b	,	/	I-c		/	I-d		/		I-e	/		I-f	/	/	I-g	,	/	I-h		/	I-i	
M - 4.3.2	52	LFG Migration Mitigation	ongoing	/	NA	NONE	,	/ NA	NONE		/ NA	NONE		/ NA	NONE		/	NA	NONE	/	NA	NONE	,	/ NA	NONE	,	/ NA	NONE		/ NA	NON	ΙE

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

									F	rst C	luar	ter						I							S	ecor	ıd Qu	arte	r						
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	4102/01/4 Status*	Further Review	Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review	Needed/Comments**	Kesolved* 4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments** Resolved*
M - 4.3.2	57	Dust Control Water	ongoing	✓	С	NONE	,	√ (NON	E	✓	С	NONE		√ C	NO	NE	~	C	NONE		√	С	NONE	,	C	NON	E	√	С	NONE		✓		NONE
M - 4.4.2	69	Offsite Mitigation Sites	status				,	√ (: I-b																										
M - 4.4.2	70	Purchasing Wetland Credit	status	/			,	/			/				/			/	,			/			,	/			/				/		
M - 4.4.2	71	Funding-Invasive Species Eradication Program	status	/			,	/			/				/			/	,			/			,	/			/				/		
M - 4.6	85	Site Lighting	status	✓	С	NONE	,	✓ (NON	Е	✓	С	NONE		√ C	NO	NE		C	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.7.1	86	Open Space Buffer Area	ongoing	✓	С	NONE	,	✓ (NON	Е	✓	С	NONE		√ C	NO	NE		C	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.9.3	106	Litter Minimization	ongoing	✓	С	NONE	,	√ (NON	Е	✓	С	NONE		√ C	NO	NE	,	C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.9.3	107	Litter/Debris Containment	ongoing	✓	С	NONE	,	√ (NON	Е	√	С	NONE		√ C	NO	NE	,	C	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	C I	NONE
M - 4.9.3	108	Vehicle Tarping Requirements	ongoing	✓	С	NONE	,	√ (NON	Е	✓	С	NONE		√ C	NO	NE	,	C	NONE		✓	С	NONE	,	/ C	NON	Е	✓	С	NONE		✓	C I	NONE
M - 4.9.3	109	Periodic Offsite Litter Pickup	ongoing	✓	FRN	I-a	,	✓ FF	N I-b		√ I	FRN	I-c		✓ FR	RN I-	d					✓ I	FRN	I-f					✓	FRN	I-h				
M - 4.9.3	110	Illegal Dumping Activities	ongoing	✓	С	NONE		/ (NON	Е	✓	С	NONE		√ C	NO	NE					✓ I	FRN	I-f					✓	FRN	I-h				
M - 4.9.3	111	Radio Dispatch Litter Control	ongoing	✓	С	NONE		/ (NON	Е	√	С	NONE		√ C	NO	NE	٠,	C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.9.3	112	Litter Control	ongoing	✓	С	NONE	,	/ (NON	Е	✓	С	NONE		√ C	NO	NE	,	FRN	I I-e		✓ I	FRN	I-f		∕ FRI	N I-g		✓	FRN	I-h				
M - 4.9.5	127	Address Concerns of Citizens' Advisory Committee	ongoing	/			,	/			/				/			/	,			/				/			/				/		
M - 4.9.6	128	Landfill Gas/Collection System-Unsafe Methane	ongoing	✓	С	NONE	,	/ (NON	Е	✓	С	NONE		√ C	NO	NE		C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.9.6	129	Landfill Gas/Collection System-Detection/Training	ongoing	√	С	NONE	,	/ (NON	E	✓	С	NONE		√ C	NO	NE		C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.9.6	130	Landfill Gas/Collection System-Risk Mitigation	ongoing	√	С	NONE		√ (NON	Е	√	С	NONE		√ C	NO	NE	,	C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE
M - 4.16.4	176	Reclaimed Water	status	/			,	/			/				/			/	,			/			,	/			/				/		
M - 4.16.4	177	Water Conservation	ongoing	✓	С	NONE		√ (NON	Е	✓	С	NONE		√ C	NO	NE	,	C	NONE		✓	С	NONE		/ C	NON	Е	✓	С	NONE		✓	C	NONE

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

				I						First						8		Ī							•	Seco	ond	Quar	ter	_	—					\neg
Reference#	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014 Status*	Further Review	Needed/Comments**	Z/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014 Status*	Further Review	Needed/Comments**	Kesolved" 4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review Needed/Comments**	Resolved*
Civil & Ge	otech	nical Engineer																												Т	П					
M - 4.1.1	2	Grading Outside of Conceptual Grading Plan Area Unsuitable Material	ongoing												✓ FF	RN	I-d													I				FRN	I-i	
M - 4.1.1	3	Removal/Buffer Zones	ongoing																																	
M - 4.1.1	4	Grading Outside of Landfill Footprint	ongoing												✓ FF	RN	I-d																	FRN	I-i	
M - 4.1.1	5	Grading Activity Compliance	ongoing												✓ FF	RN	I-d																	FRN	I-i	
M - 4.1.2	8	Landslide Guidelines	ongoing																															FRN	I-i	
M - 4.1.2	9	Soil Stabilization	ongoing																															FRN	I-i	
M - 4.1.4	10	Landfill Design	ongoing																																	
M - 4.1.4	11	Earthquake Öperations Checklist	upon event	/	NA	NONE		/ N/	A NC	ONE	/	NA	NONE		/ N	NA N	NONE		/ NA	A NOI	NE	√	С	I-f		/ 1	NA	NONE		/	NA I	NONE		/ NA	NONE	Ξ
M - 4.1.5	12	TLIQUEIACION	ongoing																																	
M - 4.1.5	13	Design/Construction- Liquefaction	ongoing																																	
M - 4.1.5	14	Design/Construction- Containment Structures	ongoing																																	
M - 4.1.6	15	Refuse Slope Gradients	ongoing	~	С	NONE		✓ C	NC	ONE	~	С	NONE		✓ (C N	NONE		✓ C	NOI	NE	✓	С	NONE		✓	С	NONE		✓	C	NONE		C	NONE	<u> </u>
M - 4.1.6	16	Cut and Fill Slope Gradients	ongoing	✓	С	NONE		✓ C	NC	ONE	✓	С	NONE		✓ (C N	NONE		✓ C	NOI	NE	√	С	NONE		✓	С	NONE		✓	C	NONE		C	NONE	Ξ
M - 4.1.6	17	Final Slope Factors of Safety	ongoing																																	
M - 4.1.6	18	Survey Monuments	ongoing	✓	С	NONE		✓ C	NC	ONE	✓	С	NONE		✓ (C N	NONE																			
M - 4.3.2	47	Landfill Liner	ongoing																																	
M - 4.3.2	48	Landfill Liner	ongoing																																	
M - 4.3.2	54	Preliminary Closure/Postclosure Plan	status																																	
M - 4.3.2	55	Landfill Design/Operation/Final	status																																	

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

									F			arter				5 v		T		·					Sec	ond	l Qua	rter							
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Z/5/ZU14 Status*	Further Review	Needed/Comments**	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review	Meeded/Collinells	Resolved.	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014 Status*	Further Review	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments** Resolved*
M - 4.3.2	56	Cover Application	ongoing															~	C	NONE		√ (✓	С	NONE		✓	С	NONE		✓		NONE
M - 4.14.1	155	Access Roadway Grade	ongoing																																
M - 4.18	178	Landfill Elevation Exceedance	ongoing															~	C	NONE		√ C	NON	_	✓	С	NONE		✓	С	NONE		✓	C I	NONE
Hydrologis	st																												1						
M - 4.1.4	11	Earthquake Operations Checklist	upon event	/	NA	NONE		/ NA	NON	NE	/	NA	NONE		/ NA	NON	E	/	' NA	NONE		/ N.	A NON	=	/	NA	NONE		/	NA	NONE		/	NA I	NONE
M - 4.3.1	36	Surface Water Infiltration Minimization	ongoing												✓ FRI	l-d		~	FRN	I-e															
M - 4.3.1	37	Surface Drainage Systems	ongoing																														✓	С	I-i
M - 4.3.1	38	Permanent/Temporary Ditches	ongoing	✓ F	FRN	I-a																											✓	С	I-i
M - 4.3.1	39	Drainage Protection	ongoing																																
M - 4.3.1	40	SWRCB Permit Coverage	ongoing																														✓	С	I-i
M - 4.3.1	41	Surface Water Collection System	ongoing																																
M - 4.3.1	42	Surface Water Quality Monitoring	ongoing																																
M - 4.3.1	43	Sediment Basin Maintenance	ongoing																														✓	С	I-i
M - 4.3.1	44	Final Landfill Cover	ongoing																																
M - 4.3.1	45	Erosion Control Plan	ongoing	✓	С	I-a																											✓	С	I-i
M - 4.3.1	46	Preventive Maintenance Program	ongoing	√ F	FRN	I-a																											✓	С	I-i
M - 4.3.2	49	Interception of Groundwater Seepage	ongoing	✓ F	FRN	I-a																											√	С	I-i
M - 4.3.2	50	LCRS/Leachate Monitoring	ongoing																																
M - 4.3.2	51	LCRS Monitoring	ongoing																																
																													$oldsymbol{\bot}$						

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

									Fire		arter					I						•	Second	d Qua	rter	,					
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved* 2/5/2014	Status*	Further Review Needed/Comments**	Resolved* 2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review Needed/Comments**	Resolved*	4/2/2014 Status*	Further Review Needed/Comments**	Resolved* 4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014 Status*	Further Review Needed/Comments**	Resolved*	6/11/2014 Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review	Resolved*
Biologist																															
	_																														
M - 4.1.1	6	Slope Erosion Control	ongoing	✓	FRN	I-a	✓	FRN	I-b	~	FRN	I-c		✓ FRN	I-d		✓ FRN	I-e	✓	FRN	I-f		✓ FRN	I-g		✓ FRN	I-h		✓ FRN	I-i	
M - 4.2.11	23	Revegetation/Excavation	ongoing	✓	FRN	I-a	✓	FRN	I-b	~	FRN	I-c		✓ FRN	I-d		✓ FRN	I-e	✓	FRN	I-f		✓ FRN	I-g		✓ FRN	I-h		✓ FRN	I-i	\perp
M - 4.2.12		Temporary Vegetation Cover Coastal Sage Scrub Mitigation	ongoing	✓	FRN	I-a	✓	FRN	I-b	~	FRN	I-c		✓ FRN	I-d		✓ FRN	I-e	✓	FRN	I-f		✓ FRN	I-g		✓ FRN	I-h		✓ FRN	I-i	
M - 4.4.1		Plan	ongoing	✓	С	I-a	✓	С	I-b					✓ C	I-d		✓ FRN	I-e	✓	FRN	I-f		✓ FRN	I-g		✓ FRN	I-h		✓ FRN	l I-i	
M - 4.4.1	61	Coastal Sage Scrub Seeding	ongoing																												
M - 4.4.1	62	Mariposa Lily Mitigation Plan San Diego Horned Lizard	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.1	63	Mitigation	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.1	64	California Gnatcatcher Surveys	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.1	65	Least Bell's Vireo Surveys	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.1	66	Western Burrowing Owl Surveys	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.1	67	Migratory Bird Treaty Act	ongoing	/			/			/				✓ C	I-d		/		/				✓ C	I-g		/			/		
M - 4.4.1	68	Raptor Nests Habitat	ongoing	/			/			/							/		/				/			/			/		
M - 4.4.3	72	Native Tree Mitigation	ongoing														✓ C	I-e	✓	С	NONE		✓ C	NONE		✓ C	NONE		✓ C	NON	E
M - 4.4.3	73	Nonnative Tree Mitigation	status														✓ C	NONE	✓		NONE		✓ C	NONE		✓ C	NONE		√ C	NONI	
M - 4.4.3	74	Mitigation Tree Planting	ongoing														✓ C	NONE	✓	С	NONE		✓ C	NONE		✓ C	NONE		√ C	NONI	E
M - 4.4.3	75	Tree Planting Mitigation Site Prep	ongoing														✓ C	I-e	✓	С	NONE		✓ C	NONE		✓ C	NONE		√ C	NONI	E
M - 4.4.3	76	Poultry Wire Screen	ongoing														✓ C	NONE	✓	С	NONE		✓ C	NONE		✓ C	NONE		√ C	NONI	E
M - 4.4.3	77	Backfill Material	ongoing														✓ C	NONE	✓		NONE		✓ C	NONE		✓ C	NONE		√ C	NONI	
M - 4.4.3	78	Tree Planting Procedure	ongoing														√ C	I-e	✓		NONE		√ C	NONE		√ C	NONE		√ C	NONI	
M - 4.4.3	79	Tree Area Mulching	ongoing														√ C	NONE	✓		NONE		√ C	NONE		√ C	NONE		√ C	NONI	

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

	# Conditions Monitored by Discipline # Review and Comments ** 114 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4																			-	Seco	nd (Quai	ter							\neg					
Reference#	Mitigation #	Conditions Monitored by	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**				ruriner Review Needed/Comments**		Status*	Further Review	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
M - 4.4.3	80	Tree Irrigation/Fertilization	ongoing																√	С	NONE		C	NONE		√ (ONE	,	C	NON	E	✓	С	NONE	
M - 4.4.3	81	Irrigation System	ongoing																																	
M - 4.4.3	82	Annual Tree Monitoring Report	annual																																	
M - 4.9.2	96	Vector Activity Monitoring	ongoing																																	
M - 4.9.2	97	Vector Elimination	ongoing																																	
M - 4.9.2	98	Fly Control	ongoing																																	
M - 4.9.2	99	Rodent Control	ongoing																																	
M - 4.9.2	100	ACTIVITY	ongoing																																	
M - 4.9.2	101	Equipment Cleanliness/Maintenance	ongoing																																	
M - 4.9.2	102	items	ongoing																																	
M - 4.9.2	103	Salvaged Material Storage- Vector Control	ongoing	✓	С	NONE													✓	С	NONE								,	C	NON	E				
M - 4.9.2	104	Periodic vector inspections	ongoing																																	
M - 4.9.2	105	Implementation of Vector Control Measures	ongoing																																	
Air Quality	& No	l ise Specialist																																		
															H																					
M - 4.2.11	19	Emissions Mitigation Measures	ongoing	√	С	NONE		√ (C N	IONE		√ C	NONE	:	√	С	NONE		√	С	NONE	,	C	NONE		√ (C N	ONE	,	C	NON	E	✓	С	NONE	
M - 4.2.11	19	Construction Curtailing due to Pollution	ongoing	/	NA	NONE		/ N	IA N	NONE		/ NA	NONE	:	/	NA	NONE		/	NA	NONE	/	′ NA	NONE		/ N	A N	ONE	,	/ NA	NON	E	/	NA	NONE	
M - 4.2.11	20	Dust Lofting Minimization	ongoing	✓	FRN	I-a						✓ FRN	I-c						✓	С	I-e	v	C	I-f		✓ ()	I-g	,	C	I-h		✓	С	I-i	
M - 4.2.11	21	Wind Speed Monitoring	ongoing	√	С	NONE		√ (C N	NONE		✓ C	NONE		✓	С	NONE		✓	С	NONE	v	C	NONE		✓ (C N	ONE		C	NON	E	✓	С	NONE	
M - 4.2.11	22	Grading-Dust Reduction	ongoing	✓	С	NONE		√ (C N	NONE		✓ C	NONE		✓	С	NONE		√	С	NONE	v	C	NONE		✓ (C N	ONE		C	NON	E	✓	С	NONE	
M - 4.2.12	24	Construction Equipment Maintenance	ongoing	√	С	NONE		✓ (C N	IONE		✓ C	NONE		√	С	NONE		✓	С	NONE	v	C	NONE		✓ (C N	ONE	,	/ C	NONI	E	✓	С	NONE	

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

									Fir		ıarte			•	9 00		I						5	ecor	ıd Qu	arte	r						
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status* Further Review	Needed/Comments**	2/5/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014 Status*	Further Review Needed/Comments**	Resolved*	5/7/2014 Status*	Further Review	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review	Needed/Comments** Resolved*
M - 4.2.12		Construction Curtailing due to Pollution	ongoing	/ N	IA NO	ONE	/	NA	NONE		/ NA			/ NA			/	NA	NONE	/	/ NA			/ NA			/	NA	NONE		/ N		
M - 4.2.12	25	Refuse Trucks-Maintenance	ongoing																														
M - 4.2.12		Refuse Trucks-Engine	ongoing																														
M - 4.2.12		Refuse Trucks-Fee Schedule	ongoing																														
M - 4.2.12		Refuse Trucks-Fee Schedule Delivery Time	ongoing																														
M - 4.2.12		Refuse Trucks-Idling	ongoing																														
M - 4.2.12		Refuse Trucks-Emissions	ongoing																														
M - 4.2.12	26	Truck Travel and Fugitive Dust Emissions	ongoing																														
M - 4.2.12		Truck Travel and Fugitive Dust Emissions	ongoing																														
M - 4.2.12		Truck Travel and Fugitive Dust Emissions	ongoing																														
M - 4.2.12		Truck Travel and Fugitive Dust Emissions	ongoing																														
M - 4.5.2	83	Landfill Hours	info	/			/				/			/			/			/	/			/			/				/		
M - 4.5.2	84	Landfill Equipment-Noise Reduction	ongoing	✓	C NO	ONE	✓	С	NONE		✓ C	NONE		✓ C	NONE		✓	С	NONE	,	✓ C	NONE		✓ C	NON		✓	С	NONE		✓ C	NOI	NE
Hydrology	, Haza	rdous Waste / Risk of Upset																													İ		
M - 4.3.2	53	Groundwater Monitoring Wells	ongoing																														
M - 4.3.2	58	Operation as Class III Landfill	ongoing	✓ ·	C NC	ONE	√	С	NONE		✓ C	NONE		✓ C	NONE		✓	С	NONE	,	v c	NONE		✓ C	NONI	=	✓	С	NONE		√ C	C NOI	NE
M - 4.3.2	59	Underground Fuel Storage	ongoing	/ N	IA NO	ONE	/	NA	NONE		/ NA	NONE		/ NA	NONE		/	NA	NONE	/	/ NA	NONE		/ NA	NONI	Ξ	/	NA	NONE		/ N	A NOI	NE
M - 4.9.1	90	Refuse Inspection Program	ongoing																														
M - 4.9.1	91	Hazardous Waste Load- Checking	status																														
M - 4.9.1	93	Hazardous Waste Detection Training	status								✓ C	NONE																					

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

			ns Monitored by Discipline Status																				;	Secor	ıd Qı	uarte	er						
Reference #	Mitigation #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved* 2/5/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved* 4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014 Status*	Further Review	Needed/Comments**	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review Needed/Comments**	Resolved*
M - 4.9.1	94	Spill Response Program	status							~	C	NONE																					
M - 4.9.4	115	Safety Inspections/Checklists	ongoing							~	C	NONE																					
M - 4.9.4	118	Accident/Injury reports, Inspections	status							~	C	NONE																					
M - 4.9.4	121	Fire Prevention Plan	ongoing	√ F	RN	I-a				~	FRI			C	I-d		✓	С	I-e														
M - 4.9.4	123	Personal Protective Equipment	ongoing							~	C	NONE																					
M - 4.9.4	125	Site Access/Fencing	ongoing	✓ F	RN	I-a				~		I-c		FRN	I-d					~	FRN	I-f											
M - 4.14.1	147	Fire Response Capabilities	ongoing							~	C	NONE																					
M - 4.14.1	148		ongoing																												$oxed{oxed}$		\prod
Archaeolo	gist																																
M - 4.19.1	183	Archaeological Resurvey	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE		FRN	I-d		✓	С	I-e								✓	С	I-h				
M - 4.19.1	184	Onsite Archaeologist	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE					✓	С	NONE	~	C	NONE		✓ C	NO	NE	✓	С	NONE		✓ C	NONE	Ε
M - 4.19.1	185	Archaeological Resources	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE					/	NA	NONE	/	NA	NONE		/ NA	NO	NE	/	NA	NONE		/ NA	NONE	Ε
M - 4.19.1	186	Archaeological Resources	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE					/	NA	NONE	/	NA NA	NONE		/ NA	NO	NE	/	NA	NONE		/ NA	NONE	Ε
Paleontolo	gist																														+	1	$\dagger \dagger$
M - 4.19.2	187	Paleontological Resources Resurvey	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE		FRN	I-d		√	С	I-e								√	С	I-h				
M - 4.19.2	188	Paleontological Resources Excavation	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE					/	NA	NONE	/	NA NA	NONE		/ NA	NO	NE	/	NA	NONE		/ NA	NONE	Ε
M - 4.19.2	189	Paleontological Resources Training	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE					✓	С	NONE	~	C	NONE		✓ C	NO	NE	✓	С	NONE		✓ C	NONE	Ε
M - 4.19.2	190	Paleontological Resources Recovery	ongoing	/	NA N	NONE	/	NA	NONE	/	NA	NONE																					

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

							Firs	t Qua	rter													S	econ	d Q	uart	er						
Reference #	City Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/13/2014 Status*	Further Review Needed/Comments**	Resolved* 2/5/2014	Status*	Further Review Needed/Comments**	Resolved* 2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014 Status*	Further Review	Needed/Comments**	AI2I2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014 Status*	Further Review	Needed/Comments**	Kesolved 6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014 Status*	Further Review	Needed/Comments** Resolved*
M - 4.19.	2 191 Paleontological Resources Inspection	ongoing	/ NA	NONE	/	NA	NONE	/	NA	NONE					~	FRN	I-e		✓ F	RN	I-f		✓ FRI	N I-	g	~	FRN	I-h		✓ FR	N I-	i

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

				I					Fir	st Q	ua		,,,,,			0		1								Ç	Sec	ond	Qua	rter	-							\neg
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	*-	_		Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Project Manager																																						
							_																															4
Amendment 45.N	45N	Daily Cover Materials	ongoing	✓	С	NONE	,	/ C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Amendment 45.N - 3	45N	Daily Cover Procedure	ongoing	✓	С	NONE	,	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Amendment 45.N 4.a	45N	Order for Abatement Status	ongoing	/		I-a	,		I-b		/		I-c		/		I-d		/		I-e		/		I-f		/		I-g		/		I-h		/		I-i	
Amendment 45.N 4.c	45N	Odor Patrol Program	ongoing	/		I-a	,	/ FRN	I-b		/		I-c		/		I-d		/		I-e		/		I-f		/		I-g		/		I-h		/		I-i	
Amendment 45.N -	45N	Landfill Gas Mitigation Plan	ongoing	/		I-a	,		I-b		/		I-c		/		I-d		/		I-e		/		I-f		/		I-g		/		I-h		/		I-i	
Amendment 45.N - 5	45N	Dust and Odor Reports	ongoing	/		I-a	,		I-b		/		I-c		/		I-d		/		I-e		/		I-f		/		I-g		/		I-h		/		I-i	
Combined Site & Bridge Area -20.A Combined Site &	20. A 20.	Joint Powers Authority Mitigation Reporting and	info	/			,				/				/				/				/				/				/				/			1
Bridge Area -20.F Landfill Capacity -	F 27	Monitoring Program Tipping Fees for Partial	status	/			/				/				/				/				/				/				/				/		\dashv	4
Grading & Drainage-41.AD	41A-	Loads/Peak Hours Water Conservation	status	✓	С	NONE	,	C	NONE		√	С	NONE		√	С	NONE		√	С	NONE		✓	С	NONE		√	С	NONE		√	С	NONE		√	С	NONE	\exists
Revegetation - 44.F	44. F	Revegetation	status	√	FRN	I-a	,	FRN	I-b		✓	FRN	I-c		✓	FRN	I-d						✓ F	FRN	I-f		√ F	FRN	I-g		✓	FRN	I-h		✓	С	I-i	
Fugitive Dust - 45.B	45. B	Working Face Areas	ongoing	✓	С	NONE	,	/ C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Fugitive Dust - 45.F	45. F	Inactive Areas Monitoring	ongoing	✓	FRN	I-a	,	FRN	I-b		✓	FRN	I-c		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Fugitive Dust - 45.I	45.I	Cleaning of Roads	ongoing	✓	С	NONE	,	/ C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Litter Control - 46.AD	46A- D	Litter Control Program	ongoing	✓	С	NONE	,	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Gas - 52	52	Landfill Gas Collection System	ongoing	✓	С	I-a					√	С	I-c														✓	С	I-g						✓	С	I-g	
Traffic - 57	57	Traffic Improvements	status	✓	С	NONE	,	/ C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Traffic - 60	60	Street Light Installation	status	✓	С	NONE	,	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Traffic - 61	61	Traffic Minimization	ongoing	✓	С	NONE	,	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				ı						`						8	70-5			/								al Out	o ret -	-						
			5							irst	Qua	arter				- 1										Si	econ	d Qua		r						
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Z/5/ZU14 Status*	Further Review	Needed/Comments** Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status* Further Review	Needed/Comments**	Resolved*	Status*	Further Review	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments** Resolved*
Permittee Fees - 64 - 72	64- 72	Permittee Fees	info	/				/			/				/				/				/			/				/				/		
Permittee Fees -	69	Permittee Fees-Contributions	info	,				/			,				/				/				/			/				/				/		
Permittee Fees - 70	70	Permittee Fees	info	/				/			/				/				/				/			/				/				/		
Permittee Fees - 72	72	Permittee Fees	info	/				/			/				/				/				/			/				/				/		
Alternative Fuel Vehicles - 77.A		Alternative Fuel Vehicles-Light Duty	status	✓	С	NONE		✓ C	NO	NE	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	C NO	ONE	v	/ C	NONI	E	√	С	NONE		✓	С	NONE
Alternative Fuel Vehicles - 77.B	В	Alternative Fuel Vehicles- Refuse/Collection Trucks	status	✓	С	NONE		✓ C	NO	NE	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	C NO	ONE	,	/ C	NONI	E	√	С	NONE		✓	С	NONE
Alternative Fuel Vehicles - 77.C	С	Alternative Fuel Vehicles- Report	status	Ц																																\perp
Alternative Fuel Vehicles - 77.D Alternative Fuel	D	Alternative Fuel Vehicles- heavy-duty, alternative fuel off- Alternative Fuel Vehicles-Non-	status																																	
Vehicles - 77.E Alternative Fuel	Ε	diesel Requirements Alternative Fuel Vehicles-Non-	status																_																	
Vehicles - 77.F Alternative Fuel	F	diesel Truck Trip Alternative Fuel Vehicles-	status					+											_																	
Vehicles - 77.G		Clean Fuel Demo Program	status																																	
Alternative Fuel Vehicles - 77.H		Alternative Fuel Vehicles- Compliance Evaluation	status																																	
Air Quality Monitoring - 81	81	Air Quality Monitoring-Testing	ongoing	/				/			/				/																					
	IMP	Air Quality Monitoring-Testing																																		\bot
IMP - Part IA		Air Quality Monitoring-Testing	ongoing	/				/			/				/				/				/			/				/				/		\perp
	IMP	Air Quality Monitoring-Testing						-		\perp									_								-		-							\perp
IMP - Part VI		Air Quality Monitoring-Testing	ongoing	/				/			/				/				/				/			/				/				/		
MMRS-12/01/06		Mitigation Monitoring and Reporting Summary	info	/				/			/				/				/				/			/				/				/		
		Permits																																		
Geology - 1.15		Permittee's On-site Solid Waste Recovery and	status	/				/			/				/				/				/			/				/				/		
Surface Water - 2.09		SWRCB Permit Coverage	ongoing	/				/			/				/				/				/			/				/				/		

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

			First Quarter Second Quarter Second Quarter																\neg																		
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**		2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	5/7/2014	Status*	Further Review Needed/Comments**	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Surface Water - 2.15		Surface Water Preventive Maintenance Program	ongoing	√	FRN																													/	FRN		
Groundwater - 3.13		Groundwater-LFG Migration Mitigation	ongoing	Ť	TIXIN	1-a																													TIXIN	1-1	
Groundwater - 3.14		Groundwater-Monitoring Wells	ongoing																																		
BIOTA – 4.05		Annual Fee Submission for SEA Studies	status	/				/				/				/				/				/			/			/				/			
BIOTA – 4.06		Buffer Zone Maintenance as Nature Preserve	ongoing	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	✓	С	NONE	✓	С	NONE		~	С	NONE	
BIOTA – 4.07		Buffer Zone Maintenance- Vegetation	ongoing	✓	С	NONE		✓	С	NONE		✓	С	NONE	:	✓	С	NONE		✓	С	NONE		✓	С	NONE	✓	С	NONE	✓	С	NONE		~	С	NONE	
BIOTA – 4.08		Ridgeline Maintenance- Remain Undisturbed	ongoing	√	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	✓	С	NONE	✓	С	NONE		~	С	NONE	
BIOTA – 4.47		Cleaning of Equipment	ongoing																																		
BIOTA – 4.48		Monitoring of Vector-Attracting Items	ongoing																																		
BIOTA – 4.49		Salvaged Material Storage- Vector Control	ongoing																	✓	С	NONE								✓	С	NONE					
BIOTA – 4.50		Vector Activity Monitoring	ongoing																																		
Air Quality - 6.03		Dust Emission Minimization	ongoing																																		
Air Quality - 6.04		Usage of Cut Material for Cover	ongoing	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	✓	С	NONE	✓	С	NONE		~	С	NONE	
Air Quality - 6.05		Operations in Accordance with SCAQMD/DOPW	info	/				/				/				/				/				/			/			/				/			
Air Quality - 6.06		Landfill Gas Control/Extraction System/Monitoring	ongoing	/				/				/				/				/				/			/			/				/			
Air Quality - 6.07		Flaring Systems	info	/				/				/				/				/				/			/			/				/			
Air Quality - 6.08		Management of Truck Arrivals	ongoing																																		
Air Quality - 6.10		Refuse Truck Mitigation	status																																		
Air Quality - 6.11		Light Duty Alternative Fuel Vehicles	status	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	✓	С	NONE	✓	С	NONE		√	С	NONE	
Air Quality - 6.11		Alternative Fuel Refuse Collection/Transfer Trucks	status																																		
Air Quality - 6.11		Alternative Fuel Vehicle Report Submission	status	Ц																																	
Air Quality - 6.11		Heavy-duty, Alternative Fuel Off-Road Equipment Pilot	status																																		

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

	First Quarter Second Quarter																0	000							,	Sec	CODO	ПОпа	rto	r								
			ıcy			*					,, ,	ua	i i CI	*				*				*				*		Jec	JUITC	* Qua	11 10	' 		*				*
Reference#	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**	Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments*	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**
Air Quality - 6.11		Non-Diesel, Alternative Fuel Vehicles-Transfer/Collection	status																																			
Air Quality - 6.11		Non-Diesel, Alternative Fuel VehiclesTruck Trips	status																																			
Air Quality - 6.11		Clean Fuel Demonstration Program	status																																			
Air Quality - 6.11		Compliance Evaluation	status																																			
Odor/Landfill Gas - 7.01		Landfill Gas Escape Prevention	ongoing	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	-	~	С	NONE
Odor/Landfill Gas – 7.02		Landfill Gas Collection System	ongoing	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		~	С	NONE		✓	С	NONE		✓	С	NONE	-	~	С	NONE
Odor/Landfill Gas - 7.04		Gas Collection/Flare System Risk Mitigation	ongoing																																			
Odor/Landfill Gas - 7.05		Wellhead Awareness	status	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Odor/Landfill Gas - 7.06		Odor Control Measures	ongoing					✓	FRN	I-b																												
Odor/Landfill Gas - 7.07		Gas Recovery and Sale	status	✓	С	I-a						✓	С	I-c														✓	С	I-g						✓	С	I-i
Traffic/Circulation – 8.03		Street Light Installation	status	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		/						/				/		✓	С	NONE	:	✓	С	NONE
Traffic/Circulation – 8.04		Truck Traffic Minimization	status																																			
Traffic/Circulation – 8.08		Tipping Fees for Partial Loads/Peak Hours	status																																			
Traffic/Circulation - 8.10		Nighttime Landfill Operations Feasibility	status	/				/				/				/				/				/				/				/				/		
Traffic/Circulation – 8.11		Parking Management along San Fernando Road	status	/				/				/				/				/				/				/				/				/		ightharpoonup
Traffic/Circulation - 8.13		Adequate Queuing	status	/				/				/				/																						ightharpoonup
Visual – 10.03		Landfill Flare Locations	status	/				/				/				/				/				/				/				/				/		\perp
Visual – 10.04		Confinement of Excavation Cover Material	status																																			
Visual – 10.05		Lighting Requirements	status																																			\perp
Visual – 10.11		Litter Control Program	ongoing																																			
Visual – 10.11		Solid Waste Load Procedures- Improperly Covered/Contained	ongoing																																			ightharpoonup
Visual – 10.11		Debris Removal at Entrance	ongoing	✓	FRN	I-a		✓	FRN	I-b		✓	FRN	I-c		✓	FRN	I-d		✓	FRN	I-e		✓	FRN	I-f						✓	FRN	I-h				

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

	- 1			ı												, 1	8	00-5			/							S = -	20:2	I O···-	rta	_							—
			cy							First	QU	art																Sec	cond	Qua									
Reference#	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**	Resolved	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Visual – 10.11		Litter Control-Fencing	ongoing																																				
Visual – 10.11		Periodic Litter Pickup	ongoing								,	/ F	RN	I-c		√	FRN	I-d						✓	FRN	I-f						✓	FRN	I-h					
Visual – 10.11		Litter Control-Additional Measures	ongoing																																				
Visual – 10.12		Discharge Control/Litter Recovery	status																																				
Water Conserv 11.01		Water Conservation	ongoing	✓	С	NONE		✓	С	NONE	,	/	C I	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Recycling - 14.01		On-site Waste Diversion/Recycling Tonnage Disposal	ongoing	√	С	NONE		✓	С	NONE	,	/	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Recycling - 14.03		Determination	info	/				/			,	/				/				/				/				/				/				/			
Recycling - 14.04		Recycling-Various Tasks	info	/				/			,	/				/				/				/				/				/				/			
		Clean Dirt Procedures																																					
Site - 15.11		Reclaimed Water Utilization	status																	/				/				/				/				/			
Site - 15.12		Water Conservation Measures	ongoing																	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Admin Rpts/Pgms - 17.4		Operation Compliance	info	/				/			,	/				/				/				/				/				/				/			
Admin Rpts/Pgms -17.10		Fill Sequencing Plans	status																																				
Admin Rpts/Pgms- 17.15 Landfill Operation -		Quarterly Newsletter Graffiti Removal/Deterrent	status																																				
18.7		Plan	ongoing	✓	С	NONE		✓	С	NONE	,	/	C I	NONE		✓	С	NONE						✓	FRN	I-f		✓	С	I-g		✓	С	NONE		✓	С	NONE	
Civil & Geotechnic	al Er	ngineer																																					
															4																					Ц			
Revegetation - 44.C	44. C	Cut Slope Requirements	ongoing																	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
Geology - 1.01		Survey Monument Locations	ongoing																																				
Geology - 1.02		Seismic Design	ongoing																									✓	FRN	I-g									

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

											•		rter															Sec	conc	l Qua	rte	r							\neg
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	*S	Further Review Needed/Comments**	Resolved*	114	×*	Further Review Needed/Comments**		/19/2014		Further Review	Resolved*	3/12/2014	*8	Further Review Needed/Comments**	Resolved*	114	*8	Further Review Needed/Comments**	Resolved*	1/16/2014	*s	Further Review Needed/Comments**				Further Review Needed/Comments**		/11/2014	*S	Further Review Needed/Comments**	Resolved*	5/24/2014	*>	Further Review Needed/Comments**	Resolved*
Refer	Mitiga		Monit	1/15/2	Status*	-urth	Sesol	2/5/2014	Status*	-urth	Resol	2/19/2	Status*	-urth	Resol	3/12/2	Status*	-urth	Sesol	1/2/2014	Status*	-urth	Resol	1/16/2	Status*	urth Veede	Resol	5/7/2014	Status*	-urth	Sesol	5/11/2	Status*	-urth	Resol	5/24/2	Status*	-urth	Resol
Geology - 1.03		Maximum Refuse Slope Gradients	ongoing																																				
Geology - 1.04		Maximum Refuse Slope Gradients	ongoing																																				
Geology - 1.05		Unsuitable Material Procedures	ongoing																																				
Geology - 1.06		Grading Activities Procedures	ongoing																																				
Geology - 1.07		Grading Activities Procedures	ongoing													✓	FRN	I-d										✓	FRN	I-g						✓	FRN	I-i	
Geology - 1.09		Outer Perimeter Ridgeline Requirements	info																																			<u> </u>	
Geology - 1.12		Soil Stabilization	ongoing																																				
Geology - 1.16		Checklists/Surveys Following Earthquake	upon event																					√	FRN	I-f													
Geology - 1.18		Alluvium- Removal/Replacement	ongoing																																				
Geology - 1.19		Landfill Design/Construction	ongoing																																				
Geology - 1.20		Landfill Design/Construction- Foundations	ongoing																																			<u> </u>	
Surface Water - 2.03		Surface Drainage Control Facilities	ongoing																																			<u> </u>	
Surface Water - 2.05		Underdrain Requirements	ongoing																																			<u> </u>	
Surface Water - 2.06		Final Cover for Surface Water Runoff Control	ongoing																																			<u> </u>	
Groundwater - 3.02		Liner System Requirements	ongoing																																			<u> </u>	
Groundwater - 3.04		Onsite Inspector for Liner Installation	ongoing																																			<u> </u>	
Groundwater - 3.09		Alluvium Removal	ongoing																																			<u> </u>	
Visual – 10.01		Landfill Elevations	ongoing																																			<u> </u>	
Visual – 10.02		Final Fill Elevations	ongoing																																			<u> </u>	
Hydrologist	<u> </u>																																						

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				Π						Firs							0	00 6		1							-	Sec	one	l Qua	rte	r							\neg
			ıcy			*					,, ,	ual	ıcı	¥				*				*				*		Jec				' 		*			ı	*	
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status	Further Review Needed/Comments**	Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Grading & Drainage - 38	38	Installation of Drainage Structures	ongoing																																				
Geology - 1.17		Landfill Design/Construction- Seismic	ongoing																																				
Surface Water - 2.01		Surface Water Runoff Interception	ongoing																															ł					
Surface Water - 2.02		Surface Water Runoff Collection	ongoing																																				
Surface Water - 2.03		Surface Drainage Control- Maintenance	ongoing													✓	FRN	I-d		√	FRN	I-e																	
Surface Water - 2- 04		Sedimentation Basin Capabilities	ongoing																																				
Surface Water - 2.05		Underdrain Placement	ongoing	✓	FRN	I-a																																	
Surface Water - 2.07		Drainage Control System Design Approval	ongoing																																				
Surface Water - 2.08		Surface Water Runoff- Drainage System	ongoing																																				
Surface Water - 2.10		Surface Water Collection System-Monitoring	ongoing																														ļ	<u> </u>					
Surface Water - 2.11		Surface Water Quality- Collection/Monitoring	ongoing																														ļ	<u> </u>					
Surface Water - 2.12		Permanent/Temporary Drainage Facilities	ongoing	✓	FRN	I-a																														√	FRN	I-i	
Surface Water - 2.13 Surface Water -		Permanent/Temporary Drainage Facilities	ongoing																															<u> </u>					
2.14 Groundwater -		Erosion Control Plan Interception of Groundwater	ongoing	✓	FRN	I-a																												<u> </u>		√	FRN	I-i	
3.03		Seepage	ongoing																															 					
Groundwater - 3.06		Monitoring Wells	ongoing																															<u> </u>					
Biologist	1																																						\dashv
		D 11' 10																																					
Revegetation - 44		Revegetation/Cover Requirements	ongoing																															<u> </u>					
Revegetation - 44.A	44. A	Temporary Hydroseed Vegetation	ongoing	✓	FRN	I-a		✓ FI	RN	I-b		✓	FRN	I-c		✓	FRN	I-d		✓	FRN	I-e		✓ F	FRN	I-f		✓	FRN	I-g		✓	FRN	I-h		√	FRN	I-i	

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				Ι							`		rter				-			Ι								Sec	ond	Qua	rter								\neg
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**		2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	*_	5/7/2014	Status*	Further Review Needed/Comments**		6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Revegetation - 44.B	44. B	Interim Reclamation/Revegetation	ongoing	✓	FRN	I-a		✓	FRN	I-b		✓	FRN	I-c		✓	FRN	I-d																					
Revegetation - 44.D	44. D	Final Fill Slope Requirements	ongoing																													✓	FRN	I-h					
Revegetation - 44.E	44. E	i signi signi si si	ongoing																														FRN	I-h					
																																H							
Geology - 1.13		Drainage Plan Approval Personnel Retention for	ongoing	✓	FRN	I-a		✓	FRN	I-b		✓	FRN	I-c	-	✓	FRN	I-d		✓	FRN	I-e		√ F	FRN	I-f		✓	FRN	I-g	<u> </u>	✓	FRN	I-h		✓	FRN	I-i	\perp
Geology - 1.14		Monitoring Soil Erosion Irrigation/Revegetation	ongoing	✓	FRN	I-a		✓	FRN	I-b		✓	FRN	I-c		✓	FRN	I-d		✓	FRN	I-e		√ F	FRN	I-f		✓	FRN	I-g	<u> </u>	✓	FRN	I-h		✓	FRN	I-i	Ш
Groundwater - 3.11		Management-Personnel	ongoing																												L	Ш				✓	FRN	I-i	
BIOTA – 4.10		Oak Tree Permit	ongoing																	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.11		Oak Tree Mitigation Plan	ongoing																	✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.13		Oak Tree Mitigation Counting	ongoing	✓	FRN	I-a										✓	С	I-d		✓	С	NONE		✓	С	NONE		✓	FRN	I-g		✓	С	NONE		✓	С	NONE	
BIOTA – 4.20		Poultry Wire Screen	ongoing																	✓	С	NONE		✓	С	NONE		✓	O	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.24		Drip Irrigation	ongoing																	✓	С	NONE		✓	С	NONE		✓	C	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.27		Coastal Sage Scrub Mitigation Plan	ongoing	✓	FRN	I-a		√	FRN	I-b						✓	FRN	I-d		√	FRN	I-e		✓ F	FRN	I-f		✓	FRN	I-g		~	FRN	I-h		✓	FRN	I-i	
BIOTA – 4.28		Coastal Sage Scrub Seeding	ongoing																																				
BIOTA – 4.29		San Diego Horned Lizard Mitigation	ongoing	✓	FRN	I-a														✓	FRN	I-e		✓ F	FRN	I-f		✓	FRN	I-g		✓	FRN	I-h		✓	FRN	I-i	
BIOTA – 4.30		California Gnatcatcher Surveys	ongoing	✓	FRN	I-a										✓	С	I-d		✓	С	NONE		√	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.31		Least Bell's Vireo Surveys	ongoing																	✓	С	NONE		√	С	NONE		√	С	NONE		✓	С	NONE		✓	С	NONE	
BIOTA – 4.32		Western Burrowing Owl Surveys	ongoing																	✓	С	NONE		√	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE	\prod
BIOTA – 4.33		Migratory Bird Treaty Act	ongoing	✓	FRN	I-a										✓	С	I-d		✓	С	NONE		√	С	NONE		✓	FRN	I-g		√	С	NONE		✓	С	NONE	\prod
BIOTA – 4.34		Raptor Nests Habitat	ongoing	✓	FRN	I-a										✓	С	I-d		✓	С	NONE			С	NONE		✓	С	NONE		√	С	NONE		~	С	NONE	
BIOTA – 4.36		Personnel Retention for	ongoing																													П							
BIOTA – 4.37		Personnel Retention for Monitoring Revegetation Plan,	status																																				
BIOTA – 4.38		Green Waste Material	ongoing																																				

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

										Firs							5										Sec	cond	d Qua	rte	r							\neg
Reference#	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**	*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	 5/7/2014	Status*	Further Review Needed/Comments**			Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
BIOTA – 4.39		Revegetation of Slopes/Fill Areas	ongoing																																			
BIOTA – 4.41		Revegetation Plan- Replacement Cover	ongoing																																		<u> </u>	
BIOTA – 4.42		Interim Vegetation	ongoing	✓	FRN	I-a		✓ F	RN	I-b		✓	FRN	I-c		✓	FRN	I-d		✓	FRN	I-e		✓	FRN	I-f	✓	FRN	I-g		✓	FRN	I-h		✓	FRN	I-i	
BIOTA – 4.43		Replacement Riparian Habitat	status																																		<u> </u>	
Air Quality - 6.02		Dust Control	ongoing	✓	FRN	I-a		✓ F	RN	I-b		✓	FRN	I-c		✓	С	NONE		✓	FRN	I-e		✓	FRN	I-f	✓	FRN	I-g		✓	FRN	I-h		✓	FRN	I-i	
Visual – 10.06		Upper Ridge Planting/Revegetation Tree Planting Around	ongoing																																		<u> </u>	
Visual – 10.07		Perimeter	ongoing																																		<u> </u>	
Visual – 10.08		Cover/Revegetation Requirements	ongoing																	✓	FRN	I-e		✓	FRN	I-f	✓	FRN	I-g		✓	FRN	I-h		✓	FRN	I-i	
Visual – 10.08		Solid Waste Disposal Procedures	ongoing																	✓	С	NONE		✓	С	NONE	✓	С	NONE		✓	С	NONE		✓	С	NONE	
Visual – 10.08		Final Cut Slope Steepness Final Fill Slopes-	ongoing																	✓	С	NONE		✓	С	NONE	✓	С	NONE	<u> </u>	✓	С	NONE	<u> </u>	✓	С	NONE	
Visual – 10.08		Reclamation/Revegetation	status																																		<u> </u>	
Visual – 10.08		Revegetation Requirements Final Cover Composition	status	✓	FRN	I-a		✓ F	RN	I-b		✓	FRN	I-c		✓	FRN	I-d																			<u> </u>	
Visual – 10.09		Requirements	ongoing																																		<u> </u>	
Visual – 10.10		Buffer Zone Maintenance	ongoing																																		<u> </u>	
Water Conservation - 11.02		Plant Species	ongoing																																			
Fire Service - 12.01		Brush Clearance Measures	ongoing																	✓	С	NONE		✓	С	NONE	✓	С	NONE		✓	С	NONE		✓	С	NONE	
Air Quality & Nois	se Spe	ecialist																																				
Fugitive Dust - 45.F	45. F	Fugitive Dust Monitoring	ongoing																																			
Fugitive Dust - 45.I	45.I	Paved Roads-Cleaning	ongoing	✓	С	NONE		✓	C I	NONE		✓	С	NONE		√	С	NONE		√	С	NONE		√	С	NONE	✓	С	NONE		√	С	NONE		√	С	NONE	
Fugitive Dust - 45.N	45. N	Report Submission-Dust/Odor	every quarter																																			

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				I					First					8-	1 00-5	<u> </u>		,						-	Sec	ond	l Qua	rtor	_						
			ıcy			*				Qu	ai tel								ž				*		عور	JI IU	± ±	i tel			ž				ž
Reference#	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	2/19/2014	Status*	Further Review Needed/Comments**	Resolved* 3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments*	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments** Resolved*
Air Quality Monitoring - 81	81	Air Quality Monitoring-Tests	ongoing																																
Air Quality – 6.01		Fugitive Dust Aversion	ongoing	√	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE		√	С	NONE		✓	С	NONE
Air Quality – 6.01		Working Face Requirements	ongoing	√	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE		✓	С	NONE
Air Quality – 6.01		Erosion Control-Daily Cover	ongoing	✓	С	NONE	~	C	NONE	~	С	NONE	✓	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE		✓	С	NONE
Air Quality – 6.01		Soil Stockpile Requirements	ongoing	✓	С	NONE	~	C	NONE	√	С	NONE	✓	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Active Area Fill	ongoing	✓	С	NONE	~	C	NONE	✓	С	NONE	✓	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE
Air Quality – 6.01		Soil Sealant	ongoing	√	FRN	I-a	~	FRN	I-b	✓	FRN	I-c	~	C	NONE		✓	FRN	I-e		√ [FRN	I-f		√ I	FRN	I-g		✓	FRN	I-h		✓ F	FRN	I-i
Air Quality – 6.01		Dust Emissions-Road Maintenance	ongoing	✓	С	NONE	~	C	NONE	✓	С	NONE	✓	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Access Roads-Paving	ongoing	✓	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Dust Generation-Dumping	ongoing	√	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Water Tanks/Piping Maintenance	ongoing	✓	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Wind Speed Monitoring	ongoing every	✓	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE
Air Quality – 6.01		Report Submission-Dust/Odor	quarter	/			/			/			/				/				/				/				/				/		
Odor/Landfill Gas – 7.03		Odor/Landfill Gas Monitoring Program	ongoing	/			/			/			/				/				/				/				,				/		
Odor/Landfill Gas - 7.03		Landfill Surface Sampling	ongoing	/			/			/			/				/				/				/				/				/		
Odor/Landfill Gas - 7.03		Landfill Perimeter Air Samples	ongoing	/			/			/			/				/				/				/				/				/		
Odor/Landfill Gas - 7.03		Landfill Surface Monitoring	ongoing	/			/			/			/				/				/				/				/				/		
Odor/Landfill Gas - 7.03		LFG Collection System Monitoring	ongoing	/						/							/				/				/				/				/		
Noise – 9.01		Landfill Access/Operation	info	/			/			/			/				/				/				/				/				/		
Noise – 9.03		Landfill Equipment- Mufflers/Silencers	ongoing	✓	С	NONE	~	C	NONE	✓	С	NONE	~	C	NONE		✓	С	NONE		✓	С	NONE		✓	С	NONE		√	С	NONE		✓	С	NONE

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				Ī							`		rter				-										Sec	cond	l Qua	rtei	_							\neg
Reference#	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	2/5/2014	Status*	Further Review Needed/Comments**		2/19/2014	Status*	Further Review	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	 5/7/2014	Status*	Further Review Needed/Comments**		6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Admin Rpts/ Pgms-17.16		Air Quality Monitoring- Corrective Action Plan	ongoing	/				/				,				/				/				/			,				/				,			
Hydrology, Hazar	dous	Waste / Risk of Upset																																			<u> </u>	Ш
IMP - Part IV.E	IMP 4	Load Inspection-Random Manual	ongoing																																			
Groundwater - 3.05		Leachate Collection and Removal System	ongoing																																			
Groundwater - 3.15		Underground Diesel Fuel Storage Tanks	ongoing	/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	/	NA	NONE		/	NA	NONE		/	NA	NONE	Ш
Fire Service - 12.02 Fire Service -		On-site Fire Response Capabilities-Operating On-site Fire Response	ongoing									✓	С	NONE	-					✓	С	NONE															<u> </u>	Ш
12.03		Capabilities-Roads/Water	ongoing	✓	FRN	I-a						✓	FRN	I-c		✓	С	I-d		✓	С	I-e		✓	FRN	I-f												Ш
Fire Service - 12.04		On-site Fuel Storage Tanks- Permit Issuance	ongoing																																		<u> </u>	
Fire Service - 12.05		Building Limits Methane Gas Monitoring-On-	ongoing																																		 	Ш
Fire Service - 12.06 Hazardous		site Structures Waste Load Checking	ongoing									✓	С	NON						✓	С	NONE															 	Ш
Materials – 13.02 Hazardous		Program	ongoing																																		 	Ш
Materials – 13.05 Hazardous		Hazardous Waste Disposal	ongoing									✓	С	NONE	-					✓	С	NONE													\sqcup			Ш
Materials – 13.10 Hazardous		Hazardous Waste-Procedures	ongoing									✓	С	NON	_	\sqcup																		-	\parallel			\sqcup
Materials - 13.11		Spill Response Program Injury and Illness Prevention	ongoing									✓	С	NON	-																			_	\sqcup			Ш
Safety - 16.02		Program Working Conditions-	status									✓	С	NON																					$\downarrow \downarrow$			\coprod
Safety - 16.03		Monitoring	status					Ц				✓	С	NON		$oxed{oxed}$															Щ				\sqcup		 	\coprod
Safety - 16.04		Inspection Checklist-Work Area Exposure	status									✓	С	NON																							 	Ш
Safety - 16.07		Accident/Injury Reports	status									✓	С	NONE																								

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

				_												9 '		- 1									_			_								—
			75	L.							ua	rter				1	ı			_							Sec	cond	Qua		r							
Reference #	Mitigation #	County Mitigation Measures and Conditions Monitored by Discipline	Monitoring Frequency	1/15/2014	Status*	Further Review Needed/Comments**	Resolved*	Status*	Further Review Needed/Comments**	Resolved*	2/19/2014	Status*	Further Review Needed/Comments**	Resolved*	3/12/2014	Status*	Further Review Needed/Comments**	Resolved*	4/2/2014	Status*	Further Review Needed/Comments**	Resolved*	4/16/2014	Status*	Further Review Needed/Comments**	Resolved*	5/7/2014	Status*	Further Review Needed/Comments**	Resolved*	6/11/2014	Status*	Further Review Needed/Comments**	Resolved*	6/24/2014	Status*	Further Review Needed/Comments**	Resolved*
Safety - 16.08		First-aid Kits	ongoing								✓	С	NONE																									
Safety - 16.10		Lockout/Blackout Procedures	status								✓	С	NONE																									
Safety - 16.11		Personal Protective Equipment	status								✓	С	NONE																									
Landfill Operation - 18.8		Prohibited Waste Procedures	ongoing								✓	С	NONE																									
				H																																	\vdash	\vdash
Archaeologist																																						Ш
																			_																			
Ecological Significance - 62	62	Archaeological/Paleontological Identification/Conservation	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		√ F	FRN	I-d		✓	С	I-e											С	I-h					
IMP - Part VII.B	IMP 7	Archaeological/Paleontological	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		/ 1	NA I	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	
Archaeological – 5.01		Archaeological Resurvey	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		/ 1	NA I	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	
Archaeological – 5.02		Onsite Archaeologist	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		/ 1	NA I	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	
Archaeological – 5.03		Onsite Paleontologist	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		✓ F	FRN	I-d		✓	С	I-e										✓	С	I-h					
Archaeological – 5.04		Archaeological/Paleontological Identification Instruction	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		/ 1	NA I	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	:	/	NA	NONE	
Archaeological – 5.05		Archaeological Resource Curat	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		/ 1	NA I	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE		/	NA	NONE	
Paleontologist																																						
		AbliUD-lk ! . ' . !																													L							
Ecological Significance - 62	62	Archaeological/Paleontological -Material Archaeological/Paleontological	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE		✓ F	FRN	I-d		✓	С	I-e											С	I-h					Щ
IMP - Part VII.B	IMP 7	Archaeological/Paleontological- Report Submission	ongoing	/	NA	NONE	,	NA	NONE		/	NA	NONE						✓	С	I-e										✓	С	I-h					

^{*} C = Compliant, NC = Non-Compliant, FRN = Further Review Needed, R = Resolved

^{**} See Appendix I for Comments

Checkmark = Condition or mitigation was monitored

^{/ =} Yearly or non-ongoing monitoring frequency

Appendix I

Further Review Needed-Comments I-e through I-i Second Quarter 2014 Site Visits

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Project Manager	Q – B.2.c		City Planning	I-e: The westside drainage ditch is being improved in the area below the old City South landfill. County Public Works was given plans for review.
				I-i: Portions of the westside V-ditch has been installed using concrete. County approval of the system of v-ditches now being installed is not known. This drainage system may not be the ultimate permanent system. Concrete foundations were being installed south of the offices along the new access road for the new temporary scale facilities.
	Q - C.5		City Planning	I-f: Graffiti was observed on the long downward sloping eastside concrete drainage channel that discharges into the terminal basin. This channel is visible from outside the landfill. Republic staff was procuring paint and scheduling removal.
				I-g: The graffiti observed on the prior monitoring visit on the eastside drainage channel was covered with paint.
		Landfill Operations - 18.7	County Planning	I-f and I-g: See Q - C.5 I-f and I-g above.
	Q - C.10.c		City Planning	I-g: The commissioning of individual systems was being done. On-line sales will follow sometime in July.
				I-i: An on-line test and power sales is scheduled for late July.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Project Manager		Odor/Landfill Gas - 7.07	County Planning/ SCAQMD SCL-LEA	I-g and I-i: See Q - C.10.c above.
		Gas - 52	County DPW EPD/SCL-LEA County Forester Fire Warden	I-g and I-i: See Q - C.10.c above.
	T -4		City Planning, City Fire Department	I-f: The City south top deck dirt road to the oil field road had some of the deep holes filled and high-center vehicles can use this as a secondary access Republic is considering improvements so that passenger cars could use this access in an emergency.
		Fire Service - 12.03	Dept. of Forester	I-f: See T - 4 above.
		Revegetation - 44 F	SCL-LEA/ County DPW EPD Regional Planning County Biologist	I-f through I-i: See M - 4.1.1/6 I-l below under Biologist Discipline.
		Alternative Fuel Vehicles - 77.D	County Planning, TAC	I-m: A status report should be prepared in the 4th Quarter on the use of alternative fuel for off-road equipment.
		Alternative Fuel Vehicles - 77.E	County Planning, TAC	I-m: A status report should be prepared in the 4th Quarter on the use of alternative fuel for transfer and collection trucks.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Project Manager	M -4.2.13/ 29, 32, 33, 34		City Planning/SCL- LEA/SCAQMD	I-e through I-i: Compliance with these mitigation measures concerning landfill gas monitoring and odor control and detection is being monitored by a multi-agency team led by the SCAQMD. Only obvious gas emission sources, lack of cover, or exposed trash resulting in odor and gas emissions observed during the monitoring visit will be reported. None of these were observed during the quarterly monitoring visits this period.
		Amendment 45.N - 4.a, 4.c, 4.d	County DPW-EPD	See M-4.2.13/29, 32, 33, and 34 above.
		Amendment 45.N - 5	County DPW-EPD	See M-4.2.13/29, 32, 33, and 34 above.
		Surface Water - 2.15	County DPW EPD/ LARWQCB, SCL- LEA	I-i: See M-4.3.1/46 below.
	M - 4.9.3/109, 110		City Planning	I-f: Illegal dumping was observed on Sierra Highway north of the I-14 overpass. The area appeared to have been cleaned of windblown litter by Republic.
				I-h: Illegal dumping was observed on Sierra Highway north of the I-14 overpass and on San Fernando Road south of the Old Road. All areas appeared to have been cleared of wind- blown litter.
		Visual - 10.11	SCL-LEA	I-f through I-h: see M - 4.9.3/109 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Project Manager	M - 4.9.3/112			I-e: Wind-blown litter was observed in the eastside drainage channel and on the back hillsides of Basins A and B. The terminal basin front exterior wall had wind-blown and illegally dumped debris.
				I-f and I-g: Wind-blown litter was observed on the back hillsides of Basin A and Basin B.
				I-h: Wind-blown litter was observed on the back hillsides of Basin A. The back hillsides of Basin B were cleared of litter.
		Visual - 10.11	SCL-LEA	I-e, I-f, and I-h: See M - 4.9.3/112 above.
Civil and Geotechnical Engineer	M - 4.1.1 / 2, 4, and 5		City Planning/ LARWQCB CalRecycle SCL-LEA LADBS PW-BOE	I-i: The excavation plans for the realignment access road has portions outside of the cut and fill footprint of the landfill. The plans should be provided to and approved by the City of Los Angeles Department of Building and Safety and the County Department of Public Works for those areas.
		Geology - 1.02	County DPW EPD/ County LEA	I-j: It is assumed by the monitor that a report and drawings for the access road realignment was provided to the County documenting that seismic design requirements are being met.
		Geology - 1.07	County DPW EPD/ County LEA	I-g: It is the monitor's understanding that in lieu of material removal, the stability buttress built was approved by the RWQCB as a remedial measure.
				I-i: See M - 4.1.1 / 2, 4 and 5 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Civil and Geotechnical Engineer	M - 4.1.4 / 11			I-f: The seismic detector/monitor recorder was relocated on a new concrete pad at the entrance near the recovered/recycled water facility. Upon evaluation of the equipment, Republic ordered a new, updated detector/recorder.
		Geology - 1.16	County DPW EPD/ County LEA	I-f: See M - 4.1.4 above.
Hydrologist	M-4.3.1/36		City Planning/ LARWQCB CalRecycle SCL-LEA PW-BOE	I-e: Ponding was observed on the road to Deck C, along the southern perimeter road, in the bottom of Cell CC-3A Part II, and on a couple of low spots on the County top deck. This was the result of the last rainstorm. Republic was scheduling crews to fix these areas.
		Surface Water - 2.03	County DPW EPD/ LARWQCB SCL-LEA	I-e: See M-4.3.1/36 above.
	M - 4.3.1/37, 38		City Planning/ LARWQCB CalRecycle SCL-LEA PW-BOE	I-i: Temporary and permanent drainage ditches have been installed to convey water to the basins. The majority of inactive and/or areas that have been disturbed have no temporary or permanent vegetation or other surface cover to retard erosion.
		Surface Water - 2.12	County DPW EPD/ LARWQCB SCL-LEA	I-i: See M - 4.3.1/ 38 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Hydrologist	M - 4.3.1/40, 45		City Planning/ LARWQCB CalRecycle SCL-LEA PW-BOE LADBS	I-i: A SWRCB plan was prepared and submitted to the water board for approval. The plan is being implemented and all control measures will be in place before October 15.
		Surface Water - 2.14	LARWQCB / County DPW EPD	I-i: See M - 4.3.1/40, 45 above.
	M - 4.3.1/43			I-i: Republic is in the process of removing sediment from Basins A, B, and the terminal basin. They are scheduled to be clear of sediment and ready for use before the rainy season.
	M - 4.3.1/ 46		City Planning/ LARWQCB CalRecycle PW-BOE	I-i: It was observed that along a portion of the west side drainage channel between Basin A and Basin D, the floor of the basin is uplifted in the middle with large cracks and weeds growing. This indicates the presence of moisture interacting with possible swelling soils. This was previously observed and noted. At the connection between the V-ditch feeding the channel, there is a gap between shotcrete and soil which is a conduit for water to infiltrate beneath the channel shotcrete into the subbase soil. Cracks mentioned in previous visits on the west side (native soil side) of the channel and eastside (landfill side) are getting worse with concrete spalling and pieces falling off.
		Surface Water - 2.15	LARWQCB / County DPW EPD	I-i: See M - 4.3.1/46 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Hydrologist	M - 4.3.1/49		City Planning/ LARWQCB CalRecycle PW-BOE	I-i: A large-diameter corrugated steel drain pipe that was unearthed in the City south soil stockpile in January was completely uncovered and the seep that was feeding this pipe was intercepted and eliminated.
				A smaller seep coming from around an abandoned gas pipeline on the slope was also intercepted and eliminated.
		Surface Water - 2.05	LARWQCB / County DPW EPD	I-i: See M - 4.3.1/49 above.
Biologist	M - 4.1.1 / 6		City Planning/ LARWQCB CalRecycle SCL-LEA LADBS	I-e: Hydroseeding of interim or inactive slopes is awaiting seed and soil conditioning supplies. I-f, g, h: Hydroseeding of interim or inactive slopes started in early April and were completed by the June 11 site monitoring. I-i: Due to the lack of rain and no irrigation, the hydroseeding did not germinate.
		Geology - 1.14	LARWQCB/ County Forester	I-e through I-i: See M - 4.1.1/6 above.
	M - 4.2.11 / 23		City Planning	I-e through I-i: See M - 4.1.1/6 above.
		Geology - 1.13	County DPW EPD/ County Forester LARWQCB	I-e through I-i: See M - 4.1.1/6 above.
	M - 4.2.12		SCL-LEA/ City Planning	I-e through I-i: See M - 4.1.1/6 above.
		Revegetation - 44.A	SCL-LEA/ County DPW EPD Regional Planning County Biologist	I-e through I-i: See M - 4.1.1/6 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Biologist		Revegetation - 44.D and 44.E	County Planning / DPW EPD	I-h: A revegetation plan should be part of the final toe berm design.
		Groundwater - 3.11	SCL-LEA/ County DPW EPD Regional Planning County Biologist	I-i: Due to the lack of rain and no irrigation, the hydroseeding did not germinate.
		Biota - 4.42	SCL-LEA	I-e through I-i: See M - 4.1.1/6 above.
		Air Quality - 6.02	SCAQMD/ SCL-LEA	I-e through I-i: See M - 4.1.1/6 above.
		Visual - 10.08	County Forester	I-e through I-i: See M - 4.1.1/6 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Biologist	M - 4.4.1 / 60		City Planning	I-e: The Deck C vegetation was getting established, with good plant coverage on the deck. Approximately 70-80% of the plants were salt bush. Black sage did not survive. Other native plants and sage were doing fair. I-f: The salt bush is growing faster and taller than other plants. Republic's biological consultant and vegetation contractor are monitoring the mitigation site. I-g: It was observed that the salt bush was providing cover for plants to grow in their understory. The area appeared to be overwatered for the sage and summer heat. I-h: The sage and other native plants were going through their summer die-back. The salt bush was growing and spreading. I-i: The area irrigation was cut back. Some salt bush was cut back to allow understory plants to grow. California Fish and Wildlife should be consulted to confirm the mitigation plants growing will meet the requirements of the sage mitigation for the agency.
		Biota - 4.27	SCL-LEA/CDFW	I-e, f, g, h, i: The County sage mitigation area had no revegetation activity by Republic occurring. The County sage area had some greening of vegetation and growth due to the rain in February and March.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Biologist		Biota - 4.29	SCL-LEA/CDFW County Biologist	I-e through I-i: Mitigation sites for the San Diego Horned Lizard will be included in the County and City Sage Mitigation.
	M-4.4.1/67		City Planning, SCL- LEA, CDFW	I-g: Observed the tree and vegetation removal along the landfill entrance road for the access road realignment. Numerous oak trees were removed along with some coastal sage vegetation. Biological monitoring was done by Republic before the start of tree and vegetation removal. The vegetation was previously evaluated, accounted for, and part of prior mitigation plans. Republic biological consultant stated that no additional biological assessment was required.
		Biota-4.13	County Planning	I-g: See M-4.4.1/67 above.
		Biota -4.33	County DPW, SCL- LEA, CDFW	I-g: See M-4.4.1/67 above.
Air Quality & Noise Specialist	M - 4.2.11/20		City Planning/ SCAQMD SCL-LEA LADBS	I-e, f, g, h, and i: Construction areas that become non-active and un-vegetated slopes should be evaluated for dust potential and soil sealant applied when required.


Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Air Quality & Noise Specialist		Air Quality - 6.01	County Planning	I-e through I-i: See M - 4.2.11/20 I-e through I-i above.
Hydrology, Hazardous Waste/ Risk of Upset	M - 4.9.4/121		City Planning/ CalRecycle Cal/OSHA SCL-LEA	I-e: Observed that the trees at the leachate treatment facility had been trimmed to clear the power lines.
	M-4.9.4/125	Fire Service - 12.03	Department of Forester/Fire Warden	I-e: See M - 4.9.4/121 above. I-f: The southern oil field perimeter gate was observed to be unlocked and standing open. I-f: The southern oil field perimeter gate was observed to be unlocked and standing open.
Archaeologist	M-4.19.1/183		City Planning	I-e: An archaeological survey was performed on the main access road realignment area. No items of concern were found. I-h: An archaeological survey was performed on the area west of the office facilities where site grading is being done. No items of concern were found. Archaeological reports are on file and are available in Republic's offices.
		Ecological Significance 62	County Planning	I-e and I-h: See M-4.19.1/183 above.

Discipline	City Condition Reference # / Mitigation #	County Condition Reference #/ Mitigation #	Responsible Agency	Further Review Needed-Comments
Paleontologist	M-4.19.2/187		City Planning	I-e: A paleontological survey was performed on the main access road realignment area. Minor non-recoverable marine fragments were observed and pieces saved for Republic. I-h: A paleontological survey was performed on the area where site grading is being done west of the landfill offices. Whale bone and other marine fragments were found. No items were recoverable in one piece. Paleontological reports are on file and are available in Republic's offices.
		Ecological Significance 62	County Planning	I-e and I-h: See M-4.19.2/187 above.
	M-4.19.2/190			I-h and I-i: A paleontological inspection was performed during grading operations. No items were recoverable except for marine bone fragments. Paleontological reports are on file and are available in Republic's offices.
		Archaeologist/ Paleontologist	County Planning	I-h and I-i: See M-4.19.2/190 above.

Appendix II

Relevant Site Photos

❖ Independent Monitor Quarter	ly Report �
[This page has intentionally been left blank]	



Service Layer Credits: National Geographic, Esri, DeLorme, HERE, UNEP-WCMC, USGS, NASA, ESA, METI, NRCAN, GEBCO, NOAA, increment P Corp., Los Angeles County, 2010; Republic, 2013; UltraSystems Environmental, Inc., 2014

	❖ Independent Monitor Quarterly Report ❖
[This page has intentionally been left blank	<i>X</i>]

Location Map – Photo Map Key

Location	Title	Photo Number
1.	Basin A	1-15
2.	Westside Drainage Channel	16-45
3.	Basin D	46-50
4.	Basin D North Drainage	51-57
5.	Materials Storage Area	58-67
6.	County Top Deck	160-195
7.	Flares 8-10	90-96
8.	Gas-to Energy Facility	68-89
9.	Flares 8-10 Adjacent Hillsides	103-109
10.	Basin B	112-124
11.	Eastside Drainage Channel	125-131
12.	Terminal Basin	132-153
13.	Wastewater Sewer Connection Facility	-
14.	Existing Access Road	196-207
15.	Access Road Realignment Area	208-273
16.	Leachate Treatment Facility	-
17.	New Truck Scale Facilities	-
18.	County Sage Mitigation	274-291
19.	Big Cone Fir Mitigation	-
20.	City Sage Mitigation - Deck A	359-360
21.	City Sage Mitigation - Deck B	357-358
22.	City Sage Mitigation - Deck C	292-356
23.	Cell CC-3A	379-385
24.	Cell CC-3A Buttress Area	-
25.	Site Working Area	421-447

	❖ Independent Monitor Quarterly Report ❖
This page has intentionally been left blank]	



Photo 1: Basin A: April 2, 2014



Photo 3: Basin A: April 2, 2014



Photo 2: Basin A: April 2, 2014



Photo 4: Basin A: April 2, 2014



Photo 5: Basin A: April 16, 2014



Photo 7: Basin A: May 7, 2014



Photo 6: Basin A: April 16, 2014



Photo 8: Basin A: May 7, 2014



Photo 9: Basin A: May 7, 2014



Photo 11: Basin A: June 11, 2014



Photo 10: Basin A: June 11, 2014



Photo 12: Basin A: June 11, 2014



Photo 13: Basin A: June 11, 2014



Photo 15: Adjacent to Basin A Inlet: April 2, 2014



Photo 14: Basin A Inlet: April 2, 2014



Photo 16: Westside Drainage Channel: April 2, 2014



Photo 17: Westside Drainage Channel: April 2, 2014



Photo 19: Westside Drainage Channel: April 2, 2014



Photo 18: Westside Drainage Channel: April 2, 2014



Photo 20: Westside Drainage Channel: April 2, 2014



Photo 21: Westside Drainage Channel: April 2, 2014



Photo 23: Westside Drainage Channel: April 2, 2014



Photo 22: Westside Drainage Channel: April 2, 2014



Photo 24: Westside Drainage Channel: May 7, 2014



Photo 25: Westside Drainage Channel: May 7, 2014



Photo 27: Westside Drainage Channel: May 7, 2014



Photo 26: Westside Drainage Channel: May 7, 2014



Photo 28: Westside Drainage Channel: May 7, 2014



Photo 29: Westside Drainage Channel: May 7, 2014



Photo 31: Westside Drainage Channel: June 11, 2014



Photo 30: Westside Drainage Channel: May 7, 2014



Photo 32: Westside Drainage Channel: June 11, 2014



Photo 33: Westside Drainage Channel: June 11, 2014



Photo 35: Westside Drainage Channel: June 11, 2014



Photo 34: Westside Drainage Channel: June 11, 2014



Photo 36: Westside Drainage Channel: June 11, 2014



Photo 37: Westside Drainage Channel: June 11, 2014



Photo 39: Westside Drainage Channel: June 24, 2014



Photo 38: Westside Drainage Channel: June 24, 2014



Photo 40: Westside Drainage Channel: June 24, 2014



Photo 41: Westside Drainage Channel: June 24, 2014



Photo 43: Westside Drainage Channel: June 24, 2014



Photo 42: Westside Drainage Channel: June 24, 2014



Photo 44: Westside Drainage Channel: June 24, 2014



Photo 45: Westside Drainage Channel: June 24, 2014



Photo 47: Basin D: April 2, 2014



Photo 46: Basin D: April 2, 2014



Photo 48: Basin D: April 2, 2014



Photo 49: Basin D: April 2, 2014



Photo 51: Basin D Outlet Channel: April 2, 2014



Photo 50: Basin D: April 2, 2014



Photo 52: Basin D Outlet Channel: April 2, 2014



Photo 53: Basin D Outlet Channel: April 2, 2014



Photo 55: Basin D Outlet Channel: April 2, 2014



Photo 54: Basin D Outlet Channel: April 2, 2014



Photo 56: Basin D Outlet Channel: May 7, 2014



Photo 57: Basin D Outlet Channel: May 7, 2014



Photo 59: Material Storage Area: May 7, 2014



Photo 58: Material Storage Area: May 7, 2014



Photo 60: Material Storage Area: May 7, 2014



Photo 61: Material Storage Area: May 7, 2014



Photo 63: Material Storage Area: May 7, 2014



Photo 62: Material Storage Area: May 7, 2014



Photo 64: Material Storage Area: June 11, 2014



Photo 65: Material Storage Area: June 11, 2014



Photo 67: Material Storage Area: June 11, 2014



Photo 66: Material Storage Area: June 11, 2014



Photo 68: Gas to Energy Facility: April 2, 2014



Photo 69: Gas to Energy Facility: April 2, 2014



Photo 71: Gas to Energy Facility: May 7, 2014



Photo 70: Gas to Energy Facility: April 2, 2014



Photo 72: Gas to Energy Facility: May 7, 2014



Photo 73: Gas to Energy Facility: May 7, 2014



Photo 75: Gas to Energy Facility: May 7, 2014



Photo 74: Gas to Energy Facility: May 7, 2014



Photo 76: Gas to Energy Facility: May 7, 2014



Photo 77: Gas to Energy Facility: May 7, 2014



Photo 79: Gas to Energy Facility: May 7, 2014



Photo 78: Gas to Energy Facility: May 7, 2014



Photo 80: Gas to Energy Facility: May 7, 2014



Photo 81: Gas to Energy Facility: May 7, 2014



Photo 83: Gas to Energy Facility: June 11, 2014



Photo 82: Gas to Energy Facility: June 11, 2014



Photo 84: Gas to Energy Facility: June 11, 2014



Photo 85: Gas to Energy Facility: June 11, 2014



Photo 87: Gas to Energy Facility: June 11, 2014



Photo 86: Gas to Energy Facility: June 11, 2014



Photo 88: Gas to Energy Facility: June 11, 2014



Photo 89: Gas to Energy Facility: June 11, 2014



Photo 91: Air Piping: April 2, 2014



Photo 90: Flare 9 & 10 Emergency Generators: April 2, 2014




Photo 92: Air Piping: June 11, 2014




Photo 93: Flare 9 Air Filter: June 11, 2014



Photo 95: Gas Can at Flare 10: June 11, 2014



Photo 94: Flare 10 Air Filter: June 11, 2014



Photo 96: Flare 10 Lighter Rod: June 11, 2014



Photo 97: Flare 8 Hill: May 7, 2014



Photo 99: Flare 8 Hill: May 7, 2014



Photo 98: Flare 8 Hill: May 7, 2014



Photo 100: Flare 8 Hill: May 7, 2014



Photo 101: Flare 8 Hill: May 7, 2014



Photo 103: Flare 9 & 10 Adjacent Slopes: May 7, 2014



Photo 102: Flare 8 Hill: May 7, 2014



Photo 104: Flare 9 & 10 Adjacent Slopes: May 7, 2014



Photo 105: Flare 9 & 10 Adjacent Slopes: June 11, 2014



Photo 107: Gas to Energy Adjacent Slopes: May 7, 2014



Photo 106: Gas to Energy Adjacent Slopes: May 7, 2014



Photo 108: Gas to Energy Adjacent Slopes: June 11, 2014



Photo 109: Gas to Energy Adjacent Slopes: June 11, 2014



Photo 111: Basin D Outlet Channel: April 2, 2014



Photo 110: Basin D Outlet Channel: April 2, 2014



Photo 112: Basin B Inlet: April 2, 2014



Photo 113: Basin B Inlet: May 7, 2014



Photo 115: Basin B: April 2, 2014



Photo 114: Basin B Inlet: June 11, 2014



Photo 116: Basin B: April 2, 2014



Photo 117: Basin B: April 2, 2014



Photo 119: Basin B: April 16, 2014



Photo 118: Basin B: April 2, 2014



Photo 120: Basin B: May 7, 2014



Photo 121: Basin B: May 7, 2014



Photo 123: Basin B: May 7, 2014



Photo 122: Basin B: May 7, 2014



Photo 124: Basin B: May 7, 2014



Photo 125: Eastside Drainage Channel: April 2, 2014



Photo 127: Eastside Drainage Channel: April 16, 2014



Photo 126: Eastside Drainage Channel: April 2, 2014



Photo 128: Eastside Drainage Channel: April 16, 2014



Photo 129: Eastside Drainage Channel: April 16, 2014



Photo 131: Eastside Drainage Channel: May 7, 2014



Photo 130: Eastside Drainage Channel: May 7, 2014



Photo 132: Terminal Basin: April 2, 2014



Photo 133: Terminal Basin: April 2, 2014



Photo 135: Terminal Basin: April 2, 2014



Photo 134: Terminal Basin: April 2, 2014



Photo 136: Terminal Basin: April 2, 2014



Photo 137: Terminal Basin: April 2, 2014



Photo 139: Terminal Basin: April 2, 2014



Photo 138: Terminal Basin: April 2, 2014



Photo 140: Terminal Basin: April 2, 2014



Photo 141: Terminal Basin: April 2, 2014



Photo 143: Terminal Basin: April 2, 2014



Photo 142: Terminal Basin: April 2, 2014



Photo 144: Terminal Basin: April 2, 2014



Photo 145: Terminal Basin: April 2, 2014



Photo 147: Terminal Basin: April 2, 2014



Photo 146: Terminal Basin: April 2, 2014



Photo 148: Terminal Basin: April 2, 2014



Photo 149: Terminal Basin: April 2, 2014



Photo 151: Terminal Basin: May 7, 2014



Photo 150: Terminal Basin: May 7, 2014



Photo 152: Terminal Basin: June 24, 2014



Photo 153: Terminal Basin: June 24, 2014



Photo 155: City Old North: April 2, 2014



Photo 154: City Old North: April 2, 2014



Photo 156: City Old North: May 7, 2014



Photo 157: City Old North: May 7, 2014



Photo 159: City Old North: June 24, 2014



Photo 158: City Old North: June 24, 2014



Photo 160: County Top Deck: April 2, 2014



Photo 161: County Top Deck: April 2, 2014



Photo 163: County Top Deck: April 2, 2014



Photo 162: County Top Deck: April 2, 2014



Photo 164: County Top Deck: April 2, 2014



Photo 165: County Top Deck: April 2, 2014



Photo 167: County Top Deck: April 2, 2014



Photo 166: County Top Deck: April 2, 2014



Photo 168: County Top Deck: April 2, 2014



Photo 169: County Top Deck: April 2, 2014



Photo 171: County Top Deck: April 16, 2014



Photo 170: County Top Deck: April 16, 2014



Photo 172: County Top Deck: April 16, 2014



Photo 173: County Top Deck: April 16, 2014



Photo 175: County Top Deck: April 16, 2014



Photo 174: County Top Deck: April 16, 2014



Photo 176: County Top Deck: April 16, 2014



Photo 177: County Top Deck: May 7, 2014



Photo 179: County Top Deck: May 7, 2014



Photo 178: County Top Deck: May 7, 2014



Photo 180: County Top Deck: May 7, 2014



Photo 181: County Top Deck: May 7, 2014



Photo 183: County Top Deck: May 7, 2014



Photo 182: County Top Deck: May 7, 2014



Photo 184: County Top Deck: June 11, 2014



Photo 185: County Top Deck: June 11, 2014



Photo 187: County Top Deck: June 11, 2014



Photo 186: County Top Deck: June 11, 2014



Photo 188: County Top Deck: June 11, 2014



Photo 189: County Top Deck: June 11, 2014



Photo 191: County Top Deck: June 11, 2014



Photo 190: County Top Deck: June 11, 2014



Photo 192: County Top Deck: June 11, 2014



Photo 193: County Top Deck: June 11, 2014



Photo 195: County Top Deck: June 11, 2014



Photo 194: County Top Deck: June 11, 2014



Photo 196: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 197: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 199: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 198: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 200: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 201: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 203: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 202: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 204: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 205: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 207: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 206: Access Road Drainage to Terminal Basin: April 2, 2014



Photo 208: Access Road Realignment Area: May 7, 2014



Photo 209: Access Road Realignment Area: May 7, 2014



Photo 211: Access Road Realignment Area: May 7, 2014



Photo 210: Access Road Realignment Area: May 7, 2014



Photo 212: Access Road Realignment Area: May 7, 2014



Photo 213: Access Road Realignment Area: May 7, 2014



Photo 215: Access Road Realignment Area: May 7, 2014



Photo 214: Access Road Realignment Area: May 7, 2014



Photo 216: Access Road Realignment Area: May 7, 2014



Photo 217: Access Road Realignment Area: May 7, 2014



Photo 219: Access Road Realignment Area: May 7, 2014




Photo 218: Access Road Realignment Area: May 7, 2014



Photo 220: Access Road Realignment Area: May 7, 2014



Photo 221: Access Road Realignment Area: May 7, 2014



Photo 223: Access Road Realignment Area: June 11, 2014



Photo 222: Access Road Realignment Area: June 11, 2014



Photo 224: Access Road Realignment Area: June 11, 2014



Photo 225: Access Road Realignment Area: June 11, 2014



Photo 227: Access Road Realignment Area: June 11, 2014



Photo 226: Access Road Realignment Area: June 11, 2014



Photo 228: Access Road Realignment Area: June 11, 2014



Photo 229: Access Road Realignment Area: June 11, 2014



Photo 231: Access Road Realignment Area: June 11, 2014



Photo 230: Access Road Realignment Area: June 11, 2014



Photo 232: Access Road Realignment Area: June 11, 2014



Photo 233: Access Road Realignment Area: June 11, 2014



Photo 235: Access Road Realignment Area: June 11, 2014



Photo 234: Access Road Realignment Area: June 11, 2014



Photo 236: Access Road Realignment Area: June 11, 2014



Photo 237: Access Road Realignment Area: June 24, 2014



Photo 239: Access Road Realignment Area: June 24, 2014



Photo 238: Access Road Realignment Area: June 24, 2014



Photo 240: Access Road Realignment Area: June 24, 2014



Photo 241: Access Road Realignment Area: June 24, 2014



Photo 243: Access Road Realignment Area: June 24, 2014



Photo 242: Access Road Realignment Area: June 24, 2014



Photo 244: Access Road Realignment Area: June 24, 2014



Photo 245: Access Road Realignment Area: June 24, 2014



Photo 247: Access Road Realignment Area: June 24, 2014



Photo 246: Access Road Realignment Area: June 24, 2014



Photo 248: Access Road Realignment Area: June 24, 2014



Photo 249: Access Road Realignment Area: June 24, 2014



Photo 251: Access Road Realignment Area: June 24, 2014



Photo 250: Access Road Realignment Area: June 24, 2014



Photo 252: Access Road Realignment Area: June 24, 2014



Photo 253: Access Road Realignment Area: June 24, 2014



Photo 255: Access Road Realignment Area: June 24, 2014



Photo 254: Access Road Realignment Area: June 24, 2014



Photo 256: Access Road Realignment Area: June 24, 2014



Photo 257: Access Road Realignment Area: June 24, 2014



Photo 259: Access Road Realignment Area: June 24, 2014



Photo 258: Access Road Realignment Area: June 24, 2014



Photo 260: Access Road Realignment Area: June 24, 2014



Photo 261: Access Road Realignment Area: June 24, 2014



Photo 263: Access Road Realignment Area: June 24, 2014



Photo 262: Access Road Realignment Area: June 24, 2014



Photo 264: Access Road Realignment Area: June 24, 2014



Photo 265: Access Road Realignment Area: June 24, 2014



Photo 267: Access Road Realignment Area: June 24, 2014



Photo 266: Access Road Realignment Area: June 24, 2014



Photo 268: Access Road Realignment Area: June 24, 2014



Photo 269: Access Road Realignment Area: June 24, 2014



Photo 271: Access Road Realignment Area: June 24, 2014



Photo 270: Access Road Realignment Area: June 24, 2014



Photo 272: Access Road Realignment Area: June 24, 2014



Photo 273: Access Road Realignment Area: June 24, 2014



Photo 275: County Sage Mitigation Area: April 2, 2014



Photo 274: County Sage Mitigation Area: April 2, 2014



Photo 276: County Sage Mitigation Area: April 2, 2014



Photo 277: County Sage Mitigation Area: April 2, 2014



Photo 279: County Sage Mitigation Area: April 2, 2014



Photo 278: County Sage Mitigation Area: April 2, 2014



Photo 280: County Sage Mitigation Area: April 2, 2014



Photo 281: County Sage Mitigation Area: April 2, 2014



Photo 283: County Sage Mitigation Area: April 16, 2014



Photo 282: County Sage Mitigation Area: April 2, 2014



Photo 284: County Sage Mitigation Area: April 16, 2014



Photo 285: County Sage Mitigation Area: April 16, 2014



Photo 287: County Sage Mitigation Area: May 7, 2014



Photo 286: County Sage Mitigation Area: May 7, 2014



Photo 288: County Sage Mitigation Area: May 7, 2014



Photo 289: County Sage Mitigation Area: May 7, 2014



Photo 291: County Sage Mitigation Area: June 11, 2014



Photo 290: County Sage Mitigation Area: June 11, 2014



Photo 292: City Sage Mitigation Deck C: April 2, 2014



Photo 293: City Sage Mitigation Deck C: April 2, 2014



Photo 295: City Sage Mitigation Deck C: April 2, 2014



Photo 294: City Sage Mitigation Deck C: April 2, 2014



Photo 296: City Sage Mitigation Deck C: April 2, 2014



Photo 297: City Sage Mitigation Deck C: April 2, 2014



Photo 299: City Sage Mitigation Deck C: April 2, 2014



Photo 298: City Sage Mitigation Deck C: April 2, 2014



Photo 300: City Sage Mitigation Deck C: April 2, 2014



Photo 301: City Sage Mitigation Deck C: April 2, 2014



Photo 303: City Sage Mitigation Deck C: April 2, 2014



Photo 302: City Sage Mitigation Deck C: April 2, 2014



Photo 304: City Sage Mitigation Deck C: April 2, 2014



Photo 305: City Sage Mitigation Deck C: April 2, 2014



Photo 307: City Sage Mitigation Deck C: April 16, 2014



Photo 306: City Sage Mitigation Deck C: April 2, 2014



Photo 308: City Sage Mitigation Deck C: April 16, 2014



Photo 309: City Sage Mitigation Deck C: April 16, 2014



Photo 311: City Sage Mitigation Deck C: April 16, 2014



Photo 310: City Sage Mitigation Deck C: April 16, 2014



Photo 312: City Sage Mitigation Deck C: April 16, 2014



Photo 313: City Sage Mitigation Deck C: April 16, 2014



Photo 315: City Sage Mitigation Deck C: April 16, 2014



Photo 314: City Sage Mitigation Deck C: April 16, 2014



Photo 316: City Sage Mitigation Deck C: April 16, 2014



Photo 317: City Sage Mitigation Deck C: April 16, 2014



Photo 319: City Sage Mitigation Deck C: April 16, 2014



Photo 318: City Sage Mitigation Deck C: April 16, 2014



Photo 320: City Sage Mitigation Deck C: April 16, 2014



Photo 321: City Sage Mitigation Deck C: April 16, 2014



Photo 323: City Sage Mitigation Deck C: April 16, 2014



Photo 322: City Sage Mitigation Deck C: April 16, 2014



Photo 324: City Sage Mitigation Deck C: April 16, 2014



Photo 325: City Sage Mitigation Deck C: May 7, 2014



Photo 327: City Sage Mitigation Deck C: May 7, 2014



Photo 326: City Sage Mitigation Deck C: May 7, 2014



Photo 328: City Sage Mitigation Deck C: May 7, 2014



Photo 329: City Sage Mitigation Deck C: May 7, 2014



Photo 331: City Sage Mitigation Deck C: May 7, 2014



Photo 330: City Sage Mitigation Deck C: May 7, 2014



Photo 332: City Sage Mitigation Deck C: May 7, 2014



Photo 333: City Sage Mitigation Deck C: May 7, 2014



Photo 335: City Sage Mitigation Deck C: May 7, 2014



Photo 334: City Sage Mitigation Deck C: May 7, 2014



Photo 336: City Sage Mitigation Deck C: May 7, 2014



Photo 337: City Sage Mitigation Deck C: May 7, 2014



Photo 339: City Sage Mitigation Deck C: May 7, 2014



Photo 338: City Sage Mitigation Deck C: May 7, 2014



Photo 340: City Sage Mitigation Deck C: May 7, 2014



Photo 341: City Sage Mitigation Deck C: May 7, 2014



Photo 343: City Sage Mitigation Deck C: May 7, 2014



Photo 342: City Sage Mitigation Deck C: May 7, 2014



Photo 344: City Sage Mitigation Deck C: May 7, 2014



Photo 345: City Sage Mitigation Deck C: June 11, 2014



Photo 347: City Sage Mitigation Deck C: June 24, 2014



Photo 346: City Sage Mitigation Deck C: June 11, 2014



Photo 348: City Sage Mitigation Deck C: June 24, 2014



Photo 349: City Sage Mitigation Deck C: June 24, 2014



Photo 351: City Sage Mitigation Deck C: June 24, 2014



Photo 350: City Sage Mitigation Deck C: June 24, 2014



Photo 352: City Sage Mitigation Deck C: June 24, 2014



Photo 353: City Sage Mitigation Deck C: June 24, 2014



Photo 355: City Sage Mitigation Deck C: June 24, 2014



Photo 354: City Sage Mitigation Deck C: June 24, 2014



Photo 356: City Sage Mitigation Deck C: June 24, 2014



Photo 357: City Sage Mitigation Deck B: May 7, 2014



Photo 359: City Sage Mitigation Deck A: June 11, 2014



Photo 358: City Sage Mitigation Deck B: May 7, 2014



Photo 360: City Sage Mitigation Deck A: June 11, 2014



Photo 361: Site Hydroseeding: April 16, 2014



Photo 363: Site Hydroseeding: April 16, 2014



Photo 362: Site Hydroseeding: April 16, 2014



Photo 364: Site Hydroseeding: April 16, 2014



Photo 365: Site Hydroseeding: April 16, 2014



Photo 367: Site Hydroseeding: April 16, 2014




Photo 366: Site Hydroseeding: April 16, 2014



Photo 368: Site Hydroseeding: April 16, 2014




Photo 369: Site Hydroseeding: April 16, 2014



Photo 371: Site Hydroseeding: April 16, 2014



Photo 370: Site Hydroseeding: April 16, 2014



Photo 372: Site Hydroseeding: April 16, 2014



Photo 373: Site Hydroseeding: April 16, 2014



Photo 375: Site Hydroseeding: June 11, 2014



Photo 374: Site Hydroseeding: June 11, 2014



Photo 376: Site Hydroseeding: June 11, 2014



Photo 377: Site Hydroseeding: June 11, 2014



Photo 379: Cell CC3A Part II Drainage: April 2, 2014



Photo 378: Site Hydroseeding: June 11, 2014



Photo 380: Cell CC3A Part II Drainage: April 2, 2014



Photo 381: Cell CC3A Part II Drainage: April 2, 2014



Photo 383: Cell CC3A Part II Drainage: April 2, 2014



Photo 382: Cell CC3A Part II Drainage: April 2, 2014



Photo 384: Cell CC3A Part II Drainage: April 2, 2014



Photo 385: Cell CC3A Part II Drainage: April 2, 2014



Photo 387: Drainage along South Perimeter Road: April 2, 2014



Photo 386: City Stockpile Buried Drainage Pipe: April 2, 2014



Photo 388: Access Road Drainage Improvements: June 24, 2014



Photo 389: Access Road Drainage Improvements: June 24, 2014



Photo 391: Access Road Drainage Improvements: June 24, 2014



Photo 390: Access Road Drainage Improvements: June 24, 2014



Photo 392: Access Road Drainage Improvements: June 24, 2014



Photo 393: Access Road Drainage Improvements: June 24, 2014



Photo 395: Standing Water along Road to Deck C: April 2, 2014



Photo 394: Standing Water along Road to Deck C: April 2, 2014



Photo 396: Standing Water along Road to Deck C: April 2, 2014



Photo 397: Flare 1: April 2, 2014



Photo 399: Flare 1: April 2, 2014



Photo 398: Flare 1: April 2, 2014



Photo 400: Flare 1: April 2, 2014



Photo 401: Flare 1: April 2, 2014



Photo 403: Flare 1: April 2, 2014



Photo 402: Flare 1: April 2, 2014



Photo 404: Flare 1: April 2, 2014



Photo 405: Flare 1: April 2, 2014



Photo 407: Flare 3: April 2, 2014



Photo 406: Flare 1: April 2, 2014



Photo 408: Flare 3: April 2, 2014



Photo 409: Flare 3: April 2, 2014



Photo 411: Flare 1: April 16, 2014



Photo 410: Flare 3: April 2, 2014



Photo 412: Flare 1: April 16, 2014




Photo 413: Flare 1: April 16, 2014



Photo 415: Flare 1: April 16, 2014



Photo 414: Flare 1: April 16, 2014



Photo 416: Flare 1: April 16, 2014



Photo 417: City South Alternate Access Road: April 16, 2014



Photo 419: Southern Perimeter Unlocked Gate: April 16, 2014



Photo 418: City South Alternate Access Road: April 16, 2014



Photo 420: Seismic Detector/ Motion Recorder: April 16, 2014



Photo 421: Site Working Areas: April 2, 2014



Photo 423: Site Working Areas: April 2, 2014



Photo 422: Site Working Areas: April 2, 2014



Photo 424: Site Working Areas: April 2, 2014



Photo 425: Site Working Areas: April 2, 2014



Photo 427: Site Working Areas: April 16, 2014



Photo 426: Site Working Areas: April 2, 2014



Photo 428: Site Working Areas: April 16, 2014



Photo 429: Site Working Areas: April 16, 2014



Photo 431: Site Working Areas: May 7, 2014



Photo 430: Site Working Areas: April 16, 2014



Photo 432: Site Working Areas: May 7, 2014



Photo 433: Site Working Areas: May 7, 2014



Photo 435: Site Working Areas: May 7, 2014



Photo 434: Site Working Areas: May 7, 2014



Photo 436: Site Working Areas: May 7, 2014



Photo 437: Site Working Areas: June 11, 2014




Photo 439: Site Working Areas: June 11, 2014



Photo 438: Site Working Areas: June 11, 2014



Photo 440: Site Working Areas: June 11, 2014



Photo 441: Site Working Areas: June 11, 2014



Photo 443: Site Working Areas: June 24, 2014



Photo 442: Site Working Areas: June 11, 2014



Photo 444: Site Working Areas: June 24, 2014



Photo 445: Site Working Areas: June 24, 2014



Photo 447: Site Working Areas: June 24, 2014



Photo 446: Site Working Areas: June 24, 2014



Photo 448: Site: April 16, 2014



Photo 449: Site: April 16, 2014



Photo 451: Site: April 16, 2014



Photo 450: Site: April 16, 2014



Photo 452: Site: April 16, 2014



Photo 453: Site: May 7, 2014



Photo 455: Site: May 7, 2014



Photo 454: Site: May 7, 2014



Photo 456: Site: May 7, 2014



Photo 457: Site: May 7, 2014



Photo 459: Site: May 7, 2014



Photo 458: Site: May 7, 2014



Photo 460: Site: June 24, 2014



Photo 461: Site: June 24, 2014



Photo 463: Site: June 24, 2014



Photo 462: Site: June 24, 2014



Photo 464: Site: June 24, 2014



Photo 465: Site: June 24, 2014



Photo 467: Site: June 24, 2014



Photo 466: Site: June 24, 2014



Photo 468: Site: June 24, 2014



Photo 469: Site: June 24, 2014



Photo 471: Site: June 24, 2014



Photo 470: Site: June 24, 2014



Photo 472: Site Grading West of Office: June 11, 2014



Photo 473: Site Grading West of Office: June 11, 2014



Photo 475: Site Grading West of Office: June 11, 2014



Photo 474: Site Grading West of Office: June 11, 2014



Photo 476: Site Grading West of Office: June 11, 2014



Photo 477: Offsite Litter: April 16, 2014



Photo 479: Offsite Litter: April 16, 2014



Photo 478: Offsite Litter: April 16, 2014



Photo 480: Offsite Litter: June 11, 2014



Photo 481: Offsite Litter: June 11, 2014



Photo 483: Offsite Litter: June 11, 2014



Photo 482: Offsite Litter: June 11, 2014



Photo 484: Offsite Litter: June 11, 2014



Photo 485: Offsite Litter: June 11, 2014




Photo 487: Offsite Litter: June 11, 2014



Photo 486: Offsite Litter: June 11, 2014



Photo 488: Offsite Litter: June 11, 2014



Photo 489: Offsite Litter: June 11, 2014



Photo 491: Offsite Litter: June 11, 2014



Photo 490: Offsite Litter: June 11, 2014



Photo 492: Offsite Litter: June 11, 2014

Appendix III

Quarterly Site Visits: Site Visit Attendees by Date of Site Visit/ Mitigation Monitoring Site Reports

UltraSystems Staff Fields of Expertise:

James Aidukas Project Manager, Permitting and Operations/ Engineer

Mike Lindsay Air Quality, Noise, Vehicle Emissions, Environmental Specialist/

Engineer

Susan Foster Hazardous Waste/ Risk of Upset

Jack Emerson Air Quality, Noise, Hydrology, Hazardous Waste

SES Staff Fields of Expertise:

Tarik Hadj-Hamou Geology

April Site Visits

April 2, 2014:

James Aidukas (UltraSystems)

Mike Lindsay (UltraSystems)

Susan Foster (UltraSystems)

April 16, 2014:

James Aidukas (UltraSystems)

Mike Lindsay (UltraSystems)

Jack Emerson (UltraSystems)



Monitor: James Aidukas	Page:	1	of	2
Discipline: Project Manager	Date: April	2, 2014		
Site Conditions: Cloudy with light rain				
	SITE LOG			

Republic Site Manager - Dave Hauser

Met with John Nelson (LACDPW), Mike Lindsay and Susan Foster (UltraSystems). Signed in and briefly met with Patti Costa and Becky Van Sickle (Republic). Mike Lindsay proceeded to monitor the County top deck and the City south. John Nelson, Susan Foster, and I proceeded to monitor the site:

- Observed standing water in Basin A. There was wind-blown litter in the native back hillsides (west and north) of the basin.
- The inlet to Basin A was blocked with tumbleweeds.
- Observed a new area of the westside channel wall that had the concrete wall cracked and spalling. The prior-noticed cracked and uplifting channel bottom and spalling wall areas are progressively getting worse. Repairs are not yet scheduled.
- The bottom of the westside channel was accumulating piles of sediment the whole length of the channel. A section of the channel had a piece of HDPE loose in the bottom.
- Basin D was observed to be clean with no ponding water. The majority of the basin appeared to sealed with sealant.
- Basin D outlet channel had sediment in the bottom and the leading edge of the channel liner with uplifted and partially blocking flow.
- Progress was being made on the gas-to-energy facility. Equipment was being set.
- Emergency generators were observed at Flare #9 and #10 for the shutdown of Edison power and the replacement of some wooden poles.
- Observed that the recent rains caused the County sage mitigation area to green-up and vegetation to flower.
- The Basin D outlet channel below Flare #9 and #10 had a portion of the side wall separating from the adjacent asphalt road.
- Basin B had sediment, ponding, and a section of a corrugated galvanized drain pipe in the bottom. The back native vegetated hillsides had wind-blown litter.
- It was observed that the eastside drainage channel had litter in the bottom near the old city north fill area. The native hillsides in the old city north also had wind-blown litter.
- The terminal basin had accumulated sediment from the recent rain storms. There was some litter around the outlet risers.
- It was observed that there was still litter and dumped debris between the terminal basin front
 wall and the slump stone wall along San Fernando Road.
- The terminal basin outflow has rock and sediment in the section under San Fernando Road.
- The terminal basin gate was replaced and locked.
- The terminal sidewall that parallels the access road has cracks that have gotten larger with grass growing out of them.
- Cell CC3A and the buttress was observed. The majority of the soil washout from the February
 rains was repaired. There was standing water in the basin downstream of the buttress. The area
 upstream of the buttress had standing water.
- The pond that was created from the water from the corrugated steel seep drain pipe in the city soil stockpile area was observed to be de-watered.
- The HDPE drainage channel along the access road was not yet repaired from the February rainstorm.

April 2, 2014, page 2 of 2

- The city south drainage along the paved access road to Deck B appeared to be in good condition.
- The working face was in two small areas: County top deck near the City/County line and in CC3A.

Flare Operating Conditions:

- o Flare 1 1695° F, 2424 SCFM, -62" H₂O vacuum
- o Flare 3 1689° F, 2011 SCFM

FURTHER REVIEW NEEDED

COMMENTS

Signed:



Monitor: Mike Lindsay	Page / of /
Discipline: Environmental Engineer	Date: 04-02-14 Wed.
Site Conditions: Cloudy, showers	,56-61°F, 6 mph
SITÉ	LOG
1. Met with John Nelson	(LACOPUS), Jim Aidukas,
Susan Foster (Ultra-	Systems
2. Checked into office and	with Patti Costa, Becky
3. Observed new erosion co	entrol BMPs installed on
County Top Deck slopes	northwest at admin.
buildings . Several romes of	-traw wattles were placed,
A. Flore 1 is operating as	7 2623 SCFM, 1683°F;
gos sample measured at	22 % Vol. CHA 5,2% Vol. 02.
5. Met with Achaya Kelepo	O'supply gos at 1220F
3. Met with Achaya Kelepa	nola (Republic) at Flore 1,
A set of old wells have	seen abundaned (capped and
sealed with bentonite), an	d their 16" Feed pipe has
been capped at Flore 13	atter small feats (~300
poin were do tected. A	tologorary our com mercor
was being used (for blow	er seal presure because
was being used (for blow fixed compressor stopped a rodent was sucked in to	working, Couse of failure?
a rodent was sucked in to	air intake BAS coew
measured Flano I gas san	ple at 27/6/6/1 CHA 2.78/6/ 07.
6. Flore 3 is operating at	2007 564, 1689 05:
gas sample mensing at	39 % blicHA, 5.1 % Vol. 02,
7. Measured City Deck C re	rece to xinu conso Usino
Trimble GPS devke (±0,1	in accuracy), including salt
bush and sage areas in se	quare feets
FURTHER REV	IEW NEEDED
Project Number: 5800 Sign	ed: Mils Linder



ivionitor: Susan Foster	Page:	1	of	1
Discipline: Hydrology, Haz. Waste, Risk of Upset	Date: April 3,	2014		
Site Conditions: Partly cloudy, cool, and windy				
	LOG			
9:45 AM: Met with John Nelson, James Aidukas, and	Mike Lindsay at	the landfi	II.	
John Nelson, James Aidukas, and I drove around operations. A rain event had occurred the night prio areas were observed. Evidence of heavy flow in chanchannels had liner that had been severely displaced energy from the recent storm flow were also noted.	r to the day's sinnels was noted	te visit, an I resulting	d multip	le puddles/ponding heavy rains: many
Duct tape was seen on a gasket on Flare 9.				
Upon returning to the office, Achaya Kelapanda, Joobservations at the landfill for the day. Achaya ment	ohn Nelson, Jam Jioned the replac	nes Aiduka cement of	is and I if	met to discuss the at was occurring.
Fire hoses were observed to have been placed on wa	ter trucks.			
FURTHER REV	IEW NEEDED			
Water ponding areas need to be addressed.		20 de 200 de		
	_			
COMN	1ENTS			
	O			<u></u>
Project Number: 5800 Signe	:d: AM	un R.	For	de 1



Monitor: James Aidukas	Page:	1	of	1
Discipline: Project Manager	Date: April	16, 2014		
Site Conditions: Clear and sunny, slight wi	nd			
	SITELOG			

Republic Site Manger - Dave Hauser

Met with John Nelson (LACDPW), Mike Lindsay and Jack Emerson (UltraSystems). Signed in and briefly met with Patti Costa and Achaya Kelapanda and arrange to meet after the monitoring. We proceeded to monitor the site:

- Observed gas blower vertical piping on Flare 1 to be slanted. Cannot determine if newly
 installed that way or the result of the recent earthquake. The pipes don't have hold-down
 brackets.
- Observed the City Deck C access road to the oil field. This road has not yet been graded as a secondary access.
- Deck C sage mitigation was observed. Salt and Quail bush are the primary plants growing. There are some sage and other plants growing in the understory.
- The pond caused by the stockpile seep is small and appears the seep has been controlled.
- The County south facing slopes and some of the City north and City south slopes have been hydroseeded.
- The active fill was only cell CC3A.
- The drainage ditch that parallels the access road was being re-worked. This was one of the drainage channels damaged in the February rain storm.
- The oil field south gate was observed being open and without a lock.
- The eastside drainage channel that ends in the terminal basin was covered with a giant graffiti
 tag, "colex". How the people responsible got access to the landfill should be investigated.
- Observed the location and foundation for relocated or replacement of the seismograph recorder.
- Illegal dumping of a door, mattress, and tarp was observed on Sierra Highway near the I-14 overpass.
- · Basin A was dry. The native back hillsides had wind-blown litter.
- · Basin B was dry. The native back hillsides had wind-blown litter.
- The County sage mitigation is still green and growing from the rainstorms.

Flare operating conditions:

- o Flare 1 Flare 1 1696° F, 2793 SCFM, -68" H₂O vacuum
- o Flare 3 1695° F, 1980 SCFM
- o Flare 9 1672° F, 4110 SCFM, -56" H₂O vacuum
- Flare 10 1652° F, 3815 SCFM, -56" H₂O vacuum

FURTHER REVIEW NEEDED

COMMENTS Signed:



Monitor: Mike Lindsay	Page / of /
Discipline: Environmental Engineer	Date: 04-16-14
Site Conditions: Sunny, clear, 5	6-84°F, 5-15 mph
SILE	LOG
1. Met with John Nelson	(LACDPW), Jim Aldokas,
HOCK EMPISON (VITES SUSTE)	m c]
2. Checked into office and	With Patti Casta, Achaya
nelepanda (Republic)	
3, Observed hydroseeding on	County Top Deck southern slope
T. Flake 1 15 operating	AT 2/36 SCFM, 1694 1/2;
gots sample mensured at 20	6 90 Volo CH4, 5, 4 90 Volo 02,
5 Observed City Dork R	supply gas at 129 degit.
6. Observed City working to	construction project.
water for dust control.	e, with worter Thurs applys no
7. Observed grading project so	oth of Admin buildings.
8. Flare 3 is operating at	1987 SCFM 1695 OF:
gas sample measured at 4/20	61. CH4. 4.9 % Vol. 02
39 ppm H28, over 500 ppin	CO: supply ans at 127 deg. F.
1. Flare 1 is operating at 4	1219 SCFM, 1673 Fi
gas sample mesovere at	57 10 VOI, CH4, 5:4 10 Vol. 02
11 ppin H2S, over 300 pp.	in CO,
10, Flare 10 is operating at	3886 SCFM, 1645 °F. to discuss fand till open tions.
11. Met with Patti Costa	To discuss found till open tions.
a Hydroseeded stopes - 30	acres covered so far,
of Uffra systems smelled land	Fill yes odors at Flane 1 today;
in a localizat area only.	are land was a some stand as
c. The Chatsworth mitigati	+ # 21 M instead of as
open space at \$1M. Att	ennous for 1 Ac April and
FURTHER REV	t \$11 M, instead of as forneys for LACOPIN and
	5 year monitoring program
(44 orcres), Last extens	ion period expired in 2014,
per USACE.	
de Sewer project update - c	City needs additional into.
for lift station shoring	90
e. Master drainage plan is	being revised by LACDPW,
P. Phase I Bypass Road pr	sect will begin in 2014.
D. L. M. J. Francis	
Project Number: 5800 Sign	ed: The Linday



Monitor: Jack Emerson	Page: 1 of 1
Discipline: Civil Engineer	Date: 4/16/14
Site Conditions: Sunny, No cloud cover, ~80	OF .
	SITE LOG
-Intermittent Odor south of flare - 68" water vacuum pressure, 12: Flare 9: -1671F, 4160scfm, -56 inlet vacu Flare 10: -1650F, 3800scfm, -56 inlet vacu Both: Wind carrying odors (presumab Talk with Terry Freeman, new Construction -Facility scheduled for August 1st finishFacility may be completed as soon as Ju Observations: -Graffiti – COLEX written across channel -Characters approximately 10' in h -Hydroseeding visible on east side of Min -Slight trash buildup in brush near north Meeting with Republic: -Graffiti believed to have occurred April -Hydroseeding has been ongoing since b -Trash buildup cleanup ongoing. Worker -Master Drainage plan being updated by -Public Works to review drainage plan	on Manager for Gas to Energy Facility: July 3 rd . Jon south facing slope of Middle Deck height total 50'. Visible from entrance and freeway. Hern retention basin. Jordan Paint supplies have been ordered already. Height total 50'. Visible from entrance and freeway. Hern retention basin. Jordan Paint supplies have been ordered already. Height total seginning of April and is still ongoing (30 acres) have purchasing poles for trash high in brush. We peter lama. Jordan Paint Supplies have been ordered already.
FUI	RTHER REVIEW NEEDED
	COMMENTS
	Jack Emerson

Signed:

Emerson 2014.04.21

13:42:36 -07'00'

May Site Visits

May 7, 2014:

James Aidukas (UltraSystems)

Mike Lindsay (UltraSystems)

Tarik Hadj-Hamou (SES)



Monitor: James Aidukas	Page:	1	of	2
Discipline: Project Manager	Date: May	7, 2014		
Site Conditions: Mid-70's, slight wind				
	SITE LOG			

Republic Site Manger - Rob Sherman

Met with John Nelson and Kawsar Vazifdar (LACDPW), Mike Lindsay and Tarik Hadj-Hamou (UltraSystems). Signed in and briefly talked to Patti Costa and Achaya Kelapanda to determine what general activities were in progress on-site today. Mike Lindsay met with Becky Van Sickle to observe site reports for the access road realignment. John Nelson, Kawsar Varifdar, and I proceeded to monitor the site. Mike Lindsay met up with us later.

- Observed the access road realignment area where the removal of trees and vegetation occurred. Noted that a potable waterline had a valve leaking. This appeared to be a water source for grading operations.
- Observed Basin A to be dry with minor sediment in the bottom. There was minor wind-blown litter in the basin and significant litter in the northwest native vegetation back hillsides.
- The westside concrete drainage channel condition was worsening in the area where the broken bottom was previously noted. The center of the channel is uplifting due to either soil expansion or movement of the adjacent hillside. This condition should be investigated and maintenance performed.
- The material storage area was in good order except for a stockpile of waste corrugated pipe.
 This material should be recycled along with a similar stockpile on the old City north top deck.
- Observed Basin D outlet drainage channel to be clean and repaired since the last monitoring.
- Observed the vegetation (sage) on the hillsides below Flare #8. Noted the condition, density and took photos.
- Trash was observed blocking the corrugated drainage pipes that were installed under the road below Flares #9 and #10.
- There was some vegetation growing on the cut hillsides above and below Flares #9 and #10.
- A plastic 1-gallon gasoline container with gasoline in it was observed lying on the ground near Flare #10.
- The gas-to-energy facility appeared to be in the commissioning mode with all equipment in place and electrical testing of equipment proceeding.
- Basin B was dry and had minor sediment. A loose piece of corrugated drainage pipe was blown into the basin. The adjacent native hillsides had wind-blown litter in the vegetation.
- Observed the terminal basin to be dry with approximately 1-2 feet of sediment.
- The inlet channel to the terminal basin had the graffiti covered with paint.
- The existing channel from the leachate treatment facility to the terminal basin was being removed to allow for the access road realignment and a new drainage channel.
- Observed the Deck C sage mitigation area. Salt and quail bush was the predominant vegetation.
 However, in their understory other plants, like sage, were growing.

Page 2 of 2, May 7, 2014.
Flare operating conditions:
o Flare 1 - 1689° F, 2701 SCFM, -64" H₂O vacuum
o Flare 3 - 1701° F, 2015 SCFM
 Flare 9 - 1662° F, 4057 SCFM, -56" H₂O vacuum
 Flare 10 - 1640° F, 3857 SCFM, -56" H₂O vacuum
Met with Patti Costa, Becky Van Sickle, and Achaya Kelapanda after the monitoring.
FURTHER REVIEW NEEDED
FORTHER REVIEW NEEDED
COMMENTS
COMMENTS
Have stockpiled waste corrugated pipe remove.
2. Investigate cause of uplifting of the westside drainage channel concrete and schedule
repair.
3. Remove wind-blown litter at Basins A and B.
1/11
Signed:
y. ye weeneas
The greaters



Monitor: Mike Lindsay	Page / of 2
Discipline: Environmental Engineer	Date: 05-07-14
Site Conditions: Sunny, clear, 60	5-78°F. 5-15 moh
SITE	LOG
1. Met with John Nelson.	Kawsar Vazi Fdor (LACDPW)
Kawsar is a County metho	ano engineer), film Aldukas
Torik Hadi-Hamou (Ultre	Systems), Checked into
office with Patti Costa, Ac	haya Kelapanda (Republic).
	(Republic) to discuss closure of
new access road tree mitig.	
3. Observed selfment Basin A	with retinch of rediment
collecting around vertical	lealy pines
4. Observed an increased an	nount of wind-blown trash
along NW slope of sedimen	it Basin A.
5. West side Drainage concrete is	s upliffing and cracking.
6. BAS pipe storage yard is scrap metal piles and 40	in good order with new
scrap metal pites and 40	-yard containers.
7. Observed City North clas	red land fill area with scrop
metal pile	111111111111111111111111111111111111111
after recent rains	s additional sediment collecting
9. New bypass access road c	anstruction work is anapire
including tree removale	one, region with is engoing,
10. Met with Portti and the	site construction manager
	I drawings for new access road
11. Measured GPS location	s at Westside Drainage uplitting
concrete using a Trimble GPS	device (to, 1 m accordy)
12 Observed South Deck C reve stakes marked with a "J	getation area, with new wooden
STAKES MANKER WITH A "] FURTHER REV	VIEW NEEDED
2. Repair West-side Diminage	concrete
Li regioni Wesper Denning	CONCOCIC
	1 - 1 / 1 / 1
Project Number: 5800 Sign	red: Mila Linda



Monitor: Mike Lindsay	Page 2 of 2
Discipline: Environmental Engineer	Date: 05-07-14
Site Conditions: Clear, Sunny, 66-78	°F, 5-15 mph
SITE	LOG
13. Met with Patticasta, Becky	Van Sickle and Achaya Kolapanda:
a. Waterline valve is leaking	by how road (misters).
b. Hydroseeding being done	two ways. (mulch down
First, then seed, @ seed	down First, then mulcho or Achana Flare 3 & set on
C. Flare 3 is "cycling." Pe	or Achaga Flare 3 & set on
d. Agas can (the Kind used to	ord as possible on the landfill.
next to Flare 10.	re-rue egosprion j was form
	rea Ainsworth (Republic
biologist) regarding biolog	reg Ainsworth CRepublic
removal at the bypass acc	ess road site
F. Tree removal mitigation	surveys and report are done.
g. Per Achaya, Well P-243	along Westside Drainage
	nonitored monthly
ho Rob Sharman is the new	
(From Waste Management	and American Airlines).
FURTHER REV	ICM NECDED
FORTHER REV	IEW NEEDED
Project Number: 5800 Sign	ed: Mh Dinley



Monitor: Tarik Hadj-Hamou, Ph.D., P.E.	PAGE 1 OF 2	
Discipline: Civil - Geotechnical (SLR)	Date: May 7, 2014	

Site Conditions: Sunny, hot and windy

SITE LOG

9:00 arrive at Sunshine Canyon Landfill; met with Jim Aidukas and Mike Lindsay (UltraSystems) and prepare for monitoring visit

9:30 met with John Nelson and Kawsar Vazifdar (LACDPW), Jim Aidukas and Mike Lindsay (UltraSystems); signed-in at the office

9:45 - 12:45 site tour

Observed the following areas: drainage, slopes, roads,

Drainage system

- Sedimentation basins
 - Basins A and D are clean
 - Terminal basin contains some fines due to latest storm –

Channels

- \circ We noted that that the condition of portion on the westside drainage channel between Basin A and Basin D noted in previous visits has worsened. , The floor of the channel is uplifted in the middle with a large crack exhibiting a vertical offset of about 1 % inch and weeds growing (Photos 1 and 2).
- Cracks mentioned in previous visits on the west side (native soil side) of the channel are getting worse with concrete spalling and pieces falling off. By contrast, on the east side (landfill side) the tree has been removed showing broken concrete wall facing (Photo 3).
- In a large storm, the conditions noted above could worsen leading to significant damage to the channel as water could enter below the slab and lift it.

Slopes

No issues

Roads

Work has begun on the new access road. Clearing and grubbing on the slope near the entrance of the landfill was on-going. The initial segment of the new access road will require cutting some of the native material and installing concrete piers socketed into native material to provide for the stability of the waste mass.

We were presented the construction drawings showing the extent of the cut and locations of the piers.

We were also provided with reports demonstrating that the requirement for a factor of safety of 1.5 and maximum slope inclination of 1.5:1 were met (per city M-4.1.6 1.6 1.7 and County Geology 1.02)

COMMENTS

Condition of west side concrete channel between Basin A and Basin D is worsening. From a slight crowning the vertical uplift deformation has now reached 1.5 inch with an offset. Republic should



of crack on north sid	rstand the reason for such uplift. Swelling soil due to water intrusion at initiation e? Leak at P243 should be addressed? Or slow creeping slope (either native or he channel to buckle?
Signed:	2, 41
1	A Stylform

June Site Visits

June 11, 2014:

James Aidukas (UltraSystems)

Mike Lindsay (UltraSystems)

June 24, 2014:

James Aidukas (UltraSystems)

Mike Lindsay (UltraSystems)



Monitor: James Aidukas	Page:	1	of	2
Discipline: Project Manager	Date: June 11, 2014			
Site Conditions: Clear and sunny, low 70's				
	SITE LOG			

Republic Site Manger - Rob Sherman

Met with John Nelson (LACDPW) and Mike Lindsay (UltraSystems). Signed in and briefly talked to Rob Sherman about general site activities. Mike Lindsay proceeded to monitor the condition of the westside drainage channel and recent activities on the City and County top decks. John Nelson and I proceeded to monitor the site and observed the following:

- The outlet risers in Basin A were blocked off by a soil berm to restrict any release of water into
 the westside drainage outlet. This was done to allow removal and reconstruction of the
 drainage channel at the toe of the City south old fill area. Wind-blown litter was seen on the
 native hillsides adjacent to Basin A.
- The area west of the offices was being excavated for future development and soil was being used for daily cover. There was a paleontologist monitor on site.
- The westside drainage channel had no change since May. The cause for the uplifting and broken concrete walls should be investigated.
- The material storage area had the scrap drainage metal corrugated pipe stockpiled for recycling.
 Other materials were being organized.
- Flare 9 and 10 had additional filtration media added to the air blower intake filters to remove
 fine dirt particles. The Flare 9 air blower rubber pipe connecter that was split was not yet
 replaced. It is scheduled to be done at the next flare shutdown. A one-gallon gas can containing
 gas was left on the Flare 10 foundation, it appears that it is used to light the flare.
- The gas-to-energy facility is nearing completion with commissioning of equipment ongoing.
 Initial start-up and test runs of the turbine driven generators is scheduled for August.
- The native hillside slopes above and below the Flare 9 and 10 site had very sparse vegetation.
 The slopes below the gas-to-energy site was void of vegetation. The hydro-seeding was not successful on these slopes.
- . The drainage channel inlet to Basin B had debris blocking one of the drainage pipes.
- · The County top deck had no filling activity since May.
- The hydroseeded areas were observed and no germination of the seed had occurred due to lack of rain.
- The City Deck A was observed and the native vegetation on the west side of the top deck and adjacent back slopes was doing well.
- The grading activity for the access road realignment was stopped. Portions of the grading to
 complete the drainage was still underway. A soil test hole approximately four feet wide and
 fifteen feet high was made into the side of one of the slopes, which revealed a fine silicone
 sand-type condition.
- Illegally dumped trash and wind-blown litter was seen on Sierra Highway near the I-14 overpass.
- Dumped concrete asphalt debris and a mattress and box springs were seen on San Fernando Road south of the I-5 overpass.

Page 2 of	2, June 11, 2014.
Flore on	perating conditions:
o o	Flare 1 - 1695° F, 2547 SCFM, -61" H ₂ O vacuum
	Flare 3 - 1684° F, 2008 SCFM
	Flare 9 - 1677° F, 4010 SCFM, -56" H ₂ O vacuum
0	Flare 10 - 1665° F, 3732 SCFM, -56" H ₂ O vacuum
Met with	Mr. Tyson after the monitoring.
	FURTHER REVIEW NEEDED
	COMMENTS
	COMMENTS
	1/60
	Signed:
	y. y. Marikas



Monitor: Mike Lindsay	Page / of 2					
Discipline: Environmental Engineer	Date: 06-11-14 Wed.					
Site Conditions: Clear, sunny, 64-75°F, 0-10 mph						
SITE	LOG					
1. Met with John Nelson	(LACDPW), Jim Aidukas (UHINSGOPA)					
a. Checked into of tice and	with Rob Sherman (Reable)					
3. Observed Sediment Boxin A	with new soil berm built					
1. Observed ward-blown tood	love Middleson of God Parker					
1. Observed wind-blown trash 5. Observed paleo, monitor at	Westside Drained construction site.					
6. Existing Westside Prainage	(built approx. 1994) has					
6. Existing Westside Drainage concrete uplitting and concretion wasse	racking that is progressively					
7-11-11						
7. Mensured GPS coordinates a						
Drainage uplitting concrete	+ Dil m consens					
8. BAS Pipe Storage Yard is in	good order with scrap					
metal piles still presents	good vive g					
8. BAS Pipe Storage Yard is in metal piles still presents 9. Observed Sediment Basin 1	3 near Temp. Flare to be in					
good condition, with little so	ediment build-up.					
contour lines from City/	long final grade elevation					
NE Perimeter.	ounty Doundary to County					
11. Measured GRS valves of Co	eventy marking stakes for					
Well GW 575 (e.g. 1866.8 Ft.	at stake number 575-2)					
12. Flave 9 is operating at	4002 SCFM, 1674 OF;					
gas sample measured at 37	% CHA % Vol., 6.1 % Vol. Oz,					
73 ppm H28, over 500 ppm	CO, 143 of supply temp.					
13. Flave 10 is operating at 3728	with flagger in againsting					
14 Observed City Working Foce & FURTHER REV	IEW NEEDED					
in Remove wind-blown trash a	long NW slope of SB-A.					
2. Repair Westside Orannage 6	proken concrete.					
•						
Project Number: 5800 Sign	ed: Mile Lindy					



Monitor: Mike Lindsay	Page 2 of 2						
Discipline: Environmental Engineer	Date: 06-11-14 Wed.						
Site Conditions: Clear, sunny, 64-75°F, 0-10 mph							
SITE LOG							
15. Flare 1 is operating at	2537 SCFM, 1697 PF;						
15. Flare 1 is operating at 2537 SCFM, 1697 °F; gas sample measured at 27 % Vol CHA, 5,3% Vol. 02,							
32 ppm H2S, 80 ppm CO, 149 of supply temp. 16. Flave 3 is approximate at 2003 SCFM 1684 oF gas sample measured out 38 To Vol. CHA, 6,0 20 Vol. 02, 46 ppm H2S, over 500 ppm CO, 151 of supply temp.							
16. Flave 3 is approxime at 2003 SCFM 1684 .F.							
gas sample measurealout 38	70 Vol. CHF, 610 70 Vol. 02,						
17 Obcomed unter frucks	- luing la ter through the						
17. Observed worter frucks ap	sir)'s						
ar Soil berm in Sediment	Boxin A & Temporary to						
retain Westerde Drainage							
from above,							
b, Paleo, monitor tound w	hole bones, fish bones, rib bones,						
etc. at Westside Draina	daily logs, sobmitted to						
Recorded all findings in	daily logs, submitted to						
Becky Van Sickle (Reput	0/12).						
FURTHER REVIEW NEEDED							
Project Number: 5800 Sign	ed: not Linda						



Monitor: James Aidukas	Page:	1	of	1	
Discipline: Project Manager	Date: June 2	24, 2014			
Site Conditions: ~80°, slight wind					
	SITE LOG				

Republic Site Manger - Rob Sherman

Met with John Nelson and Karlo Manalo (LACDPW), Mike Lindsay (UltraSystems), and Tarik Hadj-Hamou (SLR). Signed in at the office and had a brief meeting with Patti Costa. We discussed the following:

<u>Sewerline construction status</u> - Patti stated that the construction had started and was put on hold until City DOT received results from street potholing showing clearance required for the sewerline. The results from potholing was submitted and approved by the City DOT. The project is now proceeding. <u>Access road realignment status</u> - An RFP is being issued for a new scope of work. The remaining grading and drainage installation for winterizing is being done by Sukit Construction. The prior grading contractor was released from their contract.

We then proceeded to monitor the site and observed the following:

- The Terminal basin was approximately 50% cleared of sediment. The clearing of the basin is scheduled to be completed before the rainy season.
- The access road realignment area had rough graded slopes and flat areas that needed fine
 grading before winterizing could occur. The grading contractor was to complete the finish
 grading on these areas before Republic was to have soil stabilization materials installed, i.e. jute
 netting, straw wattles, and hay bales.
- City Deck C sage mitigation was doing well with salt bush and quail bush being the predominant plant.
- The westside drainage channel appears to have new cracks on the concrete sidewall of the channel. Repair of the channel has not been scheduled.

Flare operating conditions:

- o Flare 1 1690° F, 2630 SCFM, -59" H₂O vacuum
- o Flare 3 1695° F, 2015 SCFM

FURTHER REVIEW NEEDED	
COMMENTS	
COMMENTS	



Monitor: Mike Lindsay	Page / of 2						
Discipline: Environmental Engineer	Date: 06-24-14 Tue.						
Site Conditions: Clear, sunny, 66-82°F, 5-15 mph							
SITE LOG							
1. Observed lover leachate plant in good order, with area grading and clean-up in progress. 2. Met with John Nelson (LACDPH) Karlo Manalo (LACDPH Civil Engineer assigned to SCL), fin Aldokas,							
with area grading and	clean-up in progress						
2. Met with John Nelson ((LACOPW) Karlo Manalo						
(LACAPW CIVIL Engineer ass.	igued to SCL), fin Ardokas,						
Tarin frais- Francia (Offin Systems)							
3. Checked into of the and w	ith Patti Costa (Republic):						
a, sewerline project has	begun, with on early issue						
regarding potholing (day	resolved,						
holes which has been	resolved,						
be Bypass acress hoad	continctor is being replaced						
on hold,	red = Consequently, project is						
	and when water throughout cite						
4. Observed water trucks ag	spring delle production delle						
test cut executed into his	Isido and exposed cours						
6. New Southern Dramage ditch	hes are being formed and poured.						
In Observed City Working F	re with tippers being utilized.						
8. City Deck C sage mitigo	attan area is growing well						
salt and quall Bush are	dominant						
9. Observed well drilling by	Observation Deck,						
10. Flave 1 is operating at 2	622 SCFM, 1690°F;						
gas sample measure at 25%	6 Vol. CHA, 5,5% Vol. 02,						
79 poin H215, 79 ppm CO	144 of supply temp.						
11. Flace 3 is operating at 20	007 SCFM, 1689 °F,						
gas sample measured at 36 %	Vol. CH4, 6,0 % Vol. 02,						
42 ppm H25, over 500 ppm CO, 151 F" supply temp, FURTHER REVIEW NEEDED							
TORTIERREV	ILW NELDED						
	H.						
Project Number: 5800 Sign	ed: The Linds						



Monitor: Mike Lindsay	Page 2 of 2						
Discipline: Environmental Engineer	Date: 06-24-14 Tue.						
Site Conditions: Clear, sunny, 66							
SITE LOG							
12. Flare 9 is operating a	+ 4412 SCFM, 1685°F						
Using Blower 3 and Blow	er t; gas sample mensured Oz, 75 ppm HZS, over						
37% Vol. C/14, 6,5% Vol.	02, 75 ppm H28, over						
13. Flax 10 is operating at	upply temp.						
13. Flave 10 is operating at	4087 SCFM, 1666 F.						
14. Gas-to-Energy Plant is p	reporting for online jest in						
14. Gas-to-Energy Plant is p. late Gulg, 2014. 15. Observed Westside Drawing cracking, Drawage ditch co							
151 Ouserved Was 75100 Wronpany	to be uplitting and						
EV-ENING. DAMAGE ATTEN E	shere asrepair is worsening.						
FURTHER REV	IEW NEEDED						
1. Repair Westside Drainage	concrete ditch.						
Project Number: 5800 Sign	ed: Mil Lindy						

Appendix IVMeeting Logs

Sunshine Canyon Landfill Meeting Log for April 2014 Site Monitoring

April 2, 2014

Post-monitoring meeting with Achaya Kelapanda, Republic's Environmental Manager

Attendees:

John Nelson, LACDPW
James Aidukas, UltraSystems
Mike Lindsay, UltraSystems
Susan Foster, UltraSystems

Discussion:

We met with Mr. Kelapanda and informed him that we did not observe any gas recovery concerns. Mr. Kelapanda then provided us with the following update on landfill gas activity.

- 1. The rubber air blower piping expansion joint for Flare #9 was received and will be installed when the flare is shut down.
- 2. Standby generators are at Flares #9 and #10 to provide power when Edison shuts down the system to replace some wooden electric power poles.
- 3. Eighty-five (85) wells were abandoned on the Old City North and City South landfill areas. They were replaced with 85 new wells and connected to a new 18" header. This was related to the gas-to-energy facility and sections 29 and 40 tax credits. The new piping to the gas-to-energy facility will be purged with landfill gas to the other collection piping on May 15th.
- 4. The start of commissioning of the power facility is scheduled for June 15th.
- 5. The City sewer line is on hold until final permits are obtained.

April 16, 2014

Post-monitoring meeting with Patti Costa, Republic's Environmental Manager; Becky Van Sickle, Republic's Environmental Compliance Specialist; and Achaya Kelapanda, Republic's Environmental Manager

Attendees:

John Nelson, LACDPW
James Aidukas, UltraSystems
Mike Lindsay, UltraSystems
Jack Emerson, UltraSystems

Discussion:

We had a post-monitoring meeting and provided our observations and questions to the Republic staff and received comments and updates as follows:

There was a large area on the eastside drainage channel that had graffiti on it.

- Patti Costa stated that this was done about two weeks ago. Maintenance had ordered paint and will schedule the graffiti's removal when supplies are received. How they accessed the site is not known.
- Litter and illegal dumping was seen on Sierra Highway near the I-14 overpass. Also, wind-blown litter was seen on the native hillsides behind Basins A and B.
- Patti Costa stated that the crews are scheduled to clean up Sierra Highway at the end of the week. She said that she would advise the operations manager of the litter at Basins A and B.
- What is the status of moving the seismograph?
- Ms. Costa stated that their consulting geologist had selected a new location near the recycled water facility power panel near the entrance. They will be replacing the equipment with a new and updated system.
- It was observed that the hydroseeded was done. What is the status?
- Ms. Costa stated that 30 acres were hydroseeded and that completes the hydroseeding for this period.
- During monitoring of Flare #1 it was noticed that there was an intermittent and localized odor near the flare foundation.
- Ms. Costa and Mr. Kelapanda both stated that localized odors at a flare station is not an unusual occurrence as long as it is not leaving the site.

Patti Costa also gave the following status updates:

- The Chatsworth wetlands and riparian mitigation is being held up in the City approval and land transfer process. There was a new appraisal that assesses the land as commercial property at \$11 million instead of being assessed as open space at \$1 million. Ms. Costa was not aware of what the next step is to resolve any outstanding issues. The Corps of Engineers permit extension expires in December 2014.
- 2. The new sewer pipeline project is on hold until the shoring plan for the lift station is approved by City Building and Safety.
- 3. The Master Drainage Plan is being revised and will be given to the County when the design completed.
- 4. The terminal berm construction is scheduled to start in 2015.

Sunshine Canyon Landfill Meeting Log for May 2014 Site Monitoring

May 7, 2014

Post-monitoring meeting with Patti Costa, Republic's Environmental Manager; Becky Van Sickle, Republic's Environmental Compliance Specialist; and Achaya Kelapanda, Republic's Environmental Manager

Attendees:

John Nelson, LACDPW
Kawsar Vazifdar, LACDPW
James Aidukas, UltraSystems
Mike Lindsay, UltraSystems
Tarik Hadj-Hamou, SLR/UltraSystems

Discussion:

We had a post-monitoring meeting and provided our observations and questions to the Republic staff and received comments and updates as follows:

- A leaking potable watering valve was observed near the access road realignment area. It
 appears that this waterline was being used for the road construction.
 - Patti Costa stated that the construction contractor would be notified of the water leak.
- The Flare #3 was noted as cycling. The vacuum level appeared to be low.
 - Achaya Kelapanda stated that the flare was on flow control. He also thought that the
 vacuum level should be normal and that the gauge we observed must have been wrong.
 He checked the flare the next day and notified us that the flare was operating as
 required.
- A one-gallon can with gasoline in it was observed lying on the ground at Flare #10.
 - Patti Costa stated that the gasoline container will be picked up and reason why it was there would be investigated.
- It was asked if the biological monitor cleared the removal of trees and vegetation during the migratory bird period.
 - Patti Costa stated that their biological monitor, Greg Ainsworth, provide a clearance letter and that the documentation will be given to the City and County for their records.
- Patti Costa then gave us the following information:
 - The site now has a new general manager, Rob Sherman.
 - Hydroseeding is being done using two procedures in a test area: 1) Mulch being put in place first, followed by seed, and 2) Seed first, followed by mulch.
 - An evaluation of success will be done once germination takes place.

Appendix VLandfill GPS Data

INTRODUCTION

During the second quarter of 2014, UltraSystems conducted Global Positioning System (GPS) surveys at the Sunshine Canyon Landfill, located in Sylmar, California. GPS data was collected for the City of Los Angeles Deck C vegetation cover and the Los Angeles County Westside Drainage ditch and Top Deck area.

EQUIPMENT USED

A Trimble GeoXH 2008 Series handheld GPS device running TerraSync Professional software was used for the measurements. The device has a horizontal and vertical accuracy of 0.1 meters. The GPS built-in antenna was used with a four-foot vertical offset to compensate for carrying the device. Also, the unit was kept ten feet away from any materials that could have an effect on satellite signal reception (e.g. metal within well heads).

MEASUREMENT LOCATIONS

Vegetation perimeter growth lines were walked for area data at the City Deck C sage mitigation area. Measurement points were taken for comparison purposes along the Westside Drainage ditch where shotcrete is uplifting and cracking. For the County Top Deck area, GPS measurements were taken along final grade elevation contour lines from the City/ County boundary to the County northeast perimeter.

MEASUREMENT RESULTS

The City Deck C sage mitigation area was measured for vegetation cover. The overall survey area measured 4.1 acres. The dominant vegetative growth is salt bush, and measured 1.7 acres (42 %) of the total survey area (these values are approximate).

Several measurement points were taken along the Westside Drainage ditch where shotcrete damage is occurring. These points can be used to detect future movement and help evaluate the cause of the uplifting floor and walls.

For this reporting period, elevation measurements showed a slight increase in stockpiled soil on the County Top Deck. For the County Top Deck area, the average elevation was 1,874.9 feet above mean sea level. The average change in elevation for this same area was +0.9 feet (see GPS Elevation Data Table, Appendix V).

GPS Data Logs

April 16, 2014

City Deck C Vegetation Cover Measurement

Performed by:

Mike Lindsay, UltraSystems (see GPS Elevation Map)

May 7, 2014

Westside Drainage Shotcrete Damage Measurements

Performed by:

Mike Lindsay, UltraSystems

June 11, 2014


County Top Deck Elevation along Final Grade Contour Lines

Performed by:

Mike Lindsay, UltraSystems (see GPS Elevation Map and Table)

GPS Maps





GPS Elevation Data Table

SCL - Elevation Comparison of February 19, 2014 and June 11, 2014 Surveys (feet)

Map Grid	GPS Survey Date	Elevation	GPS Survey Date	Elevation	Elevation Difference Feb 19 / Jun 11
К6	02-19-2014	1863.7	06-11-2014	1863.8	0.1
J6	02-19-2014	1872.0	06-11-2014	1872.3	0.2
J6	02-19-2014	1883.9	06-11-2014	1884.1	0.2
J6	02-19-2014	1885.8	06-11-2014	1886.0	0.2
J7	02-19-2014	1889.4	06-11-2014	1888.2	-1.2
J7	02-19-2014	1889.6	06-11-2014	1888.9	-0.7
J6	02-19-2014	1891.6	06-11-2014	1890.4	-1.2
J6	02-19-2014	1888.7	06-11-2014	1887.4	-1.4
15	02-19-2014	1886.0	06-11-2014	1885.5	-0.5
J5	02-19-2014	1881.0	06-11-2014	1880.9	0.0
J5	02-19-2014	1878.3	06-11-2014	1879.1	0.9
J5	02-19-2014	1859.1	06-11-2014	1870.9	11.9
К6	02-19-2014	1856.3	06-11-2014	1855.8	-0.4
К6	02-19-2014	1853.4	06-11-2014	1852.8	-0.6
K5	02-19-2014	1851.6	06-11-2014	1863.8	12.2
J5	02-19-2014	1862.5	06-11-2014	1867.7	5.2
J5	02-19-2014	1869.6	06-11-2014	1865.2	-4.4
J5	02-19-2014	1870.5	06-11-2014	1866.5	-4.0
	02-19-2014	1874.0 (Average)	06-11-2014	1874.9 (Average)	+0.9 (Average)