

From: Mindy Nguyen <Mindy.Nguyen@lacity.org>
Sent time: 08/25/2020 04:12:01 PM
To: Lisa Webber <lisa.webber@lacity.org>
Cc: Luciralia Ibarra <luciralia.ibarra@lacity.org>
Subject: Re:
Attachments: LADBS Hollywood Center Letter_8 7 20.pdf

Hi Lisa,

Please see attached.

On Tue, Aug 25, 2020 at 4:10 PM Lisa Webber <lisa.webber@lacity.org> wrote:
can you send over the DBS seismologist communication re HC?

--



LOS ANGELES
CITY PLANNING

Lisa M. Webber, AICP
Preferred Pronouns: She, Her, Hers
Deputy Director

Los Angeles City Planning
200 N. Spring St., Room 525
Los Angeles, CA 90012
Planning4LA.org
T: (213) 978-1274 | C: (213) 202-4382
E: lisa.webber@lacity.org



--



LOS ANGELES
CITY PLANNING

Mindy Nguyen
City Planner
Los Angeles City Planning

221 N. Figueroa St., Suite 1350
Los Angeles, CA 90012
Planning4LA.org
T: (213) 847-3674



BOARD OF
BUILDING AND SAFETY
COMMISSIONERS

VAN AMBATIELOS
PRESIDENT

JAVIER NUNEZ
VICE PRESIDENT

JOSELYN GEAGA-ROSENTHAL
GEORGE HOVAGUIMIAN
ELVIN W. MOON

CITY OF LOS ANGELES
CALIFORNIA



ERIC GARCETTI
MAYOR

DEPARTMENT OF
BUILDING AND SAFETY
201 NORTH FIGUEROA STREET
LOS ANGELES, CA 90012

OSAMA YOUNAN, P.E.
GENERAL MANAGER
SUPERINTENDENT OF BUILDING

JOHN WEIGHT
EXECUTIVE OFFICER

CITY OF LOS ANGELES
INTER-DEPARTMENTAL CORRESPONDENCE

August 7, 2020

To: Luciralia Ibarra, Principle City Planner
Department of City Planning

From: Daniel Schneidereit, Engineering Geologist II
Department of Building and Safety

Subject: The California Geological Survey's Comments Regarding the Hollywood Center Fault Investigation

At the request of the Department of City Planning the Department of Building and Safety has reviewed a July 16, 2020 letter by the California Geological Survey (CGS) that concerns the proposed Hollywood Center development (Vesting Tentative Tract 82152). The CGS states they have new data they believe indicate there may be an active fault traversing the southerly portion of the site.

We acknowledge the CGS's concern and believe the best way to resolve this issue is for the developer to excavate another exploratory trench to demonstrate, or rule out, the presence of an active fault in the southerly part of the site. The trench needs to be approximately 30 feet deep or more to expose the necessary strata, and may require the use of shoring.

It is our understanding that the geologic consultants for the project are currently working on a scope of work for a trench. As part of the review, the Department of Building and Safety will ensure there will be transparency with the CGS, by requesting the CGS geologists to observe the trench and verify the exploration results.

Please contact me if you have further questions.

Thank you.

DCS