

Table 2
Gas Survey Results
Floor Seams, Cracks & Drains
Tammell-Crow Company
ABC Entertainment Center Garage
August 25, 2001

Survey Location	Methane (ppmv)	Backgd (ppmv)	Location Type	Survey Location	Methane (ppmv)	Backgd (ppmv)	Location Type	Survey Location	Methane (ppmv)	Backgd (ppmv)	Location Type
S-93	500	100	Seam	S-134	120	120	FCD	S-175	300	---	FCD
S-94	100	100	FCD	S-135	120	120	Seam	S-176	100	100	FCD
S-95	200	200	FCD	S-136	84	34	FCD	S-177	56	56	FCD
S-96	200	200	FCD	S-137	120	120	Seam	S-178	ND	ND	Seam
S-97	300	300	FCD	S-138	120	120	FCD	S-179	ND	ND	FCD
S-98	300	300	Drain	S-139	88	88	FCD	S-180	200	200	FCD
S-99	200	200	FCD	S-140	72	---	FCD	S-181	80	36	FCD
S-100	300	300	FCD	S-141	130	80	FCD	S-182	120	0	FCD
S-101	200	200	FCD	S-142	75	---	FCD	S-183	40%	80	Seam
S-102	200	200	FCD	S-143	70	---	Drain	S-184	60	60	Seam
S-103	100	100	FCD	S-144	>1000	100	FCD	S-185	>1000	36	Seam
S-104	100	100	FCD	S-145	340	240	FCD	S-186	70	70	Seam
S-105	100	100	FCD	S-146	460	460	FCD	S-187	140	140	Seam
S-106	250	250	FCD	S-147	>1000	200	Seam	S-188	100%	220	Seam
S-107	250	250	FCD	S-148	>1000	160	Seam	S-189	0.4%	140	Seam
S-108	200	200	FCD	S-149	180	180	FCD	S-190	6.5%	100	Seam
S-109	100	100	FCD	S-150	>1000	240	Seam	S-191	1.2%	100	Seam
S-110	200	200	FCD	S-151	280	100	FCD	S-192	200	150	Seam
S-111	200	200	FCD	S-152	500	---	FCD	S-193	0.4%	160	Seam
S-112	200	200	FCD	S-153	120	---	FCD	S-194	100	100	Seam
S-113	150	150	Drain	S-154	65	---	FCD	S-195	100%	500	Seam
S-114	200	200	FCD	S-155	900	---	FCD	S-196	5.3%	180	Seam
S-115	100	100	FCD	S-156	60	---	FCD	S-197	0.2%	180	Seam
S-116	100	100	FCD	S-157	6.5	---	FCD	S-198	200	200	Seam
S-117	100	100	FCD	S-158	82	---	---	S-199	>1000	160	Seam
S-118	100	100	FCD	S-159	75	---	Drain	S-200	0.5%	100	Seam
S-119	200	200	Drain	S-160	80	80	FCD	S-201	600	200	Seam
S-120	22.20%	---	Seam	S-161	75	75	FCD	S-202	60	60	Seam
S-121	5.60%	---	Seam	S-162	140	140	FCD	S-203	140	100	Seam
S-122	600	200	Seam	S-163	140	140	FCD	S-204	60	60	Seam
S-123	4.20%	---	Seam	S-164	120	0	FCD	S-205	260	260	Seam
S-124	200	200	Drain	S-165	25	0	FCD	S-206	240	240	Seam
S-125	100	100	FCD	S-166	200	0	FCD	S-207	260	260	Seam
S-126	>1000	120	Seam	S-167	100	0	FCD	S-208	220	220	Seam
S-127	120	120	FCD	S-168	170	26	FCD	S-209	280	260	Seam
S-128	120	120	FCD	S-169	0	0	FCD	S-210	0.5%	100	Seam
S-129	120	120	Seam	S-170	8.5%	0 %	---	S-211	140	140	Drain
S-130	120	120	Seam	S-171	1.3%	0	FCD	S-212	1.2%	100	Seam
S-131	120	120	FCD	S-172	80	0	FCD	S-213	240	200	Seam
S-132	120	120	Seam	S-173	5.5	0	FCD	S-31	63.6%	---	Dup
S-133	120	120	Seam	S-174	0.2%	0%	FCD	S-32	2.4%	---	Dup
								S-90	17.6%	---	Dup

Hydrogen Sulfide was not detected at any location.

Methane measured with FID (100 ppmv to 1,000 ppmv) or Landtec (0.1% to 100%) if concentration >1,000 ppmv

FCD- Floor Cleanout Drain cover;

Seam- seep along a concrete seam in the floor;

Drain- grate to the sub-floor storm drain

Background measured approximately 5 feet off the floor

Samples collected at approximately 1" off the floor or drain.

--- = data not available.